

*Like* *CKK/AIG*

COMFORTDELGRO ENGINEERING PTE LTD

Date: 21.07.2020  
Time: 11:49:20  
Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305412123  
REGN NO : SHC2510X  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 25.01.2017  
DATE/TIME IN : 21.07.2020 08:00  
ACCIDENT DATE : 20.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	1,106.00	20.00	884.80	<i>del</i>	
0002	04-01-0103-0907-G	I40VC BRKT ASSY-RR BUMPER	1 L	35.60	20.00	28.48	<i>re</i>	
0003	04-01-0103-0576-G	I40V2 PANEL ASSY-QUARTER	1 L	2,171.40	20.00	1,737.12	<i>Rp</i>	
0004	04-01-0103-0745-G	I40VC MOULDING-RR WDO GLA	1 L	51.80	20.00	41.44	<i>x nm</i>	
0005	05-01-0199-0032-A	(ALL)WINDSCREEN AHESIVE-3	2 N	46.00	2.00-	46.00	<i>x ny</i>	
0006	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	0.20	80.00	<i>re</i>	
0007	04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1 L	112.50	20.00	90.00	<i>at</i>	<i>1083.28</i>

SUB-TOTAL : 2,907.84

JOB NATURE

0000	L	PANEL BEATING		850.00		<i>560.</i>	
0001	23-502	SPRAYPAINT ON AFFECTED AREA		650.00		<i>600.</i>	
0002	20-00	TUFF COAT ON AFFECTED PARTS.		30.00		<i>✓</i>	
0003	20-20	REMOVE/REFIX RR W/SCREEN TO ASST R/P				<i>120.00 x nm</i>	

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305412123  
 REGN NO : SHC2510X  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 25.01.2017  
 DATE/TIME IN : 21.07.2020 08:0  
 ACCIDENT DATE : 20.07.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0004 20-204 REMOVE/REFIX UPHOLSTERY ASST REPAIR	150.00	X	MM		
0005 20-08 ADJUST FRONT WHEEL ALIGNMENT	80.00	✓			1270
SUB-TOTAL :					1,880.00
TOTAL :					4,787.84

MVA NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO  
 SURVEYOR NAME & SIGNATURE  
 DATE :

Tanpin 97495749  
 -wp' 21/7/2020 3pm  
 Wmpson  
 Repair after repair.  
 = 3 days  
 tanpin @ lkhank.wm.

1083.28  
 1270  
 -----  
 2353.28  
 4541900  
 = 3 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: