

*Lke* *LKK/AIG*

COMFORTDELGRO ENGINEERING PTE LTD

Date: 21.07.2020

Time: 11:49:20

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305412123  
 REGN NO : SHC2510X  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 25.01.2017  
 DATE/TIME IN : 21.07.2020 08:00  
 ACCIDENT DATE : 20.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	1,106.00	20.00	884.80	<i>add ✓</i>
0002	04-01-0103-0907-G	I40VC BRKT ASSY-RR BUMPER	1 L	35.60	20.00	28.48	<i>re ✓</i>
0003	04-01-0103-0576-G	I40V2 PANEL ASSY-QUARTER	1 L	2,171.40	20.00	1,737.12	<i>Rp ✓</i>
0004	04-01-0103-0745-G	I40VC MOULDING-RR WDO GLA	1 L	51.80	20.00	41.44	<i>X</i>
0005	05-01-0199-0032-A	(ALL)WINDSCREEN AHESIVE-3	2 N	46.00	2.00-	46.00	<i>X</i>
0006	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	0.20	80.00	<i>re ✓</i>
0007	04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1 L	112.50	20.00	90.00	<i>at ✓</i>

SUB-TOTAL : 2,907.84

JOB NATURE

0000	L	PANEL BEATING		850.00		560.	
0001	23-502	SPRAYPAINT ON AFFECTED AREA		650.00		600.	
0002	20-00	TUFF COAT ON AFFECTED PARTS.		30.00		✓	
0003	20-20	REMOVE/REFIX RR W/SCREEN TO ASST R/P				120.00	<i>X</i>

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 21.07.2020  
Time: 11:49:20  
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305412123  
REGN NO : SHC2510X  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 25.01.2017  
DATE/TIME IN : 21.07.2020 08:0  
ACCIDENT DATE : 20.07.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0004 20-204 REMOVE/REFIX UPHOLSTERY ASST REPAIR	150.00	X			
0005 20-08 ADJUST FRONT WHEEL ALIGNMENT	80.00	✓			
SUB-TOTAL :					1,880.00
TOTAL :					4,787.84

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

Tanpin 97495749  
-wp' 21/7/2020 3pm  
Lumpsum  
Repair after repair.  
3 days  
Tanpin @ 11 hands.wm.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**Workshops**

59 Loyang Drive Singapore 508969  
 383 Sin Ming Drive Singapore 575717  
 45 Pandan Road Singapore 609286  
 320 Upper Road Singapore 128648

24 Seroko Loop Singapore 758156  
 7 Sungei Kadut Way, Singapore 728791  
 501 Yishun Industrial Park A Singapore 768732

Date/Time: 21.07.2020 10:57 Page : 1

Team: ARC Repair TP(CLSO)1

**JOB CARD Sales Order:**

JC NO.:305412123


CUSTOMER COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) IDENTIFICATION CARD NO.	REGN NO: <b>SHC2510X</b>	MILEAGE
	MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
	MODEL <b>I-40</b>	DATE/TIME IN <b>21.07.2020 08:00</b>
	YR OF MANU. <b>25.01.2017</b>	TARGET DATE
	CHASSIS CODE <b>KMHLB41UMHU098568</b>	COMPLETION DATE/TIME:

**AIG**

Accident Date: 20.07.2020  
 NATURE: 3P 20/07.2020

JOB DESCRIPTION

/NO                      LABOR CODE                      DESCRIPTION



RECEIVED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Engagement Slip

Exit Pass

SHC2510X

LKE

Vehicle No.:

SHC2510X

Service Advisor

Signature/Date

Name of Service Advisor

Date