

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS F	IRST CAPITAL IN	SURANCE LTD	Ref : CS/FCI20007510/Qtf3s2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 07-10-2020 Code: FCI2		
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 9414E	Veh. Inspected	GBF 6310K	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D20002543MFSH	Excess (\$)	0.00	
	Assign From	MERINA CHIA SAN SAN	Assign Date	17/07/2020	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JTFAT35Y70K207301	Colour	BLUE	
	Odometer	175637	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195 R15C	MICHELIN	6 mm	
	L/H Front Tyre	195 R15C	MICHELIN	6 mm	
	R/H Rear Tyre	195 R15C	MICHELIN	6 mm	
	L/H Rear Tyre	195 R15C	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	23/06/2020	Inspection Date	22/07/2020	
	Survey held at	SIONG LEE MOTOR2			
		38 WOODLANDS INDUSTRIAL PARK E1 #01-14 OR # 03-14 SINGAPORE 757700			
5a.	Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				