

AI GAsia Insured's Veh No : SGQ4577D

Date of Accident : 16 July 2020



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs EC Auto Leasing Pte Ltd

Date : 18 July 2020

Estimate To Repair SMM1545R - NISSAN QASHQAI 1.2 DIG-T CVT

Chassis No : SJNFEAJ11U1677239

S/No	Quantity	Description	Amount
NETT ITEMS			
01	1 pc	rear bumper	\$ 717.00
02	10 ps	rear bumper clips @ \$5.00	\$ 50.00
03	2 ps	rear bumper side retainer @ \$38.00	\$ 76.00
04	2 ps	rear bumper reflector @ \$66.00	\$ 132.00
05	1 pc	rear bumper lower bracket	\$ 176.80
06	2 ps	rear bumper parking sensor @ \$265.00	\$ 530.00
07	1 pc	rear bumper reinforcement	\$ 619.20
08	1 pc	rear bumper sponge	\$ 146.40
Less 10 %			\$ 2,447.40
			\$ 244.74
			\$ 2,202.66
LABOUR & MISC. CHARGES			
01		To check electrical lighting concerned.	\$ 60.00
02		To reinstall of rear bumper parking sensor.	\$ 80.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 600.00
04		Putty and spray painting of the affected portion.	\$ 500.00
			\$ 1,240.00
Total			\$ 3,442.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1817.6

102

9-1364.84

S.N-200.00

2-750.00

2315.84

202

1812