

**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Hill: khancha

Car Number: SJJ90T

Model : BMW M3 4.0 MT

Damaged Area: (Front Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

NOT Authorised
han
2/5 4200/
22/7/20
3 days.

Parts / Material :

1	Front Bumper (M3)	de/ton 1650	\$	2,480.00	✓
2	Front Bumper Centre Air-Grille	^^	\$	586.00	X
3	Front Bumper LH Grille	^^	\$	365.00	X
4	Front Bumper LH Headlamp Nozzle Garnish	M.S 45	\$	150.00	✓
5	Front Bumper LH Headlamp Nozzle	CNA	\$	297.00	✓
271/ 6	Front Bumper Sensor @ 475.00	^^	\$	950.00	X
271/ 7	Front Bumper Sensor Holder @ 28.00	^^	\$	112.00	X
271/ 8	Front Bumper Sensor Holder Ring @ \$9.00	^^	\$	36.00	X
9	Front Bumper sponge	CNA	\$	168.00	✓
10	Front Bumper Left Corner Mount	^^	\$	148.00	X
11	Front Bumper Top Carrier	^^	\$	397.00	X
12	Front Bumper Reinforcement	^^	\$	586.00	X
180/ 13	Front Bumper Clips	rec 60	\$	100.00	✓
14	Front Headlamp LH	CNA 2450	\$	2,518.00	✓
15	Front Left Headlamp Bracket	^^	\$	76.00	X
16	Front Left Fender	^^		Repair	X
17	Front Bonnet	^^		Repair	X
			Parts :	\$ 8,969.00	
			Less Parts 5% :	\$ 448.45	
			Total Parts :	\$ 8,520.55	

Special Net Items :

Front Bumper Diffuser Accessories Carbon M3 Series	CNA	alc	\$	2,680.00	X
Rear Number Plate W/Garnish	^^		\$	68.00	X
			Total S/N Parts : \$	2,748.00	

Labour :

To Remove, Repair & Renew Front Affected Accident Areas	\$	1,200.00	420
To Putty, Spray Paint on Affected Accident Areas	\$	1,600.00	420
To Check & Re-Connect all electrical wiring	\$	50.00	20
To Conduct AC Leakage Test	\$	200.00	X
To Conduct Radiator Leakage Test	\$	200.00	X
To Re-Position, Drill & Install Front Angle Sensor	\$	150.00	
To Conduct & Rest BMW Diagnostic Management	\$	500.00	350
To Rust Proof Affected Areas	\$	200.00	X
Total Labour :		\$ 4,100.00	

TOTAL PARTS :	\$	8,520.55
TOTAL SPECIAL NET ITEM :	\$	2,748.00
TOTAL LABOUR :	\$	4,100.00
TOTAL REPAIR COST :	\$	15,368.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-4670
52
2-4436-50
2-870.00
530680
202
4245