



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Page 1 / 2

Email : dorrer@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TAN CHOON HOCK TERENCE
10 JURONG LAKE LINK #02-35
SINGAPORE 648131

Attention : THE OWNER
Contact : 81181881

Estimate : ES007006

Date : 20/07/2020
Vehicle Num. : SBS541X
Make/Model : TOYOTA HARRIER PREMIUM 2.0 CVT
Chassis/Eng# : ZSU600072718/3ZRB731637
Accident Date : 18/07/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT FENDER R/H	1,112.00	✓
2.	1	FRONT FENDER INNER SHIELD REAR R/H	409.00	✓
3.	1	FRONT BUMPER	861.30	✓
4.	1	FRONT BUMPER SIDE RETAINER R/H	92.33	✓
5.	6	FRONT BUMPER CLIP	39.00	✓
6.	1	HEADLAMP R/H	3,687.00	✓
7.	1	FRONT DOOR R/H	1,560.00	✓
8.	1	FRONT DOOR LOWER CHROME MOULDING R/H	221.20	✓
9.	1	FRONT DOOR LOWER HINGE R/H	87.00	✓
10.	1	FRONT DOOR UPPER HINGE R/H	138.50	✓
11.	1	FRONT DOOR CHECK R/H	87.00	✓
12.	1	FRONT DOOR RUBBER SEAL R/H	198.78	✓
13.	1	FRONT DOOR SUN VISOR R/H	118.00	✓
14.	2	FRONT DOOR FRAME STICKER R/H	158.40	✓
15.	1	FRONT DOOR GLASS CHANNEL R/H	262.40	✓
16.	1	FRONT DOOR INNER LOWER RUBBER R/H	89.20	✓
17.	1	FRONT DOOR SPEAKER R/H	552.00	✓
18.	1	REAR DOOR R/H	1,319.00	✓
19.	1	SIDE SKIRTING GARNISH R/H	585.20	✓
20.	1	REAR BUMPER	1,351.20	✓
21.	1	REAR BUMPER SIDE RETAINER R/H	92.33	✓
22.	1	RUNNING BOARD PANEL R/H	862.00	✓
23.	1	FRONT SPORT RIM R/H	769.00	✓
24.	1	FRONT SHOCK ABSORBER R/H	255.20	✓
25.	1	FRONT WHEEL BEARING R/H	642.10	✓
26.	1	FRONT LOWER ARM R/H	493.20	✓
27.	1	FRONT KNUCKLE ARM R/H	541.60	✓
28.	1	FRONT DOOR PILLAR OUTER R/H	852.00	✓
29.	1	FRONT DOOR MIRROR COVER R/H	179.00	✓

CONTINUE / ...

Scanned with CamScanner



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Page 2 / 2

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TAN CHOON HOCK TERENCE
10 JURONG LAKE LINK #02-35
SINGAPORE 648131

Attention : THE OWNER
Contact : 81181881

Estimate : ES007006

Date : 20/07/2020
Vehicle Num. : SBB541X
Make/Model : TOYOTA HARRIER PREMIUM 2.0 CVT
Chassis/Eng# : ZSU600072718/3ZRB731637
Accident Date : 18/07/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount SS
30.	1	REAR SPORT RIM R/H	769.00	X
31.	1	FRONT WIPER GARNISH R/H	69.00	X
32.	1	FRONT FENDER TOP RUBBER R/H	152.00	X
33.	1	FRONT DOOR INNER BOARD R/H	965.00	?
List Total SS :			19,567.94	
25.00% Discount SS :			4,891.99	
			14,675.95	
LABOUR :				
TO TRANSFER R/H FRONT DOOR COMPONENT TO NEW DOOR			180.00	60%
RUST PROOFING TREATMENT			100.00	
REMOVE & REINSTALL FRONT SUSPENSION R/H			250.00	
COMPUTER WHEEL ALIGNMENT			120.00	60%
SPRAY PAINT DAMAGED AREA AFFECTED			1,200.00	110%
CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION			90.00	30%
TO CUT OFF R/H RUNNING BOARD PANEL R/H FRONT PILLAR				
LOWER KNOCK AND STRAIGHTEN FRONT CHASSIS FRAME AND				
RE-ALIGN BODY			1,100.00	70%
Labour Total SS :			3,040.00	

SingDollars : Seventeen Thousand Seven Hundred Fifteen & Cents Ninety-Five Only

COMPLETE VMS PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LIXX Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Non-repair information(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Advised by Repairer
Signature:
Date:

Total SS : 17,715.95

Scanned with CamScanner