

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 22 Jul 2020

Preliminary Advice

Insured Vehicle No	: SKE764Y	Accident Date	: 19/06/2020
TP Vehicle No	: SKW899Y	Assignment Date	: 21/07/2020
Make	: VOLVO S60	Est. Duration of Repair	: 0
Date of Inspection	: 21/07/2020		
Inspection At	: SK AUTOMOBILE PTE LTD (HQ) 23 KAKI BUKIT AVENUE 4, #03-01 VICOM INSPECTION CENTRE SINGAPORE 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s body,n/s body and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :