

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jul 2020		21 Jul 2020 14:28 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: NIL , ID: NIL									
Main Claimant: WOON WEE PENG , ID: S1826681D									
Vehicle Reg. No.: SKW899Y		Date of Loss: 19/06/2020 11:00 - :59 [56 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D202334/C02/TKL		Policy/Cover Note No.: DMHCSN19306819000							
Vehicle Reg. No. (Insured): SKE764Y		Policy No. (Claimant): MA002643							
		Excess: S\$0.00							
Repairer: SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: Etiqa Insurance Pte Ltd (HQ) - Tel: 63360477									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 30/07/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKW899Y (SNM20D202334/C02/TKL)**
[SKE764Y]

TP
WOON WEE PENG
Jun 19 2020 11:00AM
[NIL]
SK Automobile Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail Print
1	22/06/20 14:45	Accident Statement		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	22/07/20 11:46	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail Print
1	19/06/20 17:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
2	19/06/20 17:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
3	19/06/20 17:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
4	19/06/20 17:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
5	19/06/20 17:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
6	19/06/20 17:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
7	19/06/20 17:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
8	19/06/20 17:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
9	19/06/20 17:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	22/07/20 12:04	General View		Load JPG ☒
2	22/07/20 12:04	General View		Load JPG ☒
3	22/07/20 12:04	General View		Load JPG ☒
4	22/07/20 12:04	General View		Load JPG ☒
5	22/07/20 12:04	General View		Load JPG ☒
6	22/07/20 12:04	General View		Load JPG ☒
7	22/07/20 12:04	General View		Load JPG ☒
8	22/07/20 12:04	General View		Load JPG ☒
9	22/07/20 12:04	General View		Load JPG ☒
10	22/07/20 12:04	General View		Load JPG ☒
11	22/07/20 12:04	General View		Load JPG ☒
12	22/07/20 12:04	General View		Load JPG ☒
13	22/07/20 12:04	General View		Load JPG ☒
14	22/07/20 12:04	General View		Load JPG ☒
15	22/07/20 12:04	General View		Load JPG ☒
16	22/07/20 12:05	General View		Load JPG ☒
17	22/07/20 12:05	General View		Load JPG ☒
18	22/07/20 12:05	General View		Load JPG ☒
19	22/07/20 12:05	General View		Load JPG ☒
20	22/07/20 12:05	General View		Load JPG ☒
21	22/07/20 12:05	General View		Load JPG ☒
22	22/07/20 12:05	General View		Load JPG ☒
23	22/07/20 12:05	General View		Load JPG ☒

Assessment Reports				1 per page ▾	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
24	22/07/20 12:05	General View		Load JPG	☒
25	22/07/20 12:05	General View		Load JPG	☒
26	22/07/20 12:05	General View		Load JPG	☒
27	22/07/20 12:05	General View		Load JPG	☒
28	22/07/20 12:05	General View		Load JPG	☒
29	22/07/20 12:05	General View		Load JPG	☒
30	22/07/20 12:05	General View		Load JPG	☒
31	22/07/20 12:05	General View		Load JPG	☒
32	22/07/20 12:05	General View		Load JPG	☒
33	22/07/20 12:05	General View		Load JPG	☒
34	22/07/20 12:05	General View		Load JPG	☒
35	22/07/20 12:05	General View		Load JPG	☒
36	22/07/20 12:05	General View		Load JPG	☒
37	22/07/20 12:05	General View		Load JPG	☒
38	22/07/20 12:05	General View		Load JPG	☒
39	22/07/20 12:05	General View		Load JPG	☒
40	22/07/20 12:05	General View		Load JPG	☒
41	22/07/20 12:05	General View		Load JPG	☒
42	22/07/20 12:05	General View		Load JPG	☒
43	22/07/20 12:05	General View		Load JPG	☒
44	22/07/20 12:05	General View		Load JPG	☒
45	22/07/20 12:05	General View		Load JPG	☒
46	22/07/20 12:05	General View		Load JPG	☒
47	22/07/20 12:05	General View		Load JPG	☒
48	22/07/20 12:05	General View		Load JPG	☒
49	22/07/20 12:05	General View		Load JPG	☒
50	22/07/20 12:05	General View		Load JPG	☒
51	22/07/20 12:05	General View		Load JPG	☒
52	22/07/20 12:05	General View		Load JPG	☒
53	22/07/20 12:05	General View		Load JPG	☒
54	22/07/20 12:05	General View		Load JPG	☒
55	22/07/20 12:05	General View		Load JPG	☒
56	22/07/20 12:05	General View		Load JPG	☒
57	22/07/20 12:05	General View		Load JPG	☒
58	22/07/20 12:05	General View		Load JPG	☒
59	22/07/20 12:05	General View		Load JPG	☒
60	22/07/20 12:05	General View		Load JPG	☒
61	22/07/20 12:05	General View		Load JPG	☒
62	22/07/20 12:05	General View		Load JPG	☒
63	22/07/20 12:05	General View		Load JPG	☒
64	22/07/20 12:05	General View		Load JPG	☒
65	22/07/20 12:05	General View		Load JPG	☒
66	22/07/20 12:05	General View		Load JPG	☒
67	22/07/20 12:05	General View		Load JPG	☒
68	22/07/20 12:05	General View		Load JPG	☒
69	22/07/20 12:05	General View		Load JPG	☒
70	22/07/20 12:05	General View		Load JPG	☒
71	22/07/20 12:05	General View		Load JPG	☒
72	22/07/20 12:05	General View		Load JPG	☒
Documentation				1 per page ▾	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
1	19/06/20 17:12	Sketch Plan [Linked Accident Report Documents]		Load TIF	

Assessment Reports			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	22/07/20 11:48	LTA	Load PDF	
2	18/08/20 09:46	LETTER	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	1 per page	☒
1	22/06/20 14:45	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail Print
1	19/06/20 17:13	Accident Photo	Load JPG	☒
2	19/06/20 17:13	Accident Photo	Load JPG	☒
3	19/06/20 17:13	Accident Photo	Load JPG	☒
4	19/06/20 17:13	Accident Photo	Load JPG	☒
5	19/06/20 17:13	Accident Photo	Load JPG	☒
6	19/06/20 17:13	Accident Photo	Load JPG	☒
7	19/06/20 17:13	Accident Photo	Load JPG	☒
8	19/06/20 17:13	Accident Photo	Load JPG	☒
9	19/06/20 17:13	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail Print
1	19/06/20 17:12	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20007515/AVF3S2**Date:** 18/08/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN19306819000
Claimant Vehicle No :	SKW899Y	Insured Vehicle No :	SKE764Y
Date of Loss:	19/06/2020	Nature of Claim:	TP
		Claim No:	SNM20D202334/C02/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW899Y	Engine No:	B4204T111328840
Make & Model:	VOLVO S60, 2.0 T5 (A)	Chassis No:	YV1FS40LDG2399797
Reg. Date:	30/09/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	Beige		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/45 R17	Rear Tyre Size:	235/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/07/2020	
Date Inspected:	21/07/2020 Inspected At:	8 Kaki Bukit Ave 4 #08-45, Premier @ Kaki Bukit Singapore 415875 Repairer: SK Automobile Pte Ltd
Estimated Period of Repair:	0.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value (EST) :	\$69,000.00
OMV :	\$25,961.00
PARF Rebate (1) :	\$21,259.00
Quota Premium Paid :	\$60,101.00
COE Rebate (2) :	\$30,668.00
Total Rebate (1) + (2) = :	\$51,927.00

The total amount incurred will be Market Value \$69,000.00 minus Total Rebate \$51,927.00 = \$17,073.00

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Aug 2020)
Parts:	143	VOLVO S60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW899Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >