

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

MUS'AB BIN IBRAHIM BAMADHAJ  
BLK 526B PASIR RIS ST 51 #03-513  
SINGAPORE 512526

Contact : 91111712

## ESTIMATE

Repair Code : CLM16337  
Date in : 21/07/2020  
Vehicle Num. : SFL7313S  
Model : HONDA CIVIC 1.8L A  
Chassis/Eng# : JHMFD16308S216535/R18A13036586

|  |                         |                          |                              |
|--|-------------------------|--------------------------|------------------------------|
|  |                         | Subtotal before discount | 10,322.00                    |
|  | Percentage discount 20% |                          | 2,064.40                     |
|  |                         | <b>Sub-total 1</b>       | <b>8,257.60</b>              |
| FRONT BUMPER CLIPS - SET                     | <i>New</i>              | 1                        | 50.00 <del>30 50.00</del>    |
| FRONT BUMPER NUMBER PLATE                    | <i>Dented</i>           | 1                        | 25.00 <del>✓ 25.00</del>     |
| FRONT BUMPER NUMBER PLATE HOLDER             | <i>Dented</i>           | 1                        | 50.00 <del>30 50.00</del>    |
| FRONT GRILLE CLIPS - SET                     | <i>New</i>              | 1                        | 50.00 <del>20 50.00</del>    |
| REAR BOOTLID INNER TRIM BOARD CLIPS - SET    | <i>New</i>              | 1                        | 50.00 <del>30 50.00</del>    |
| REAR BOOTLID NUMBER PLATE                    | <i>Best</i>             | 1                        | 25.00 <del>✓ 25.00</del>     |
| REAR BOOTLID NUMBER PLATE HOLDER             | <i>Dented</i>           | 1                        | 50.00 <del>30 50.00</del>    |
| REAR BUMPER CLIPS - SET                      | <i>New</i>              | 1                        | 80.00 <del>30 80.00</del>    |
| REAR BUMPER REVERSE SENSOR - SET             | <i>Damaged</i>          | 1                        | 350.00 <del>200 350.00</del> |
| REAR END PANEL INNER TOP GARNISH CLIPS - SET | <i>New</i>              | 1                        | 50.00 <del>10 50.00</del>    |
| REAR FENDER INNER TRIM BOARD CLIPS L/R - SET | <i>New</i>              | 2                        | 50.00 <del>60 100.00</del>   |
| REAR FLOOR PANEL INSULATOR                   | <i>New</i>              | 1                        | 300.00 <del>200 300.00</del> |
| REAR TAILLAMP CLIPS L/R - SET                | <i>New</i>              | 2                        | 30.00 <del>20 60.00</del>    |
| TRIANGLE WARNING SIGN                        | <i>Cracked</i>          | 1                        | 350.00 <del>150 350.00</del> |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# N-51 AUTOMOTIVE PTE LTD

2 Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

MUS'AB BIN IBRAHIM BAMADHAJ  
BLK 526B PASIR RIS ST 51 #03-513  
SINGAPORE 512526

Contact : 91111712

## ESTIMATE

Repair Code : CLM16337  
Date in : 21/07/2020  
Vehicle Num. : SFL7313S  
Model : HONDA CIVIC 1.8L A  
Chassis/Eng# : JHMFD16308S216535/R18A13036586

|                          |                 |
|--------------------------|-----------------|
| Subtotal before discount | 1,590.00        |
| Percentage discount 0%   | 0.00            |
| <b>Sub-total 2</b>       | <b>1,590.00</b> |
| <b>Parts-total</b>       | <b>9,847.60</b> |

860

## LABOUR

- To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.
- To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.
- To transfer rear bootlid mechanism lock outer handle reflector

30 100.00  
70 100.00  
120 140.00  
400 800.00  
1200 1,400.00  
80 100.00  
1600 2,600.00  
80 120.00  
60 80.00

3640

|                      |           |
|----------------------|-----------|
| Labour Total         | 5,440.00  |
| Parts & Labour Total | 15,287.60 |

KK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

page 5

total: 11926.80  
A/S: 9K

Adnan Lj  
A/S 21/07/20  
12 Days.