

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MUS'AB BIN IBRAHIM BAMADHAJ
BLK 526B PASIR RIS ST 51 #03-513
SINGAPORE 512526

Contact : 91111712

TP Budget Direct
Shirley.

ESTIMATE

Repair Code : CLM16337

Date in : 21/07/2020

Vehicle Num. : SFL7313S

Model : HONDA CIVIC 1.8L A

Chassis/Eng# : JHMFD16308S216535/R18A13036586

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Rehd</i>	1	638.00	✓ 638.00
FRONT BUMPER NUMBER PLATE GARNISH <i>Rehd</i>	1	34.10	✓ 34.10
FRONT BUMPER REINFORCEMENT <i>Best</i>	1	218.00	✓ 218.00
FRONT BUMPER RH FOGLAMP <i>could</i>	1	250.40	✓ 250.40
FRONT BUMPER RH FOGLAMP BRACKET <i>Not in</i>	1	16.50	x 16.50
FRONT BUMPER RH FOGLAMP GARNISH <i>could</i>	1	22.20	✓ 22.20
FRONT BUMPER SIDE RETAINER L/R <i>Not in</i>	2	12.80	✓ 25.60
FRONT GRILLE <i>could</i>	1	84.60	✓ 84.60
FRONT GRILLE 'LOGO' EMBLEM <i>Not in</i>	1	23.40	✓ 23.40
FRONT GRILLE OUTER COVER <i>at</i>	1	175.30	✓ 175.30
FRONT GRILLE TOP GARNISH <i>Rehd</i>	1	65.70	✓ 65.70
FRONT HEADLAMP L/R <i>could</i>	2	912.10	✓ 1,824.20
FRONT HEADLAMP LOWER BRACKET L/R <i>Best</i>	2	29.10	✓ 58.20
REAR BOOTLID <i>Dented</i>	1	610.70	✓ 610.70
REAR BOOTLID '1.8' EMBLEM <i>2</i>	1	17.00	✓ 17.00
REAR BOOTLID 'CIVIC' EMBLEM <i>Not in</i>	1	29.10	✓ 29.10
REAR BOOTLID 'I-VTEC' EMBLEM	1	34.10	✓ 34.10
REAR BOOTLID 'LOGO' EMBLEM	1	25.70	✓ 25.70

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 #01-18 Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MUS'AB BIN IBRAHIM BAMADHAJ

BLK 526B PASIR RIS ST 51 #03-513

SINGAPORE 512526

Contact : 91111712

ESTIMATE

Repair Code : CLM16337

Date in : 21/07/2020

Vehicle Num. : SFL7313S

Model : HONDA CIVIC 1.8L A

Chassis/Eng# : JHMFD16308S216535/R18A13036586

REAR BOOTLID HINGES L/R	<i>Neu</i>	2	48.60	<i>x</i>	97.20
REAR BOOTLID INNER LOWER RUBBER STOPPER L/R	<i>Neu</i>	2	12.50	<i>x</i>	25.00
REAR BOOTLID INNER RUBBER STOPPER L/R	<i>Neu</i>	2	18.50	<i>x</i>	37.00
REAR BOOTLID INNER TRIM BOARD	<i>Del'd</i>	1	133.70	✓	133.70
REAR BOOTLID LOCK CABLE	<i>Neu</i>	1	87.60	<i>x</i>	87.60
REAR BOOTLID LOCK STRIKER	<i>Neu</i>	1	27.50	<i>x</i>	27.50
REAR BOOTLID MECHANISM LOCK	<i>Pay'd</i>	1	194.50	✓	194.50
REAR BOOTLID NUMBER PLATE LAMP GARNISH	<i>incl'd</i>	1	121.60	✓	121.60
REAR BOOTLID NUMBER PLATE LAMP L/R	<i>Neu</i>	2	15.50	<i>x</i>	31.00
REAR BOOTLID REFLECTOR INNER BLACK GASKET L/R	<i>Neu</i>	2	15.20	✓	30.40
REAR BOOTLID REFLECTOR L/R	<i>incl'd</i>	2	145.10	✓	290.20
REAR BOOTLID WEATHER STRIP	<i>lit</i>	1	97.60	✓	97.60
REAR BUMPER	<i>Dist'd</i>	1	638.00	✓	638.00
REAR BUMPER EXHAUST COVER	<i>Pay'd</i>	1	19.50	✓	19.50
REAR BUMPER MUDFLAT L/R	<i>Not Neu</i>	2	74.90	<i>x</i>	149.80
REAR BUMPER SIDE RETAINER L/R	<i>Neu</i>	2	14.90	✓	29.80
REAR END PANEL	<i>Distorted</i>	1	300.50	✓	300.50
REAR END PANEL INNER TOP GARNISH	<i>Del'd</i>	1	56.10	✓	56.10

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg No : 200616038C

GST Registration No : 200616038C

MUS'AB BIN IBRAHIM BAMADHAJ
BLK 526B PASIR RIS ST 51 #03-513
SINGAPORE 512526

ESTIMATE

Repair Code : CLM16337

Date in : 21/07/2020

Vehicle Num : SFL7313S

Model : HONDA CIVIC 1.8L A

Chassis/Eng# : JHMF16308S216535/R18A13036586

REAR EXHAUST CHROME TAIL PIPE L/R	ut	2	93.40	✓	186.80
REAR EXHAUST GASKET	nu	1	38.50	+	38.50
REAR EXHAUST HEAT COVER	AK nu	1	43.80	X✓	43.80
REAR EXHAUST RUBBER MOUNTING	AK nu	2	16.00	+	32.00
REAR EXHAUST SILENCER BOX	Best	1	535.00	✓	535.00
REAR FENDER INNER TRIM BOARD L/R	Dented	2	145.90	/	291.80
REAR FLOOR LOWER JET PANEL	Dented	1	265.00	/	265.00
REAR FLOOR PANEL	Buckled	1	992.20	✓	992.20
REAR FLOOR PANEL TOP BOARD COVER	Dented	1	316.00	✓	316.00
REAR FLOOR SIDE PANEL L/R	Repair	2	205.00	+	410.00
REAR FLOOR SPONGE COMPARTMENT TRAY	could	1	56.50	✓	56.50
REAR TAILLAMP INNER BLACK GASKET L/R	nu	2	10.50	✓	21.00
REAR TAILLAMP INNER PANEL L/R	Repair	2	65.70	+	131.40
REAR TAILLAMP L/R	could	2	226.20	✓	452.40
REAR TAILLAMP LOWER BRACKET L/R	Best	2	14.90	/	29.80

*** This is a computer-generated document which requires no signature.***

page 3

Rear Spare tyre screw lock Rnd 45.00 ✓
Rear RH fender inner air vent nu 38.00 +
Front Radiator nu 1507.40 X
coolant 5/4 80 X,
nu nu

928350
7426.80

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MUS'AB BIN IBRAHIM BAMADHAJ
BLK 526B PASIR RIS ST 51 #03-513
SINGAPORE 512526

Contact : 91111712

ESTIMATE

Repair Code : CLM16337

Date in : 21/07/2020

Vehicle Num. : SFL7313S

Model : HONDA CIVIC 1.8L A

Chassis/Eng# : JHMF16308S216535/R18A13036586

		Subtotal before discount	10,322.00
Percentage discount 20%			2,064.40
		Sub-total 1	8,257.60
FRONT BUMPER CLIPS - SET	<i>Neu</i>	1	50.00 30 50.00
FRONT BUMPER NUMBER PLATE	<i>Dented</i>	1	25.00 ✓ 25.00
FRONT BUMPER NUMBER PLATE HOLDER	<i>Dented</i>	1	50.00 30 50.00
FRONT GRILLE CLIPS - SET	<i>Neu</i>	1	50.00 20 50.00
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	<i>Neu</i>	1	50.00 30 50.00
REAR BOOTLID NUMBER PLATE	<i>Beut</i>	1	25.00 ✓ 25.00
REAR BOOTLID NUMBER PLATE HOLDER	<i>Dented</i>	1	50.00 30 50.00
REAR BUMPER CLIPS - SET	<i>Neu</i>	1	80.00 30 80.00
REAR BUMPER REVERSE SENSOR - SET	<i>Damaged</i>	1	350.00 200 350.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>Neu</i>	1	50.00 10 50.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	<i>Neu</i>	2	50.00 60 100.00
REAR FLOOR PANEL INSULATOR	<i>Neu</i>	1	300.00 200 300.00
REAR TAILLAMP CLIPS L/R - SET	<i>Neu</i>	2	30.00 20 60.00
TRIANGLE WARNING SIGN	<i>Crushed</i>	1	350.00 150 350.00

*** This is a computer-generated document which requires no signature. ***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MUS'AB BIN IBRAHIM BAMADHAJ
BLK 526B PASIR RIS ST 51 #03-513
SINGAPORE 512526

ESTIMATE

Repair Code : CLM16337

Date in : 21/07/2020

Vehicle Num. : SFL7313S

Model : HONDA CIVIC 1.8L A

Chassis/Eng# : JHMFD16308S216535/R18A13036586

Contact : 91111712

Subtotal before discount 1,590.00

Percentage discount 0% 0.00

Sub-total 2 1,590.00

Parts-total 9,847.60

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof rack, trim upholstery, car's seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the changed body parts, repair portion, and where consistent to the accident.

To re-spray painting on the rear end, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To remove and change exhaust silencer on L/R side, to align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on removed and replaced panel.

To transfer rear bootlid mechanism lock outer handle reflector

Labour Total 5,440.00

Parts & Labour Total 15,287.60

16,639.92

K Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 5

total: 11926.80

A/S: 9K

Adnan Lj
A/S 21/07/20
12 Days.