

TP: CHINA
SER:
20/7/2020
(Mon)

K. Kim Hin

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 31243

Vehicle Insured : SKV 9973 L
Accident Date : 16-Jul-2020

Date : 20-Jul-2020

Our Ref : 020294 (CHINA) / QUEK

PAGE : 1

LOH KIM CHAH (MR)
Singapore

Not Authorized

Recovery B & paint 4 days

ESTIMATED COST OF REPAIR FOR LEXUS RX350 LUXURY AT(3456cc)(2017) SKR380C

1 pc rear bumper		RM 995.00	✓
2 pcs rear bumper side retainer (LH/RH)	@ S\$110.00	RM 220.00	X
10 pcs rear bumper clips	@ S\$ 5.50	RM 55.00	✓
1 pc rear bumper sponge		124.00	?
1 pc rear bumper reinforcement		515.30	?
1 pc rear bumper lower spoiler		361.00	✓
2 pcs rear bumper lower side garnish (LH/RH)	@ S\$152.00	RM 304.00	X
1 pc n/s rear bumper exhaust chrome		325.00	?
2 pcs rear bumper parking sensor - inner (LH/RH)	@ S\$490.00	980.00	?
1 pc o/s rear bumper parking sensor -outer		RM 490.00	X
4 pcs rear bumper parking sensor bracket	@ S\$ 38.00	152.00	?
1 pc tailgate		RM 1,249.00	✓
1 pc tailgate glass moulding		RM 107.10	✓
1 pc tailgate logo		RM 195.00	✓
1 pc tailgate 'LEXUS' emblem		RM 64.30	✓
1 pc tailgate 'RX350' emblem		RM 77.60	✓
1 pc tailgate lock		RM 961.70	X

Less 10% : 7,176.00
-717.60

6,458.40

1 pc tailgate glass sealant	RM 40.00	sn —
1 pc tailgate glass damping seal	RM 20.00	sn —
1 pc to reprogram rear parking sensor and recalibrate blind spot monitor sensor	280.00	sn ?

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SKV 9973 L
Our Ref : 020294

Page : 2
No. : 31243

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

400.00 ✓

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

To remove and refit reverse sensor
assy.

60.00 ✓

To putty and respray on affected
portions.

500.00 440

Total : -----
S\$ 7,878.40
=====

Singapore Dollars Seven Thousand Eight Hundred
and Seventy Eight and Cents Forty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: