

TP: CHINA
SER:
20/7/2020
(Mon)



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SKV 9973 L
Accident Date : 16-Jul-2020

No. : 31243

Date : 20-Jul-2020

Our Ref : 020294 (CHINA) / QUEK

PAGE : 1

LOH KIM CHAH (MR)
Singapore

Not Authorized

84498.20

Return B4 paint

4 day

ESTIMATED COST OF REPAIR FOR LEXUS RX350 LUXURY AT(3456cc)(2017) SKR380C
=====

1 pc rear bumper		Re	995.00	✓
2 pcs rear bumper side retainer (LH/RH)	@ S\$110.00	sn	220.00	X
10 pcs rear bumper clips	@ S\$ 5.50	Re	55.00	✓
1 pc rear bumper sponge		CMA	124.00	✓
1 pc rear bumper reinforcement		R	515.30	X
1 pc rear bumper lower spoiler		R	361.00	✓
2 pcs rear bumper lower side garnish (LH/RH)	@ S\$152.00	sn	304.00	X
1 pc n/s rear bumper exhaust chrome		sn	325.00	X
1 pc rear bumper parking sensor - inner (LH/RH) @ 418.00	@ S\$490.00	short	980.00	2+
1 pc o/s rear bumper parking sensor -outer		sn	490.00	X
4 pcs rear bumper parking sensor bracket	@ S\$ 38.00	Nuc	152.00	✓
1 pc tailgate		R	1,249.00	✓
1 pc tailgate glass moulding		Re	107.10	✓
1 pc tailgate logo		Re	195.00	✓
1 pc tailgate 'LEXUS' emblem		Re	64.30	✓
1 pc tailgate 'RX350' emblem		Re	77.60	✓
1 pc tailgate lock		R	961.70	X
			7,176.00	
Less 10% :			-717.60	
			6,458.40	
1 pc tailgate glass sealant		Re	40.00	sn
1 pc tailgate glass damping seal		Re	20.00	sn
1 pc to reprogram rear parking sensor and recalibrate blind spot monitor sensor		sn	280.00	sn X

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SKV 9973 L
Our Ref : 020294

Page : 2
No. : 31243

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

400.00 ✓

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

To remove and refit reverse sensor
assy.

60.00 ✓

To putty and respray on affected
portions.

500.00 440/

Total : S\$ 7,878.40
=====

Singapore Dollars Seven Thousand Eight Hundred
and Seventy Eight and Cents Forty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: