

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jul 2020		21 Jul 2020 16:27 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: TAN LAI HOCK , ID: S7348787J									
Main Claimant: LAM SIN HONG JUSTINE , ID: S9239779C									
Vehicle Reg. No.: SMD8532D		Date of Loss: 18/07/2020 02:00 - :59 [130 Months and 23 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D202496/C02/TOHHS		Policy/Cover Note No.: DMPCSN A00023642001 (Comprehensive) Coverage: 03/03/2020 - 02/03/2021							
Vehicle Reg. No. (Insured): SFK805R		Policy No. (Claimant): DMPCSN3066461900							
		Excess: S\$4,000.00							
Repairer: RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Alfred Toh - 6389 6183]									
Claimant's Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 30/07/2020]									
Adj Asg. Remarks: Please survey third party vehicle & let us have your report & bill for our negotiation with third party workshop									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMD8532D (SNM20D202496/C02/TOHHS)**
[SFK805R]

TP

LAM SIN HONG JUSTINE

Jul 18 2020 2:00AM

[TAN LAI HOCK]

RICO 60 AUTO SERVICES PTE LTD

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/07/20 16:53	Chassis Number	Load JPG	
2	22/07/20 16:53	Odometer Reading	Load JPG	
3	22/07/20 16:58	General View	Load JPG	
4	22/07/20 16:58	General View	Load JPG	
5	22/07/20 16:58	General View	Load JPG	
6	22/07/20 16:58	General View	Load JPG	
7	22/07/20 16:58	General View	Load JPG	
8	22/07/20 16:58	General View	Load JPG	
9	22/07/20 16:58	General View	Load JPG	
10	22/07/20 16:58	General View	Load JPG	
11	22/07/20 16:58	General View	Load JPG	
12	22/07/20 16:58	General View	Load JPG	
13	22/07/20 16:58	General View	Load JPG	
14	22/07/20 16:58	General View	Load JPG	
15	22/07/20 16:58	General View	Load JPG	
16	22/07/20 16:58	General View	Load JPG	
17	22/07/20 16:58	General View	Load JPG	
18	22/07/20 16:58	General View	Load JPG	
19	22/07/20 16:58	General View	Load JPG	
20	22/07/20 16:58	General View	Load JPG	
21	22/07/20 16:58	General View	Load JPG	
22	22/07/20 16:58	General View	Load JPG	
23	22/07/20 16:58	General View	Load JPG	
24	22/07/20 16:58	General View	Load JPG	
25	22/07/20 16:58	General View	Load JPG	
26	22/07/20 16:58	General View	Load JPG	
27	22/07/20 16:58	General View	Load JPG	
28	22/07/20 16:58	General View	Load JPG	
29	22/07/20 16:58	General View	Load JPG	
30	22/07/20 16:58	General View	Load JPG	
31	22/07/20 16:58	General View	Load JPG	
32	22/07/20 16:58	General View	Load JPG	
33	22/07/20 16:58	General View	Load JPG	
34	22/07/20 16:58	General View	Load JPG	
35	22/07/20 16:58	General View	Load JPG	
36	22/07/20 16:58	General View	Load JPG	
37	22/07/20 16:58	General View	Load JPG	
38	22/07/20 16:58	General View	Load JPG	
39	22/07/20 16:58	General View	Load JPG	
40	22/07/20 16:58	General View	Load JPG	

Photos/Images				3 per page ▾	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	22/07/20 16:58	General View		Load JPG	☒
42	22/07/20 16:58	General View		Load JPG	☒
43	22/07/20 16:58	General View		Load JPG	☒
44	22/07/20 16:58	General View		Load JPG	☒
45	22/07/20 16:58	General View		Load JPG	☒
46	22/07/20 16:58	General View		Load JPG	☒
47	22/07/20 16:58	General View		Load JPG	☒
48	22/07/20 16:58	General View		Load JPG	☒
49	22/07/20 16:58	General View		Load JPG	☒
50	22/07/20 16:58	General View		Load JPG	☒
51	22/07/20 16:58	General View		Load JPG	☒
52	22/07/20 16:58	General View		Load JPG	☒
53	22/07/20 16:58	General View		Load JPG	☒
54	22/07/20 16:58	General View		Load JPG	☒
55	22/07/20 16:58	General View		Load JPG	☒
56	22/07/20 16:58	General View		Load JPG	☒
57	22/07/20 16:58	General View		Load JPG	☒
58	22/07/20 16:58	General View		Load JPG	☒
59	22/07/20 16:58	General View		Load JPG	☒
60	22/07/20 16:58	General View		Load JPG	☒
61	22/07/20 16:58	General View		Load JPG	☒
62	22/07/20 16:58	General View		Load JPG	☒
63	22/07/20 16:58	General View		Load JPG	☒
64	22/07/20 16:58	General View		Load JPG	☒
65	22/07/20 16:58	General View		Load JPG	☒
66	22/07/20 16:58	General View		Load JPG	☒
67	22/07/20 16:58	General View		Load JPG	☒
68	22/07/20 16:58	General View		Load JPG	☒
69	22/07/20 16:58	General View		Load JPG	☒
70	22/07/20 16:58	General View		Load JPG	☒
71	22/07/20 16:58	General View		Load JPG	☒
72	22/07/20 16:58	General View		Load JPG	☒
73	22/07/20 16:58	General View		Load JPG	☒
74	22/07/20 16:58	General View		Load JPG	☒
75	22/07/20 16:58	General View		Load JPG	☒
76	22/07/20 16:58	General View		Load JPG	☒
77	22/07/20 16:58	General View		Load JPG	☒
78	22/07/20 16:58	General View		Load JPG	☒
79	22/07/20 16:58	General View		Load JPG	☒
80	22/07/20 16:58	General View		Load JPG	☒
81	22/07/20 16:58	General View		Load JPG	☒
82	22/07/20 16:58	General View		Load JPG	☒
83	22/07/20 16:58	General View		Load JPG	☒
84	22/07/20 16:58	General View		Load JPG	☒
85	22/07/20 16:58	General View		Load JPG	☒
86	22/07/20 16:58	General View		Load JPG	☒
87	22/07/20 16:58	General View		Load JPG	☒
88	22/07/20 16:58	General View		Load JPG	☒
89	22/07/20 16:58	General View		Load JPG	☒
90	22/07/20 16:58	General View		Load JPG	☒
91	22/07/20 16:58	General View		Load JPG	☒
92	22/07/20 16:58	General View		Load JPG	☒
93	22/07/20 16:58	General View		Load JPG	☒

Photos/Images			3 per page ▼		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
94	23/07/20 14:50	Reinspection Photo		Load JPG	☒
95	23/07/20 14:50	Reinspection Photo		Load JPG	☒
96	23/07/20 14:50	Reinspection Photo		Load JPG	☒
97	23/07/20 14:50	Reinspection Photo		Load JPG	☒
98	23/07/20 14:50	Reinspection Photo		Load JPG	☒
99	23/07/20 14:50	Reinspection Photo		Load JPG	☒
100	23/07/20 14:50	Reinspection Photo		Load JPG	☒
101	23/07/20 14:50	Reinspection Photo		Load JPG	☒
102	23/07/20 14:50	Reinspection Photo		Load JPG	☒
103	23/07/20 14:50	Reinspection Photo		Load JPG	☒
104	23/07/20 14:50	Reinspection Photo		Load JPG	☒
105	23/07/20 14:50	Reinspection Photo		Load JPG	☒
106	23/07/20 14:50	Reinspection Photo		Load JPG	☒
107	23/07/20 14:50	Reinspection Photo		Load JPG	☒
108	23/07/20 14:50	Reinspection Photo		Load JPG	☒
109	23/07/20 14:50	Reinspection Photo		Load JPG	☒
110	23/07/20 14:50	Reinspection Photo		Load JPG	☒
111	23/07/20 14:50	Reinspection Photo		Load JPG	☒
112	23/07/20 14:50	Reinspection Photo		Load JPG	☒
113	23/07/20 14:50	Reinspection Photo		Load JPG	☒
114	23/07/20 14:50	Reinspection Photo		Load JPG	☒
115	23/07/20 14:50	Reinspection Photo		Load JPG	☒
116	23/07/20 14:50	Reinspection Photo		Load JPG	☒
117	23/07/20 14:50	Reinspection Photo		Load JPG	☒
118	23/07/20 14:50	Reinspection Photo		Load JPG	☒
119	23/07/20 14:50	Reinspection Photo		Load JPG	☒
120	23/07/20 14:50	Reinspection Photo		Load JPG	☒
121	23/07/20 14:50	Reinspection Photo		Load JPG	☒
122	23/07/20 14:50	Reinspection Photo		Load JPG	☒
123	23/07/20 14:50	Reinspection Photo		Load JPG	☒
124	23/07/20 14:50	Reinspection Photo		Load JPG	☒
125	23/07/20 14:50	Reinspection Photo		Load JPG	☒
126	23/07/20 14:50	Reinspection Photo		Load JPG	☒
127	23/07/20 14:50	Reinspection Photo		Load JPG	☒
128	23/07/20 14:50	Reinspection Photo		Load JPG	☒
129	23/07/20 14:50	Reinspection Photo		Load JPG	☒
130	23/07/20 14:50	Reinspection Photo		Load JPG	☒
131	23/07/20 14:50	Reinspection Photo		Load JPG	☒
132	23/07/20 14:50	Reinspection Photo		Load JPG	☒
133	23/07/20 14:50	Reinspection Photo		Load JPG	☒
134	23/07/20 14:50	Reinspection Photo		Load JPG	☒
135	23/07/20 14:50	Reinspection Photo		Load JPG	☒
136	23/07/20 14:50	Reinspection Photo		Load JPG	☒
137	23/07/20 14:50	Reinspection Photo		Load JPG	☒
138	23/07/20 14:50	Reinspection Photo		Load JPG	☒
139	23/07/20 14:50	Reinspection Photo		Load JPG	☒
140	23/07/20 14:50	Reinspection Photo		Load JPG	☒
141	23/07/20 14:50	Reinspection Photo		Load JPG	☒
142	23/07/20 14:50	Reinspection Photo		Load JPG	☒
143	23/07/20 14:50	Reinspection Photo		Load JPG	☒
144	23/07/20 14:50	Reinspection Photo		Load JPG	☒
145	23/07/20 14:50	Reinspection Photo		Load JPG	☒
146	23/07/20 14:50	Reinspection Photo		Load JPG	☒

Photos/Images

3 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
147	23/07/20 14:50	Reinspection Photo		Load JPG	☒
148	23/07/20 14:50	Reinspection Photo		Load JPG	☒
149	23/07/20 14:50	Reinspection Photo		Load JPG	☒
150	23/07/20 14:50	Reinspection Photo		Load JPG	☒
151	23/07/20 14:50	Reinspection Photo		Load JPG	☒
152	23/07/20 14:50	Reinspection Photo		Load JPG	☒
153	23/07/20 14:50	Reinspection Photo		Load JPG	☒
154	23/07/20 14:50	Reinspection Photo		Load JPG	☒
155	23/07/20 14:50	Reinspection Photo		Load JPG	☒
156	23/07/20 14:50	Reinspection Photo		Load JPG	☒
157	23/07/20 14:50	Reinspection Photo		Load JPG	☒
158	23/07/20 14:50	Reinspection Photo		Load JPG	☒
159	23/07/20 14:50	Reinspection Photo		Load JPG	☒
160	23/07/20 14:50	Reinspection Photo		Load JPG	☒
161	23/07/20 14:50	Reinspection Photo		Load JPG	☒

Documentation

1 per page

☒

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/07/20 16:25	Singapore Accident Statement		Load PDF	
2	21/07/20 16:25	REPORT OF SMD8532D		Load PDF	
3	21/07/20 16:25	REPORT OF GBF4206S		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI20007530/UQF3S2**Date:** 18/09/2020**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00023642001

**Claimant Vehicle
No :** SMD8532D**Insured
Vehicle No :** SFK805R

Date of Loss: 18/07/2020

Nature of Claim: TP

Claim
No: SNM20D202496/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMD8532D**

Make & Model: AUDI A4 AVANT, 2.0 TFSI (A)

Engine No: CDN040684

Reg. Date: 25/08/2009 (Man. Year: 2009)

Chassis No: WAUZZZ8K59A232069

Colour: Black

Odometer: 146711 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/07/2020

Date Inspected: 22/07/2020 Inspected At:

RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @
KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

9/18/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$10,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2020)
Parts:	143	AUDI A4 AVANT 2.0 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD8532D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >