

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/20007530/Uqf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD P5-320

at Workshop m/s Rico 60

of _____

Insured: SFLK 805 R

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 58

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Rep 6000

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMD P5-320 Yr Regn: 8, 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Audi A4 Avant c.c 1984

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading 146711 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W A N 2228 K 59 A 2320 69

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

18/7/20

D.O.I.

22/7/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Roof.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 36307 NTH 21693

Should claim GBF 42065

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SMD 8532 D
AUDI A4

Not Authorized
1/53
To be signed by the customer
7 days

ATTN:		CHASSIS NO. 7d	
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	BONNET <i>See ✓</i>	1	
2	BONNET LOCK <i>11X</i>	1	
3	BONNET CATCH <i>11X</i>	1	
4	BONNET INSULATOR <i>11X</i>	1	
5	BONNET HINGE (L+R) <i>11X</i>	2	
6	BONNET DAMPER (L+R) <i>11X</i>	2	
7	BONNET STOPPER (L+R) <i>11X</i>	2	
8	BONNET RUBBER STRIP (L+R) <i>11X</i>	2	
9	HEADLAMP (L+R) <i>1/514 0/500 lpc</i>	2	
10	HEADLAMP BRACKET (L+R) <i>0/500 lpc</i>	2	
11	HEADLAMP NOZZLE (L+R) <i>0/500 lpc</i>	2	
12	FRONT GRILLE <i>?</i>	1	
13	FRONT GRILLE LOGO (AUDI) <i>See ✓</i>	1	
14	FRONT GRILLE FRAME <i>?</i>	1	
15	FRONT SENSOR (L+R) <i>11X</i>	2	
16	FRONT BUMPER <i>DD/100 ✓</i>	1	
17	FRONT BUMPER RETAINER (L+R) <i>?</i>	2	
18	FRONT BUMPER REINFORCEMENT BAR <i>?</i>	1	
19	FRONT BUMPER BRACKET (L+R) <i>?</i>	2	
20	FRONT BUMPER BEAM <i>?</i>	1	
21	FRONT BUMPER SPONGE <i>?</i>	1	
22	FRONT BUMPER NOZZLE COVER (L+R) <i>?</i>	2	
23	FRONT BUMPER TOWING CAP <i>11X</i>	1	
24	FRONT BUMPER FOG LAMP (L+R) <i>0/500 lpc</i>	2	
25	FRONT BUMPER FOG LAMP CHROME (L+R) <i>?</i>	2	
26	FRONT BUMPER FOG LAMP GARNISH (L+R) <i>?</i>	2	
27	FRONT BUMPER LOWER GRILLE <i>11X</i>	1	
28	FRONT BUMPER UNDERCOVER <i>11X</i>	1	
29	FRONT FENDER (L+R) <i>11X</i>	2	
30	FRONT FENDER COWLING (L+R) <i>11X</i>	2	
31	FRONT SUPPORT PANEL <i>See ✓</i>	1	
32	FRONT SUPPORT PANEL TOP GARNISH <i>See ✓</i>	1	
33	AIRCON CONDENSOR <i>11X</i>	1	
34	HIGH PRESSURE HOSE <i>11X</i>	1	
35	LOW PRESSURE HOSE <i>11X</i>	1	
36	AIRCON CONDENSOR AIR GUIDE (CENTER) <i>11X</i>	1	
37	AIRCON CONDENSOR AIR GUIDE (L+R) <i>11X</i>	2	
38	RADIATOR <i>11X</i>	1	
39	SUCTION PIPE <i>11X</i>	1	
40	DISCHARGE PIPE <i>11X</i>	1	

41	RADIATOR FAN COWLING	11X	1
42	RADIATOR FAN BLADE	11X	1
43	RADIATOR FAN MOTOR	11X	1
44	WIPER WASHER TANK	11X	1
45	WIPER WASHER MOTOR	11X	1
46	REAR WINDSCREEN MOULDING	11X	1
47	TAILGATE	11X	1
48	TAILGATE WIPER	11X	1
49	TAILGATE WIPER MOTOR	11X	1
50	TAILGATE WIPER GARNISH		1
51	TAILGATE LOGO (AUDI)	11X	1
52	TAILGATE LAMP (L+R)	11X	2
53	TAILGATE LOCK SWITCH	11X	1
54	TAILGATE CARPLATE LAMP (L+R)	11X	2
55	TAILGATE LOCK	11X	1
56	TAILGATE LOCK COVER	11X	1
57	TAILGATE LOCK CATCH	11X	1
58	TAILGATE INNER TRIM TOP	11X	1
59	TAILGATE INNER TRIM BOTTOM	11X	1
60	TAILGATE HINGE (L+R)	11X	2
61	TAILGATE HINGE COVER (L+R)	11X	2
62	TAILGATE DAMPER (L+R)	11X	2
63	TAILGATE STOPPER (L+R)	11X	2
64	TAILGATE WEATHERSTRIP	?	1
65	TAIL LAMP (L+R)	?	2
66	TAIL LAMP PANEL (L+R)	11X	2
67	REAR BUMPER	11X/22	1
68	REAR BUMPER RETAINER TOP (L+R)	?	2
69	REAR BUMPER RETAINER LOWER (L+R)	?	2
70	REAR BUMPER CENTER BRACKET	?	1
71	REAR BUMPER REINFORCEMENT BAR	?	1
72	REAR BUMPER REINFORCEMENT BRACKET (L+R)	?	2
73	REAR BUMPER SPONGE	?	2
74	REAR BUMPER REVERSE SENSOR SET	should be 5.2	4
75	REAR BUMPER TOW COVER	11X	1
76	REAR BUMPER LOWER	11X	1
77	REAR BUMPER LOWER GRILLE	?	1
78	REAR BUMPER UNDERCOVER	11X	1
79	REAR FENDER (L+R)	11X	2
80	REAR FENDER WINDOW MOULDING (L+R)	11X	2
81	REAR FENDER WINDOW CHROME STRIP TOP (L+R)	11X	2
82	REAR FENDER WINDOW CHROME STRIP BOTTOM (L+R)	11X	2
83	REAR FENDER INNER TRIM TOP (L+R)	11X	2
84	REAR FENDER INNER TRIM BOTTOM (L+R)	11X	2
85	REAR FENDER COWLING (L+R)	11X	2
86	END PANEL	11X	1
87	END PANEL TOP GARNISH	11X	1
88	END PANEL TOP GARNISH TOP CHROME	11X	1

	REAR SMART LOCK ANTENNA	✓ 1X		1	
90	SPAREWHEEL PANEL	✓ 17X		1	
91	SPAREWHEEL PANEL TOP BOARD	✓ 1X		1	
92	SPAREWHEEL PANEL TOP BOARD TOP MAT	✓ 1X		1	
93	SPAREWHEEL PANEL TOP TRIM (L+R)	✓ 1X		2	
94	SPAREWHEEL PANEL TOP TRIM CENTER	✓ 1X		1	
95	EXHAUST PIPE	✓ 1X		1	
96	EXHAUST GASKET	✓ 1X		1	
97	EXHAUST BRACKET (L+R)	✓ 1X		2	
98	EXHAUST HEAT SHIELD (L+R)	✓ 1X		2	
	SUBTOTAL		\$ -		
	LESS 10%		\$ -		
	PARTS TOTAL		\$ -		
	SPECIAL NETT		QTY	PRICE	
1	BONNET INSULATOR CLIPS	✓ 11 X	10	\$ 100.00	
2	FRONT CARPLATE	. cm	1	\$ 300.00	
3	FRONT CARPLATE FRAME		1	\$ 120.00	
4	FRONT BUMPER CLIPS	m	10	\$ 100.00	
5	FRONT BUMPER CARBON FIBRE LOWER LIP	cna? 600	1	\$ 8,000.00	
6	FRONT BUMPER CARBON FIBRE LOWER LIP STICKER	?	1	\$ 600.00	
7	FRONT BUMPER CARBON FIBRE LOWER LIP CLIPS	✓ 11 X	20	\$ 300.00	
8	FRONT FENDER COWLING CLIPS	✓ 11 X	20	\$ 200.00	
9	FRONT SUPPORT PANEL TOP GARNISH CLIPS	✓ 11 X	10	\$ 100.00	
10	RADIATOR COOLANT	✓ 11 X	1	\$ 120.00	
11	REAR WINDSCREEN SEALANT	m 40	1	\$ 120.00	
12	TAILGATE WIPER BLADE	✓ 11 X	1	\$ 250.00	
13	TAILGATE INNER TRIM CLIPS (TOP)	✓ 11 X	10	\$ 100.00	
14	TAILGATE INNER TRIM CLIPS (BOTTOM)	✓ 11 X	10	\$ 100.00	
15	REAR CARPLATE	✓ 11 X	1	\$ 300.00	
16	REAR CARPLATE FRAME	✓ 11 X	1	\$ 120.00	
17	TAIL LAMP CLIPS	✓ 11 X	4	\$ 80.00	
18	TAIL LAMP PANEL SEALANT	✓ 11 X	1	\$ 120.00	
19	REAR BUMPER CLIPS	m 50	10	\$ 100.00	
20	REAR FENDER SEALANT	✓ 11 X	1	\$ 120.00	
21	REAR FENDER WINDOW SEALANT	✓ 11 X	1	\$ 120.00	
22	REAR FENDER INNER TRIM CLIPS TOP	✓ 11 X	20	\$ 200.00	
23	REAR FENDER INNER TRIM CLIPS BOTTOM	✓ 11 X	20	\$ 200.00	
24	REAR FENDER COWLING CLIPS	✓ 11 X	20	\$ 200.00	
25	END PANEL SEALANT	m	1	\$ 120.00	
26	END PANEL TOP GARNISH CLIPS	✓ 11 X	10	\$ 100.00	
27	SPAREWHEEL PANEL SEALANT	✓ 11 X	1	\$ 120.00	
28	EXHAUST CHROME TIP SET	gvcx	4	\$ 8,000.00	
	SPECIAL NETT TOTAL		\$ 10,470.00		
	LABOUR		QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	1200	1	\$ 6,000.00	
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1700	1	\$ 4,200.00	

3	TO RUST PROOF ACCIDENT AFFECTED AREA	90	1	\$	400.00
4	TO RNR REAR WINDSCREEN	120	1	\$	400.00
5	TO RNR REAR FENDER WINDOW	11X	1	\$	600.00
6	TO RNR REAR BOOT MECHANISM	60	1	\$	400.00
7	TO RNR UPHOLSTERY,GARNISH AND ATTACHMENT PARTS	80	1	\$	600.00
8	TO RNR FRONT SENSOR & CHECK FUNCTION	50	1	\$	200.00
9	TO RNR REVERSE SENSOR & CHECK FUNCTION.		1	\$	200.00
10	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	11X	1	\$	450.00
11	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	?	1	\$	300.00
12	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	30	1	\$	200.00
13	TO CHECK WIRING LAYOUT AND FOG LAMP FUNCTION		1	\$	200.00
14	TO CHECK WIRING LAYOUT AND TAILGATE LAMP FUNCTION		1	\$	200.00
15	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION		1	\$	200.00
16	TO RNR REAR SMART LOCK ANTENNA AND TEST FUNCTION	11X	1	\$	250.00
17	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11X	1	\$	800.00
18	TO DO WATER LEAK TEST .	11X	1	\$	100.00
19	TO RNR FUEL TANK TO ASSIST WORK LOAD	11X	1	\$	450.00
20	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	11X	1	\$	250.00
	TOTAL			\$	16,400.00
	GRAND TOTAL COST			\$	26,870.00