

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

 Model : **Toyota Sienta**

 Registraion No : **SMS 2958 U**

 Chassis No: **NHP1707173524**

 Year of Manufacturing: **2019**

S/No	Qty	Items	Unit Price	Amount	
1	1	Rear bumper ✓ DE	\$ 458.10	\$ 458.10	✓
2	1	LHS rear bumper ✓ DE	\$ 199.80	\$ 199.80	67.2
3	1	RHS rear bumper ✓ DE	\$ 199.80	\$ 199.80	67.2
4	1	Rear bumper cover ✓ DE	\$ 297.40	\$ 297.40	171
5	2	Rear bumper retainer ✓ DE	\$ 189.40	\$ 378.80	139
6	2	Rear bumper reflector ✓ CRA	\$ 181.20	\$ 362.40	138.4
7	1	Rear bumper plate ✗ NN	\$ 290.10	\$ 290.10	✗
8	2	Rear bumper seal ✗ NN	\$ 43.70	\$ 87.40	✗
9	1	Rear bumper energy absorber ✗ NN	\$ 231.20	\$ 231.20	✗
10	2	Rear bumper support LH ✓CRA RH ✗ SVC	\$ 597.80	\$ 1,195.60	70
11	1	Rear bumper outside moulding retainer ✗ NN	\$ 190.10	\$ 190.10	✗
12	1	Tailgate ✓ BUC	\$ 1,247.50	\$ 1,247.50	1086
13	1	Tailgate weatherstrip ✓ TWI	\$ 403.40	\$ 403.40	356.6
14	2	Tailgate hinge ✗ NN	\$ 189.10	\$ 378.20	✗
15	2	Tailgate absorber ✗ NN	\$ 388.10	\$ 776.20	✗
16	1	Tailgate logo ✓ NEC	\$ 83.70	\$ 83.70	✓
17	1	Tailgate emblem ✓ NEC	\$ 87.70	\$ 87.70	65.6
18	2	Tailgate reflector ✓ CUT	\$ 313.30	\$ 626.60	563.1
19	1	Tailgate inner trim board ✓ CUT	\$ 579.10	\$ 579.10	415
20	1	Tailgate lock ✓ JM	\$ 387.90	\$ 387.90	✓
21	1	Tailgate lock switch ✗ NN	\$ 197.10	\$ 197.10	✗
22	1	Tailgate catch ✗ NN	\$ 123.20	\$ 123.20	✗
23	2	Tailgate stopper ✗ NN	\$ 58.90	\$ 117.80	✗
24	1	Tailgate garnish ✓ DE	\$ 387.40	\$ 387.40	281.6
25	2	LHS & RHS taillamp ✓ CRA	\$ 453.50	\$ 907.00	790.8
26	2	LHS & RHS taillamp panel ✗ NN	\$ 378.90	\$ 757.80	✗
27	1	End panel ✓ BUC	\$ 554.90	\$ 554.90	✓
28	1	End panel top garnish ✓ DE	\$ 287.10	\$ 287.10	207
29	2	LHS & RHS air duct LH ✓ BR RH ✗ NN	\$ 198.70	\$ 397.40	45
30	1	Spare tyre compartment ✓ BUC	\$ 798.10	\$ 798.10	✓

31	1	Spare tyre compartment board ✓ CRA	\$	578.10	\$	578.10	541.75
32	1	Rear windscreen wiper ✗ NN	\$	190.20	\$	190.20	✗
33	1	Rear windscreen wiper motor ✓ DM	\$	780.10	\$	780.10	559.3
34	1	Rear windscreen moulding ✓ NEC	\$	188.20	\$	188.20	112
35	1	Rear windscreen ✗ NN	\$	1,181.90	\$	1,181.90	✗
36	2	No.plate lamp ✓ CRA	\$	71.20	\$	142.40	✓
37	2	RHS & LHS Rear fender inner trim board ✓CRA	\$	829.70	\$	1,659.40	1406.2
38	1	LHS rear fender shield ✓ MIS	\$	281.20	\$	281.20	152
39	1	Keyless antenna ✓ DM	\$	89.70	\$	89.70	✓
						<u>\$ 18,080.00</u>	9749.55
						-25% <u>\$ 4,520.00</u>	
Total for spare parts						<u>\$ 13,560.00</u>	7312.16

Special Nett

1	10	Rear bumper clip ✓ NEC	\$	5.00	\$	50.00	30
2	10	LHS rear fender shield clip ✓ NEC	\$	5.00	\$	50.00	20
3	10	RHS rear fender shield clip ✗ NN	\$	5.00	\$	50.00	✗
4	10	End panel top garnish clip ✓ NEC	\$	5.00	\$	50.00	20
5	1	Rear no.plate with casing ✓ BT	\$	50.00	\$	50.00	40
6	1 set	Reverse sensor ✓ DM	\$	380.00	\$	380.00	220
	1	Rear camera ✓ DM	\$	780.00	\$	780.00	250
						<u>\$ 1,410.00</u>	580
Total for SP						<u>\$ 1,410.00</u>	
Sub-Total for Parts :						<u>\$ 14,970.00</u>	

Labour: 2500

Total: 10392.16

-20%: 8300

7 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____