

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

 Model : **Toyota Sienta**

 Registraion No : **SMS 2958 U**

 Chassis No: **NHP1707173524**

 Year of Manufacturing: **2019**

S/No	Qty	Items	Unit Price	Amount
1	1	Rear bumper / <i>Re</i>	\$	-
2	1	LHS rear bumper / <i>Re</i>	\$	-
3	1	RHS rear bumper / <i>Re</i>	\$	-
4	1	Rear bumper cover / <i>Re</i>	\$	-
5	2	Rear bumper retainer / <i>Re</i> / <i>CRA</i>	\$	-
6	2	Rear bumper reflector / <i>Re</i> / <i>CR</i>	\$	-
7	1	Rear bumper plate X	\$	-
8	2	Rear bumper seal X	\$	-
9	1	Rear bumper energy absorber X	\$	-
10	2	Rear bumper support ? LH ✓	\$	-
11	1	Rear bumper outside moulding retainer X	\$	-
12	1	Tailgate / <i>Bue</i>	\$	-
13	1	Tailgate weatherstrip / <i>Tu</i>	\$	-
14	2	Tailgate hinge X / <i>na</i>	\$	-
15	2	Tailgate absorber X / <i>na</i>	\$	-
16	1	Tailgate logo / <i>Gabe</i>	\$	-
17	1	Tailgate emblem / <i>na</i>	\$	-
18	2	Tailgate reflector ✓	\$	-
19	1	Tailgate inner trim board ✓	\$	-
20	1	Tailgate lock / <i>Im</i>	\$	-
21	1	Tailgate catch X	\$	-
22	2	Tailgate stopper X / <i>na</i>	\$	-
23	1	Tailgate garnish / <i>Re</i>	\$	-
24	2	LHS & RHS taillamp ✓	\$	-
25	2	LHS & RHS taillamp panel X	\$	-
26	1	End panel / <i>Bue</i>	\$	-
27	1	End panel top garnish / <i>Re</i>	\$	-
28	2	LHS & RHS air duct ? LH ✓	\$	-
29	1	Spare tyre compartment ✓	\$	-
30	1	Spare tyre compartment board ✓ X 2	\$	-
31	1	Rear windscreen wiper X / <i>na</i>	\$	-
32	1	Rear windscreen wiper motor ✓	\$	-
33	1	Rear windscreen moulding / <i>Re</i>	\$	-
34	1	Rear windscreen X / <i>na</i>	\$	-
35	2	No.plate lamp ✓	\$	-

\$ -

-25% \$ -

Total for spare parts \$ -

Special Nett

1	10	Rear bumper clip	✓	\$	5.00	\$	50.00
2	10	LHS rear fender shield clip	✓	\$	5.00	\$	50.00
3	10	RHS rear fender shield clip	X	\$	5.00	\$	50.00
4	10	End panel top garnish clip	✓	\$	5.00	\$	50.00
5	1	Rear no.plate with casing	✓	\$	50.00	\$	50.00
6	1 set	Reverse sensor	✓	\$	280.00	\$	280.00

LH Fender shield - m.s
 spare side Bumper, re

Total for SP \$ 530.00

Sub-Total for Parts : \$ 530.00

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	1,500.00
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,200.00
3		Apply rust proofing on the adjacent panels	\$	100.00
4		To supply under coating / putty on parts replaced	\$	80.00
5		To perform water seepage test after repair	\$	80.00
6		To reset engine management system with diagnostic fault	\$	150.00
7		Disconned and check electrical wiring, harness, wire socket	\$	80.00
8		Remove and replace front windscreen	\$	150.00
12		Remove and refit rear end panel lining and garnish to facilitate repair	\$	80.00
13		Remove and replace exhaust pipe/system to facilitate repair	\$	80.00

7-9 Days.

Unpsum repair.

After repair photos.

Eno Qian.

22/7/2020.

TOTAL AMOUNT : \$ 3,500.00

OVERALL COST: \$ 4,030.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: