

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT20002207	Page	1
	300 BEACH ROAD #17-04/07	Date	: 20. Jul 2020		
	THE CONCOURSE	Customer No.	: WZL009		
	SINGAPORE 199555	Svc Advisor	:		
Registration No	: SMK1699R	Engine No	: L15Z16206824		
Chassis No	: MRHGM6670KT000225	Date Time	: 20. Jul 2020 2:24:03 PM		
Model	: CITY 1.5V CVT 2019 (EURO 6)	Surveyor Name	:		
Owner's Name	: CHAN GUAN ZHI	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 20/7/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
60210-T9A-T50ZZ	PANEL COMP,R.FR.FENDER <i>repair</i>	1	343.80	25	257.85	18.05	275.90
67010-T9A-T00ZZ	PANEL COMPR.FR.DOOR <i>buc</i>	1	738.40	25	553.80	38.77	592.57
67326-T9A-T01	TAPER.FR.DOOR SASH CENTER <i>re</i>	1	18.50	25	13.87	0.97	14.84
67410-T9A-T01ZZ	HINGER.FR.DOOR UPPER ?	1	56.80	25	42.60	2.98	45.58
67420-T9A-T01ZZ	HINGER.FR.DOOR LOWER ?	1	58.40	25	43.80	3.07	46.87
72324-T9A-T01	SUB SEALR.FR DOOR ?	1	14.60	25	10.95	0.77	11.72
72325-T9A-T01	SUB SEALR.ROOF ?	1	27.20	25	20.40	1.43	21.83
72326-T9A-T01	SEALFR.DOOR LOWER ?	1	19.90	25	14.92	1.04	15.96
72340-T9A-T11	CHECKER COMP,R.FR.DOOR ?	1	23.10	25	17.32	1.21	18.53
67510-T9A-T00ZZ	PANEL COMPR.RR.DOOR <i>buc</i>	1	712.50	25	534.37	37.41	571.78
67825-T9A-T01	TAPER.RR.DOOR SASH CENTER <i>re</i>	1	15.40	25	11.55	0.81	12.36
67910-T2M-T02ZZ	HINGER.RR.DOOR UPPER <i>bt</i>	1	41.40	25	31.05	2.17	33.22
67920-T2M-T02ZZ	HINGER.RR.DOOR LOWER <i>buc</i>	1	42.00	25	31.50	2.21	33.71
72824-T9A-T01	SUB SEALR.RR.DOOR ?	1	16.10	25	12.07	0.84	12.91
72826-T9A-T01	SEALRR.DOOR LOWER ?	1	7.10	25	5.32	0.37	5.69
72840-T9A-T11	CHECKER COMP,R.RR. <i>ca</i>	1	9.50	25	7.12	0.50	7.62
72825-T9A-T11	SUB SEAL,R.RR.DOOR OUTER ?	1	43.90	25	32.92	2.30	35.22
04631-T9A-T00ZZ	PANELR.SIDE SILL ?	1	1174.80	25	881.10	61.68	942.78
04635-T9A-T00ZZ	PANELR.FR.OUTSIDE ?	1	1257.50	25	943.12	66.02	1009.14

Printed on 21/7/2020 6:49:14 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53 50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

(Member of the Oriental Holdings Berhad)

Body and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SMK1699R
Chassis No : MRHGM6670KT000225
Model : CITY 1.5V CVT 2019 (EURO 6)
Owner's Name : CHAN GUAN ZHI
Ins Policy No :
Date of Accident : 20/7/2020

Document No. : SQT20002207
Date : 20. Jul 2020
Customer No. : WZL009
Svc Advisor :
Engine No : L15Z16206824
Date | Time : 20. Jul 2020 2:24:03 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
63210-T9A-T00ZZ	STIFFENER COMPR.CENTER PILLAR ?	1	207.40	25	155.55	10.89	166.44
63220-T9A-305ZZ	STIFFENER COMPR.SIDE SILL ?	1	285.00	25	213.75	14.96	228.71
76201-T5A-J31ZQ	CAPR.SKULL T99 <i>ms</i>	1	48.20	25	36.15	2.53	38.68
76208-T9A-T21	SETR.RH.RC MIRROR <i>bu</i>	1	287.90	25	215.92	15.11	231.03
04636-T9A-T00ZZ	PANEL SETR.RR.OUTSIDE <i>repair</i>	1	1276.90	25	957.67	67.04	1024.71
Sum Item					<u>5044.67</u>	<u>353.13</u>	<u>5,397.80</u>
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BMS03R	REMOVE & RENEW FR SEAT & LEATHER TRIM	1	800.00 <i>650</i>		800.00	56.00	856.00
BML11R	REMOVE & INSTALL CABIN WIRE HARNESS. RESET ECU	1	800.00 <i>325</i>		800.00	56.00	856.00
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	650.00		650.00	45.50	695.50
BKDR32R	REMOVE & TRANSFER ITEMS TO NEW RR R SLIDING DR.	1	650.00		650.00	45.50	695.50
BKSP12R	CUT OFF & RENEW R SILL PANEL. STRAIGHTEN ALIGN	<i>10650</i>	6000.00 <i>3900</i>		6000.00	420.00	6420.00
BOJSE	BODY JOINT SEALANT RH F DOOR	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT RHR DOOR	1	100.00		100.00	7.00	107.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>520</i>	1	4000.00 <i>3120</i>		4000.00	280.00	4280.00
BOJSE	BODY JOINT SEALANT SILL PANEL	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	520.00		520.00	36.40	556.40
BML00I	INSPECT ALL LIGHTINGS MECHANISMS FOCUS HEADLAMP	1	180.00		180.00	12.60	192.60
Sum Labor					<u>14000.00</u>	<u>980.00</u>	<u>14,980.00</u>

Survey By Pasul - Hp 90010068

Date & Time 22/07/2020 @ 1020

Excess

Status

Signature *[Signature]*

Total Amount 19,044.67 1,333.13 20,377.80

Total (Inclusive of GST) 20,377.80

Printed on 21/7/2020 6:49:14 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

*9 days
Resin before
paint*

HONDA

KAH MOTOR CO. SDN. BHD.

(Member of the Oriental Holdings Berhad)

Paint and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT20002207	Page	3
Registration No	: SMK1699R	Date	: 20. Jul 2020		
Chassis No	: MRHGM6670KT000225	Customer No.	: WZL009		
Model	: CITY 1.5V CVT 2019 (EURO 6)	Svc Advisor	:		
Owner's Name	: CHAN GUAN ZHI	Engine No	: L15Z16206824		
Ins Policy No.	:	Date Time	: 20. Jul 2020 2:24:03 PM		
Date of Accident	: 20/7/2020	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 21/7/2020 6:49:14 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.