

Ryder

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-18/22 AutoHub @ Kaki Bukit, Singapore 417921

23/7/20, 11.15am

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# SDV133L

Model:

TOYOTA HARRIER

(11/7/2016)

Accident Date 17/7/2020

Location ANG MO KIO AVE 10

3P: GBE1145J(Sompo)

Q'ty	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper / NR	1,496.00	-	-
2	10 pcs	Front bumper clips / NR	-	50.00	-
3	1 pc	Front bumper tow cover / CUT	100.00	79.10	-
4	1 pc	Front bumper o/s insulator / NR	462.00	129	-
5	1 pc	Front bumper o/s retainer / NR	146.00	-	-
6	1 pc	Front grille upper / CUT	986.00	530	-
7	6 pcs	Front grille clips / NR	-	30.00	-
8	1 pc	Front bumper grille (Lower) / CUT	398.00	276	-
9	1 pc	Front bumper lower spoiler / CUT	692.00	387.40	-
10	1 pc	Front o/s head-lamp / CUT	3,640.00	3300	-
11	1 pc	Front reg number plate X NN	-	45.00	-
12	1 pc	Front reg number plate bracket X NN	-	29.00	-
		Sub-Total:	7,920.00	154.00	0.00
			25%	0%	10%
		After Less %:	5,940.00	154.00	0.00
		Labour			
1		To remove and replace front damage parts	800.00	300	
2		To spray painting.	600.00	250	
3		To check wiring.	100.00	30	
		Sub-Total:	1,500.00		
		Total:	7,594.00	8,124.40	
		After Less 20%:	6,075.20		

Chan San Choon

Director

DipEng, AAE(MIM),MSAE(Aust)



P-6335

-25%

4751.25

N-50

L-580



bizSAFE 8778 1999

24 hr accident call

Mobil 1



5381.25

Supp - 217.27

3598.52

L/S - 4478.81

= 4500

SDV133L ESTIMATEPg1

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# SDV133L Model: TOYOTA HARRIER

Accident Date 17/7/2020 (11/7/2016)

Location ANG MO KIO AVE 10 3P: GBE1145J(Sompo)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front grill emblem ✓ NEC	145.20	120 ✓ -	-
2	1 pc	Front bumper sponge(Middle) BR ✓	562.00	169.70 ✓	-
		Sub-Total:	707.20	0.00	0.00
			25%	0%	10%
		After Less %:	530.40	0.00	0.00
		Total:		530.40	
		After Less 20%:		424.32	



Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

289.70
-25%
217.27

