

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# SDV133L

Model: TOYOTA HARRIER

Accident Date 17/7/2020

(11/7/2016)

Location ANG MO KIO AVE 10

3P: GBE1145J(Sompo)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front grill emblem ✓ NEC	145.20	120 ✓ -	-
2	1 pc	Front bumper sponge(Middle) BR ✓	562.00	169.70 ✓	-
		Sub-Total:	707.20	0.00	0.00
			25%	0%	10%
		After Less %:	530.40	0.00	0.00
		Total:		530.40	
		After Less 20%:		424.32	



Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

289.70
-25%
217.27

