





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/07/2020

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB25P
Case Reference Number	BUS/07/20/1014
Registration Date	11/11/2008
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	SEAH TING HOCK
Type of Accident	Side Swipe
Accident Date and Time	15/7/2020 7:19 AM
Accident Reported Date and Time	15/7/2020 9:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107585
Special Instruction to ARC,if any	SMB25P-FRONT RIGHT PORTION SKS38X (TP) INSURED WITH
Prepared Date and Time	17/7/2020 9:38 AM
Chassis Number	WEB63442021000086
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$530.00
Total Spray Cost	\$446.00	\$354.00
Total Spare Part Cost	\$1,694.02	\$111.82
Total Other Cost	\$0.00	(\$176.80)
TOTAL COST	\$3,200.02	\$819.02
Lump Sum Total	\$0.00	\$800.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	17/07/2020 9:47 AM	20/07/2020 1:04 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/07/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$1,060.00				\$530.00			
Total Labour		\$1,060.00				\$530.00			
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$446.00				\$354.00			
Total Spray Painting & Panel Beating		\$446.00				\$354.00			
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Lump Sum Adjustment by Surveyor		\$0.00				(\$176.80)			
Total Other Costs		\$0.00				(\$176.80)			
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009362	BODY RH		COVER,HEADLAMP:RH, FIBREGLASS,MB OC500	1.00	\$621.00	100.00	\$0.00	Replace	Repair X R
6009701	VE		LAMP,BLINKER:FRONT, RIGHT,FOR MB OC500 LE	1.00	\$155.30	10.00	\$139.77	Replace	Replace / CRU
6009508	VE		HEADLAMP FOR MERCEDES OC500 LE, RIGHT	1.00	\$1,276.50	100.00	\$0.00	Replace	Repair X SVC
6009510	VE		LAMP,FRONT FOG,RIGHT SIDE FOR MB OC500LE	1.00	\$300.00	100.00	\$0.00	Replace	Repair X SVC
Total					\$2,352.80		\$139.77		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

139.77
530
+ 354

1,023.77
- 20%

819.02

LIS
\$ 800