

Section A - Accident Details

Registration Number	SHB340M
Case Reference Number	TAX/07/20/2038
Registration Date	19/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHENG WAI YIP
Type of Accident	Side Swipe
Accident Date and Time	20/7/2020 1:20 PM
Accident Reported Date and Time	20/7/2020 3:10 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107587
Special Instruction to ARC, if any	TP
Prepared Date and Time	20/7/2020 4:32 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$2,214.00	\$780.00
Total Spare Part Cost	\$10,279.94	\$1,008.38
Total Other Cost	\$1,165.32	(\$38.38)
TOTAL COST	\$14,504.26	\$2,150.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	21/07/2020 3:04 PM	21/07/2020 2:49 PM
Signature		
Remarks		L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2008-0047	Invoice Number	
Quotation Date	06.08.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
RESPRAY MIRROR COVER LH	\$180.00	\$80.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,214.00	\$780.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$445.32	\$445.32
Lump Sum Adjustment by Surveyor	\$0.00	(\$523.70)
Total Other Costs	\$1,165.32	(\$38.38)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number: 63685592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated: 06/08/2020

User ID: kimmingchin

57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Not Given	X
	NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X
	NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	X
53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	X
81521-47050	LENS & BODY,FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X
53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given	X
53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given	X
76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X
51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given	X
53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given	X
81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	✓
67002-47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair	✓
	STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓
68740-12120	HINGE LOWER LHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X
68720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given	X
68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X
53802-47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair	✓
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X
53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Not Given	X
53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
53852-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Not Given	X
42611-47140	WHEEL DISC, FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
75852-47900	MOULDING BODY, LH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	✓
61132-47030	PILLAR, FR BODY, LH	0.00	\$363.10	0.00	\$0.00	Replace	Not Given	X
87940-47310	MIRROR ASSY,LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given	X
81740-52040	MIRROR LAMP LH	1.00	\$65.30	10.00	\$58.77	Replace	Replace	✓
87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	100.00	\$0.00	Replace	Repair	✓
Total			\$13,316.35		\$1,008.38			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1008.38
+ 400.00
+ 1265.32

2673.70
- 207

2466.70

45 \$2150/-

3 days