


MBM WHEELPOWER PTE. LTD.



YOUR REF.: SKU7453P
 OUR REF.: SKZ1323U

TO: AIG Asia Pacific Insurance Pte. Ltd.
 CC: MOTOR CLAIMS DEPARTMENT

DATE: 22/7/2020
 FROM: Lee Shirley
 FAX: 6452 5333
 CONTACT: 8686 5188
 MAKE & MODEL: HONDA VEZEL 1.5X CVT
 CHASSIS NO.: RU11106121
 ENGINE NO.: L15B4026134
 YEAR MADE: 2015
 ACCIDENT DATE: 21 July 2020

FAX:

ESTIMATE FOR VEHICLE NO.: SKZ1323U

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAIL GATE		1	\$ 1100 <i>bt</i> 1,700.00
2	TAIL GATE GLASS MOULDING		1	\$ <i>all</i> 120.00
3	WEATHERSTRIP, TAILGATE		1	\$ <i>nnx</i> 150.00
4	TAIL GATE HINGE		2	\$ <i>nnx</i> 60.00
5	TAILGATE SPOILER		1	\$ <i>nnx</i> 250.00
6	TAIL GATE INNER TRIM		1	\$ <i>nnx</i> 480.00
7	TAIL GATE UPPER LINING		1	\$ <i>nnx</i> 120.00
8	TAIL GATE SIDE INNER LINING LH		1	\$ <i>nnx</i> 50.00
9	TAIL GATE SIDE INNER LINING RH		1	\$ <i>nnx</i> 50.00
10	TAIL GATE EMBLEM "VEZEL"		1	\$ <i>all</i> 50.00
11	TAIL GATE EMBLEM "HONDA" LOGO		1	\$ <i>all</i> 20.00
12	TAIL GATE LAMP LH		1	\$ <i>nnx</i> 300.00
13	TAIL GATE LAMP RH		1	\$ <i>nnx</i> 300.00
14	REAR BUMPER		1	\$ 850 <i>de</i> 1,000.00
15	REAR BUMPER REFLECTOR LH		1	\$ <i>nt</i> 150.00
16	REAR BUMPER REFLECTOR RH		1	\$ <i>nnx</i> 150.00
17	REAR BUMPER CORNER PANEL RH		1	\$ <i>nnx</i> 380.00
18	REAR BUMPER CORNER PANEL LH		1	\$ <i>Rv</i> 380.00
19	REAR BUMPER CORNER PANEL INNER LINING RH		1	\$ <i>nnx</i> 250.00
20	REAR BUMPER CORNER PANEL INNER LINING LH		1	\$ <i>nnx</i> 250.00
21	REAR BUMPER CORNER COVER BRACKET RH		1	\$ <i>nnx</i> 75.00
22	REAR BUMPER CORNER COVER BRACKET LH		1	\$ <i>nnx</i> 75.00
23	REAR BUMPER CROSS MEMBER		1	\$ <i>X</i> 200.00
24	REAR BUMPER CLIP		10	\$ <i>rec</i> 90.00
25	REAR BUMPER UNDERCOVER		1	\$ <i>nnx</i> 200.00

- 26 FENDER INNER LINER RH
- 27 FENDER INNER LINER LH
- 28 WHEEL ARCH PROTECTOR RH
- 29 WHEEL ARCH PROTECTOR LH
- 30 TAIL LAMP RH
- 31 TAIL LAMP LH
- 32 REAR END PANEL
- 33 REAR END PANEL TOP GARNISH

1	\$	x	100.00
1	\$	x	100.00
1	\$	nnx	150.00
1	\$	x	150.00
1	\$	x	500.00
1	\$	x	500.00
1	\$	Rx	650.00
1	\$	nnx	85.00

2380
20% - 1904

TOTAL:	\$	9,085.00
LESS 20%:	\$	(1,817.00)
PARTS TOTAL:	\$	7,268.00

SPECIAL NETT

- REAR NUMBER PLATE & HOLDER
- BODY SEALANT
- TAIL GATE SEALANT
- REAR BUMPER SENSOR

1	\$	x	50.00
1	\$	nnx	50.00
1	\$	new	80.00
1	\$	200mm	250.00

280.

LABOUR

- TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS
- TO REMOVE & INSTALL REAR UPHOLSTERY TO FACILITATE REPAIR
- TO REMOVE & INSTALL TAILGATE GLASS
- TO APPLY ANTI RUST COATING
- TO CHECK & RECONNECT ALL NECESSARY WIRING
- TO REMOVE & INSTALL REVERSE SENSOR
- TO SPRAY PAINT ON THE AFFECTED AREAS

\$	600	1,600.00
\$	60.	150.00
\$	120.	180.00
\$	30.	80.00
\$	30.	100.00
\$	30	80.00
\$	600	1,000.00

1470.

3654
1/5 @ 2900
4 days #

TOTAL:	\$	10,888.00
7% GST:	\$	762.16
GRAND TOTAL:	\$	11,650.16

Tanfah 97495749
- WP' 4 days
Lumpsum 27/7/20 @ 1140
Resurvey after repair
tanfah@lkhaut.com
to check part price

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: