


MBM WHEELPOWER PTE. LTD.



YOUR REF: SKU7453P
 OUR REF: SKZ1323U

TO: AIG Asia Pacific Insurance Pte. Ltd.
 CC: MOTOR CLAIMS DEPARTMENT

DATE: 22/7/2020
 FROM: Lee Shirley
 FAX: 6452 5333
 CONTACT: 8686 5188
 MAKE & MODEL: HONDA VEZEL 1.5X CVT
 CHASSIS NO.: RU11106121
 ENGINE NO.: L15B4026134
 YEAR MADE: 2015
 ACCIDENT DATE: 21 July 2020

FAX:

ESTIMATE FOR VEHICLE NO.: SKZ1323U

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAIL GATE		1	\$ <i>be</i> 1,700.00
2	TAIL GATE GLASS MOULDING		1	\$ <i>all</i> 120.00
3	WEATHERSTRIP, TAILGATE		1	\$ X 150.00
4	TAIL GATE HINGE		2	\$ X 60.00
5	TAILGATE SPOILER		1	\$ X 250.00
6	TAIL GATE INNER TRIM		1	\$ X 480.00
7	TAIL GATE UPPER LINING		1	\$ X 120.00
8	TAIL GATE SIDE INNER LINING LH		1	\$ X 50.00
9	TAIL GATE SIDE INNER LINING RH		1	\$ X 50.00
10	TAIL GATE EMBLEM "VEZEL"		1	\$ <i>all</i> 50.00
11	TAIL GATE EMBLEM "HONDA" LOGO		1	\$ <i>all</i> 20.00
12	TAIL GATE LAMP LH		1	\$ X 300.00
13	TAIL GATE LAMP RH		1	\$ X 300.00
14	REAR BUMPER		1	\$ <i>de</i> <i>ut</i> 1,000.00
15	REAR BUMPER REFLECTOR LH		1	\$ <i>ut</i> 150.00
16	REAR BUMPER REFLECTOR RH		1	\$ X 150.00
17	REAR BUMPER CORNER PANEL RH		1	\$ X 380.00
18	REAR BUMPER CORNER PANEL LH		1	\$ <i>Rv</i> 380.00
19	REAR BUMPER CORNER PANEL INNER LINING RH		1	\$ X 250.00
20	REAR BUMPER CORNER PANEL INNER LINING LH		1	\$ X 250.00
21	REAR BUMPER CORNER COVER BRACKET RH		1	\$ X 75.00
22	REAR BUMPER CORNER COVER BRACKET LH		1	\$ X 75.00
23	REAR BUMPER CROSS MEMBER		1	\$? 200.00
24	REAR BUMPER CLIP		10	\$ <i>reci</i> 90.00
25	REAR BUMPER UNDERCOVER		1	\$ X 200.00

26	FENDER INNER LINNER RH	1	\$	X	100.00
27	FENDER INNER LINNER LH	1	\$	X	100.00
28	WHEEL ARCH PROTECTOR RH	1	\$	X	150.00
29	WHEEL ARCH PROTECTOR LH	1	\$	X	150.00
30	TAIL LAMP RH	1	\$	X	500.00
31	TAIL LAMP LH	1	\$	X	500.00
32	REAR END PANEL	1	\$	Ry	650.00
33	REAR END PANEL TOP GARNISH	1	\$	X	85.00
TOTAL:					\$ 9,085.00
LESS 20%:					\$ (1,817.00)
PARTS TOTAL:					\$ 7,268.00

SPECIAL NETT

REAR NUMBER PLATE & HOLDER	1	\$	X	50.00
BODY SEALANT	1	\$	X	50.00
TAIL GATE SEALANT	1	\$		80.00
REAR BUMPER SENSOR	1	\$	200mm ✓	250.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	600	1,600.00
TO REMOVE & INSTALL REAR UPHOLSTERY TO FACILITATE REPAIR	\$	60.	150.00
TO REMOVE & INSTALL TAILGATE GLASS	\$	120.	180.00
TO APPLY ANTI RUST COATING	\$	30.	80.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	30.	100.00
TO REMOVE & INSTALL REVERSE SENSOR	\$	30	80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	600	1,000.00
TOTAL:	\$		10,888.00
7% GST:	\$		762.16
GRAND TOTAL:	\$		11,650.16

Tanfah 97445749
 -wp' 0 4 days
 Lumpsum 27/7/20 R 1140
 Resurvey after repair
 tanfah@lkhamp.com
 * to check part price

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: