

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Make & Model : Honda

Civic

Vehicle Number : SJY7597Z

Quantity	Description	Repairer's Estimate
	SIDE	
1	Bumper Strip X NN	\$200
1	Right Side Fender (Front RH door handle & lock cover) ✓	\$555 371.80 ✓
1	RH Wing Mirror (& signal) ✓ Jammed/BR	\$1,050 837 ✓
1	Under Tray Cover X NN	\$350
1	Rim tyre X NN	\$360
1	Right Headlight X NN	\$400
1	Condenser X NN	\$450
1	Radiator X NN	\$450
1	Reinforcement Bar Sponge X NN	\$450
	LABOUR & MISC	
	Checking of wiring, lighting and resetting	\$300 30 ✓
	Remove and replace damaged parts	\$500 X
	Apply undercoating on repaired and replaced panel	\$350 30 ✓
	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$350 250 ✓
	Respray including polishing and waxing on the changed body parts, repaired portortions where consistent to the accident	\$800 300 ✓
	Total Repair Cost :	\$6,565

CUT

1208.80
-20%
967.04

610

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK)
 22/07/20
 Without Prejudice
 3-2 repair days
 Lumpsum
 Resurvey after spray

967.04
 610
 1577.04

Lumpsum - \$1261.63
 = \$1250