

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : YEO MING JIE, EUGENE
 BLK 472B FERVALE STREET #18-47
 SINGAPORE 792472

Estimate No: MC1901293
 Date: 17 Jul 2020
 Policy No: MP312381
 Veh Reg No: SMG8251Z
 Make/Model: JAGUAR E-PACE 2.0P
 (200PS)

ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 16/07/2020
 TP Veh Reg No: GBG4215K

Not authorized
Resurvey B4 pricing
5-7 days

Estimate Repair Cost to Vehicle No : SMG8251Z

Description	U/Price	Quantity	Cost	Amount
			SS	SS
SPARE PARTS				
1 REAR WINDSCREEN WITH MOULDING		1 PC	950.00	✓
2 TAILGATE		1 PC	1,650.00	✓
3 TAILGATE EMBLEM		1 PC	105.00	✓
4 TAILGATE E-PACK LOGO		1 PC	105.00	✓
5 TAILGATE AWD LOGO		1 PC	105.00	✓
6 TAILGATE LAMP LH		1 PC	310.00	✓
7 TAILGATE NO PLATE LAMP LH & RH		2 PC	39.00	X
8 TAILGATE REVERSE CAMERA -CHECK PRICE		1 PC	0.0000	?
9 TAILGATE REVERSE CAMERA COVER -CHECK PRICE		1 PC	0.0000	?
10 TAILGATE ABSORBER LH & RH -CHECK PRICE		2 PC	0.0000	X
11 TAILGATE SENSOR LH -CHECK PRICE		1 PC	0.0000	?
12 TAILGATE LOCK		1 PC	0.0000	X
13 TAILGATE LOCK COVER		1 PC	0.0000	X
14 TAILGATE LOCK ACTUATOR		1 PC	95.00	X
15 TAILGATE RUBBER		1 PC	120.00	?
16 TAILGATE INNER TRIMBOARD -CHECK PRICE		1 PC	0.0000	?
17 TAILLAMP LH		1 PC	354.00	✓
18 REAR BUMPER		1 PC	1,150.00	✓
19 REAR BUMPER SIDE RETAINER UPPER LH		1 PC	60.00	?
20 REAR BUMPER SIDE RETAINER OUTER LH		1 PC	65.00	?
21 REAR BUMPER SIDE CLIPS -CHECK PRICE		15 PC	0.0000	?
22 REAR BUMPER LOWER GARNISH CENTER		1 PC	175.00	?
23 REAR BUMPER LOWER GARNISH SIDE LH		1 PC	40.00	?
24 REAR BUMPER LOWER MOULDING (SILVER)		1 PC	100.00	?
25 REAR BUMPER REINFORCEMENT		1 PC	360.00	?
26 REAR BUMPER CENTER BRACKET		1 PC	80.00	?
27 REAR BUMPER TOP BRACKET		1 PC	105.00	?
28 REAR BUMPER FOGLAMP LH -CHECK PRICE		1 PC	0.0000	✓
29 REAR BUMPER REVERSE SENSOR OUTER LH -CHECK PRICE		1 PC	0.0000	?
30 REAR BUMPER REVERSE SENSOR OUTER HOLDER LH -CHECK PRICE		1 PC	0.0000	?
31 REAR BUMPER REVERSE SENSOR INNER LH -CHECK PRICE		1 PC	0.0000	?
32 REAR BUMPER REVERSE SENSOR INNER HOLDER LH -CHECK PRICE		1 PC	0.0000	?
33 RADAR SENSOR LH -CHECK PRICE		1 PC	0.0000	?
34 RADAR SENSOR BRACKET LH -CHECK PRICE		1 PC	0.0000	?
35 REAR FENDER WHEEL ARCH TRIM LH -CHECK PRICE		1 PC	0.0000	✓
36 END PANEL OUTER		1 PC	380.00	?
37 END PANEL INNER		1 PC	1,380.00	?
38 END PANEL TOP GARNISH -CHECK PRICE		1 PC	0.0000	X

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : YEO MING JIE, EUGENE
 BLK 472B FERNSVALE STREET #18-47
 SINGAPORE 792472

Estimate No: MC1901293
Date: 17 Jul 2020
Policy No: MP312381
Veh Reg No: SMG8251Z
Make/Model: JAGUAR E-PACE 2.0P (200PS)

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 16/07/2020
TP Veh Reg No: GBG4215K

Estimate Repair Cost to Vehicle No : SMG8251Z

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
39 END PANEL REINFORCEMENT PLATE LH		1 PC	78.00	?
40 END PANEL BUFFER BRACKET LH		1 PC	24.00	?
41 REAR EXHAUST PIPE		1 PC	1,700.00	?
42 REAR EXHAUST PIPE CHROME LH		1 PC	198.00	✓
			9,728.00	
			1,459.20	11,187.20
			Add 15%	
			35.00	✓
			20.00	✓
			40.00	✓
				95.00
Special Nett				
43 NUMBER PLATE		1 PC	35.00	✓
44 INNER SEAL		1 PC	20.00	✓
45 SEALANT		1 PC	40.00	✓
LABOUR				
46 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	300
47 TO REMOVE & REFIT REAR WINDSCREEN		1 EA	120.00	✓
48 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	250.00	800
49 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.		1 PC	60.00	✓
50 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.		1 PC	60.00	✓
51 TO RESET RADAR SENSOR		1 PC	500.00	?
52 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.		1 PC	80.00	?
53 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.		1 PC	90.00	600
54 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL INNER & OUTER. TO KNOCK & REPAIR SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	1,600.00	?
55 TO SPRAY TAILGATE, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH		1 PC	1,200.00	900
				4,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : YEO MING JIE, EUGENE
BLK 472B FERNSVALE STREET #18-47
SINGAPORE 792472

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 16/07/2020
TP Veh Reg No: GBG4215K

Estimate No: MC1901293
Date: 17 Jul 2020
Policy No: MP312381
Veh Reg No: SMG8251Z
Make/Model: JAGUAR E-PACE 2.0P
(200PS)

Estimate Repair Cost to Vehicle No : SMG8251Z

Lump Sum Repair	SS 15,282.20
Add GST @ 7%	1,069.75
Total Amount payable	SS 16,351.95

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND THREE HUNDRED FIFTY ONE AND CENTS NINETY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE