

Kr

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : YEO MING JIE, EUGENE
BLK 472B FERVALE STREET #18-47

SINGAPORE 792472

Claim No: MC1901293
Ref No: MF1901280
Date: 15 Oct 2020
Policy No: MP312381
Veh Reg No: SMG8251Z
Make/Model: JAGUAR E-PACE 2.0P
(200PS)

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 16/07/2020
TP Veh Reg No: GBG4215K

DRAFT FINALISATION
Chassis No: SADFA2AX4K1Z45338
TP Ins Co: AIG

Repair Cost to Vehicle No (For Finalization): SMG8251Z

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 REAR WINDSCREEN WITH MOULDING		1 PC	950.00	
2 TAILGATE		1 PC	1,650.00	
3 TAILGATE EMBLEM		1 PC	105.00	
4 TAILGATE E-PACK LOGO		1 PC	105.00	
5 TAILGATE AWD LOGO		1 PC	105.00	
6 TAILGATE LAMP LH		1 PC	310.00	
7 TAILGATE RUBBER		1 PC	120.00	
8 TAILGATE INNER TRIMBOARD		1 PC	330.00	
9 TAILLAMP LH		1 PC	354.00	
10 REAR BUMPER		1 PC	1,150.00	
11 REAR BUMPER SIDE RETAINER UPPER LH		1 PC	60.00	
12 REAR BUMPER LOWER GARNISH SIDE LH		1 PC	40.00	
13 REAR BUMPER REINFORCEMENT		1 PC	360.00	
14 REAR BUMPER CENTER BRACKET		1 PC	80.00	
15 REAR BUMPER TOP BRACKET		1 PC	105.00	
16 REAR BUMPER FOGLAMP LH		1 PC	135.00	
17 REAR BUMPER REVERSE SENSOR OUTER LH		1 PC	170.00	
18 REAR FENDER WHEEL ARCH TRIM LH		1 PC	135.00	
19 REAR EXHAUST PIPE		1 PC	1,700.00	
20 REAR EXHAUST PIPE CHROME LH		1 PC	198.00	
21 REAR EXHAUST CHROME HEAT SHIELD		1 PC	86.00	
22 REAR EXHAUST MOUNTING		1 PC	34.00	
23 TAILGATE COVER		1 PC	64.00	
24 TAILLAMP COVER LH		1 PC	100.00	
25 REVERSE SENSOR WIRE HARNESS		1 PC	135.00	
			8,581.00	
	Add 15%		1,287.15	9,868.15
Special Nett				
26 NUMBER PLATE		1 PC	35.00	
27 INNER SEAL		1 PC	20.00	
28 SEALANT		1 PC	40.00	
				95.00

LABOUR

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : YEO MING JIE, EUGENE
 BLK 472B FERVALE STREET #18-47
 SINGAPORE 792472

Claim No: MC1901293
 Ref No: MF1901280
 Date: 15 Oct 2020
 Policy No: MP312381
 Veh Reg No: SMG8251Z
 Make/Model: JAGUAR E-PACE 2.0P
 (200PS)
 Chassis No: SADFA2AX4K1Z45338
 TP Ins Co: AIG

ATTN:

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 16/07/2020
 TP Veh Reg No: GBG4215K

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization): SMG8251Z

Description	U/Price	Quantity	Cost	Amount
			SS	SS
29 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	30.00	
30 TO REMOVE & REFIT REAR WINDSCREEN		1 EA	120.00	
31 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	80.00	
32 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.		1 PC	60.00	
33 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.		1 PC	60.00	
34 TO RESET REAR TAILBOOT ONTO ABSORBER AND LOCK		1 PC	180.00	
35 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.		1 PC	60.00	
36 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL INNER & OUTER. TO KNOCK & REPAIR SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	1,200.00	Pool
37 TO SPRAY TAILGATE, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH		1 PC	900.00	
				2,690.00

Amount Before Excess	SS 12,653.15
Less Excess	SS 500.00
Amount Before GST	SS 12,153.15
Add GST @ 7%	850.72
Total Amount payable	SS 13,003.87

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND AND THREE AND CENTS EIGHTY SEVEN ONLY

The above vehicle was surveyed by LKK - KENNETH on 28/07/2020

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170
 AUTHORIZED SIGNATURE

12353.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

0:919

SURVEYOR COPY

M/S : YEO MING JIE, EUGENE
BLK 472B FERNVALE STREET #18-47

SINGAPORE 792472

Estimate No: MC1901293
Date: 17 Jul 2020
Policy No: MP312381
Veh Reg No: SMG8251Z
Make/Model: JAGUAR E-PACE 2.0P (200PS)

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 16/07/2020
TP Veh Reg No: GBG4215K

Not Authorized
Resurvey B4 paint

Resurvey photo

5-7 days 09.7.2020

Estimate Repair Cost to Vehicle No : SMG8251Z

Description	U/Price	Quantity	Cost	Amount
			SS	SS
SPARE PARTS				
1 REAR WINDSCREEN WITH MOULDING <i>P1?</i>		1 PC	950.00	✓
2 TAILGATE		1 PC <i>B1</i>	1,650.00	✓
3 TAILGATE EMBLEM		1 PC <i>me</i>	105.00	—
4 TAILGATE E-PACK LOGO		1 PC <i>me</i>	105.00	—
5 TAILGATE AWD LOGO		1 PC <i>me</i>	105.00	—
6 TAILGATE LAMP LH		1 PC <i>Bu</i>	310.00	✓
7 TAILGATE NO-PLATE LAMP LH & RH		2 PC <i>lu</i>	39.00	X
8 TAILGATE REVERSE CAMERA - CHECK PRICE		1 PC <i>lu</i>	0.0000	?
9 TAILGATE REVERSE CAMERA COVER - CHECK PRICE		1 PC <i>lu</i>	0.0000	?
10 TAILGATE ABSORBER LH & RH - CHECK PRICE		2 PC <i>lu</i>	0.0000	X
11 TAILGATE SENSOR LH - CHECK PRICE		1 PC <i>lu</i>	0.0000	?
12 TAILGATE LOCK		1 PC <i>lu</i>	0.0000	X
13 TAILGATE LOCK COVER		1 PC <i>lu</i>	0.0000	X
14 TAILGATE LOCK ACTUATOR		1 PC <i>lu</i>	95.00	X
15 TAILGATE RUBBER		1 PC <i>lu</i>	120.00	? photo ✓
16 TAILGATE INNER TRIMBOARD - CHECK PRICE		1 PC <i>MTG CRACKED</i>	330.00	? photo ✓
17 TAILLAMP LH		1 PC <i>CM</i>	354.00	—
18 REAR BUMPER		1 PC <i>B1</i>	1,150.00	—
19 REAR BUMPER SIDE RETAINER UPPER LH		1 PC <i>CM</i>	60.00	? photo ✓
20 REAR BUMPER SIDE RETAINER OUTER LH		1 PC <i>lu</i>	65.00	?
21 REAR BUMPER SIDE CLIPS - CHECK PRICE		15 PC <i>lu</i>	0.0000	?
22 REAR BUMPER LOWER GARNISH CENTER		1 PC <i>lu</i>	175.00	?
23 REAR BUMPER LOWER GARNISH SIDE LH		1 PC <i>lu</i>	40.00	✓
24 REAR BUMPER LOWER MOULDING (SILVER)		1 PC <i>lu</i>	100.00	?
25 REAR BUMPER REINFORCEMENT		1 PC <i>B1</i>	360.00	? photo
26 REAR BUMPER CENTER BRACKET		1 PC <i>lu</i>	80.00	? photo
27 REAR BUMPER TOP BRACKET		1 PC <i>lu</i>	105.00	? photo
28 REAR BUMPER FOGLAMP LH - CHECK PRICE		1 PC <i>Bu</i>	0.0000	135.00
29 REAR BUMPER REVERSE SENSOR OUTER LH - CHECK PRICE		1 PC <i>shan</i>	170.00	? photo ✓
30 REAR BUMPER REVERSE SENSOR OUTER HOLDER LH - CHECK PRICE		1 PC <i>lu</i>	0.0000	X
31 REAR BUMPER REVERSE SENSOR INNER LH - CHECK PRICE		1 PC <i>lu</i>	0.0000	X
32 REAR BUMPER REVERSE SENSOR INNER HOLDER LH - CHECK PRICE		1 PC <i>lu</i>	0.0000	X
33 RADAR SENSOR LH - CHECK PRICE		1 PC <i>lu</i>	0.0000	X
34 RADAR SENSOR BRACKET LH - CHECK PRICE		1 PC <i>lu</i>	0.0000	X
35 REAR FENDER WHEEL ARCH TRIM LH - CHECK PRICE		1 PC <i>lu</i>	0.0000	—
36 END PANEL OUTER		1 PC <i>lu</i>	380.00	X
37 END PANEL INNER		1 PC <i>lu</i>	1,380.00	X
38 END PANEL TOP GARNISH - CHECK PRICE		1 PC <i>lu</i>	0.0000	X

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : YEO MING JIE, EUGENE
 BLK 472B FERVALE STREET #18-47
 SINGAPORE 792472

Estimate No: MC1901293
 Date: 17 Jul 2020
 Policy No: MP312381
 Veh Reg No: SMG8251Z
 Make/Model: JAGUAR E-PACE 2.0P
 (200PS)

ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 16/07/2020
 TP Veh Reg No: GBG4215K

Estimate Repair Cost to Vehicle No : SMG8251Z

Description	U/Price	Quantity	Cost	Amount
39 END-PANEL REINFORCEMENT-PLATE LH		1 PC	78.00	78.00
40 END-PANEL BUFFER-BRACKET LH		1 PC	24.00	24.00
41 REAR EXHAUST PIPE		1 PC	1,700.00	1,700.00
42 REAR EXHAUST PIPE CHROME LH		1 PC	198.00	198.00
			9,728.00	
		Add 15%	1,459.20	11,187.20

Special Nett

43 NUMBER PLATE		1 PC	35.00	35.00
44 INNER SEAL		1 PC	20.00	20.00
45 SEALANT		1 PC	40.00	40.00
				95.00

LABOUR

46 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	40.00
47 TO REMOVE & REFIT REAR WINDSCREEN		1 EA	120.00	120.00
48 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	250.00	250.00
49 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.		1 PC	60.00	60.00
50 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.		1 PC	60.00	60.00
51 TO RESET RADAR SENSOR rear tail boot auto absorber and lock		1 PC	500.00	500.00
52 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.		1 PC	80.00	80.00
53 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.		1 PC	90.00	90.00
54 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL INNER & OUTER. TO KNOCK & REPAIR SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	1,600.00	1,600.00
55 TO SPRAY TAILGATE, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH		1 PC	1,200.00	1,200.00
				4,000.00

Man photo
 03-09-20

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : YEO MING JIE, EUGENE
 BLK 472B FERNSVALE STREET #18-47
 SINGAPORE 792472

ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 16/07/2020
 TP Veh Reg No: GBG4215K

Estimate No: MC1901293
 Date: 03 Sep 2020
 Policy No: MP312381
 Veh Reg No: **SMG8251Z**
 Make/Model: JAGUAR E-PACE 2.0P
 (200PS)

Estimate Repair Cost to Vehicle No : SMG8251Z

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
SPARE PARTS				
1 REAR EXHAUST CHROME HEAT SHIELD		1 PC	86.00	—
2 REAR EXHAUST MOUNTING		1 PC	34.00	—
3 TAILGATE COVER		1 PC	64.00	—
4 TAILLAMP COVER LH		1 PC	100.00	—
5 REVERSE SENSOR WIRE HARNESS		1 PC	0.0000	✓ 135.00
			284.00	
	Add 15%		42.60	326.60

Lump Sum Repair	S\$ 326.60
GST Amount	S\$ 22.86
Total Amount payable	S\$ 349.46

The above vehicle was surveyed by LKK - KENNETH on 28/07/2020

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE