

REF: TP / 20007577/KJ

ASSIGNMENT

Veh No: SLA 4333R Yr Regn: 02, 16
 Type: MC Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Trailer Or 4 C.C. 1988

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : PROPERTY
 Accident Date : 16-Jul-2020

No. : 06195

Date : 18-Jul-2020

Our Ref : 020076 () / CHAN

PAGE : 1

SOH TECK SOON
 BLK 237 HOUGANG STREET 21
 #06-386
 Singapore 530237

Not Authorised
L1 Smp 832504
4 days

ESTIMATED COST OF REPAIR FOR MAZDA 6 2.0 SLA4333R

- 1 pc Front windscreen glass
- 1 pc Front o/s wiper garnish
- 1 pc Front n/s wiper garnish
- 2 pcs Wiper garnish side cover
- 2 pcs Wiper arm
- 2 pcs Wiper blade
- 1 pc Wiper motor
- 1 pc Front dashboard

	CDN 1,533.90	✓
	Del 322.00	✓
	Gr 327.00	✓
	In 98.60	X
DD/Gr @ S\$ 49.30	292.00	✓
ND/Gr @ S\$ 146.00	118.60	✓
ND/Gr @ S\$ 59.30	374.00	X
	ND/Gr 1,363.00	✓

4,429.10

Less 20% : 885.82

- 1 pc Front w/s glass sealant
- 1 pc ERP IU bracket
- 1 pc Front w/s glass solar film

To remove & renew front windscreen glass and conduct water leak test.

To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.

To sand down roof top, bonnet and to polish whole car

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3,543.28 *40sm*
 NEC 60.00 sn
 25.00 sn ✓
 300.00 sn / bon

150.00 *12d*

200.00 *18d*

500.00 *40d*

Total : S\$ 4,778.28

Singapore Dollars Four Thousand Seven Hundred and Seventy Eight and Cents Twenty Eight Only