

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)
8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875
Tel : 6341 6789 Fax: 6341 6778
E-mail:visionautowork@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No allegation(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DATE: 21.07.20

Acknowledged by Repairer

Signature:

Date:

TO : AIG MOTOR CLAIMS DEPTS
VEHICLE NO : SMR6079K
MODEL : TOYOTA PRIUS
DATE OF ACCIDENT : 21.07.20
TIME OF ACCIDENT : 10:30HRS

Signature:

Date:

5TDZS3E440J052689

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE	1	\$ 1,211.40	\$ 1,211.40
2	TAILGATE EMBLEM 'PRIUS-C'	1	\$ 58.35	\$ 58.35
3	TAILGATE EMBLEM 'HYBRID'	1	\$ 65.20	\$ 65.20
4	TAILGATE WEATHER STRIP	1	\$ 298.40	\$ 298.40
5	REAR BUMPER	1	\$ 968.70	\$ 968.70
6	REAR BUMPER REFLECTOR LH	1	\$ 85.20	\$ 85.20
7	REAR BUMPER DIFFUSER	1	\$ 694.30	\$ 694.30
8	REAR BUMPER CENTER BOTTOM GARNISH	1	\$ 646.90	\$ 646.90
9	REAR BUMPER SIDE RETAINER	2	\$ 69.80	\$ 139.60
10	TAILLAMP LH	1	\$ 596.80	\$ 596.80
11	TAILLAMP LOWER BRACKET LH	1	\$ 69.30	\$ 69.30
12	REAR FENDER LH	1	\$ 1,432.50	\$ 1,432.50
13	REAR FENDER GLASS LH	1	\$ 546.40	\$ 546.40
14	REAR FENDER INNER COWLING	2	\$ 124.10	\$ 248.20
15	REAR FENDER AIR VENT LH	1	\$ 61.70	\$ 61.70

TOTAL PRICE \$ 7,122.95
LESS 25% \$ 1,780.74
SUB TOTAL PRICE \$ 5,342.21

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET)	1	\$ 60.00	\$ 60.00
2	REAR BUMPER CENTER BOTTOM GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
3	TAILGATE SEALANT	1	\$ 150.00	\$ 150.00
4	TAILGATE INNER BOARD CLIP (SET)	1	\$ 60.00	\$ 60.00
5	TAILLAMP CLIP (SET)	1	\$ 40.00	\$ 40.00
6	REAR FENDER INNER COWLING CLIP (SET)	1	\$ 60.00	\$ 60.00
7	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 60.00	\$ 60.00
8	REAR FENDER GLASS SEALANT LH	1	\$ 80.00	\$ 80.00
9	REAR FENDER GLASS INNER SHIELD LH	1	\$ 60.00	\$ 60.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMR6079K**
 MODEL : **TOYOTA PRIUS**
 DATE OF ACCIDENT : 21.07.20
 TIME OF ACCIDENT : 10:30HRS

10	REAR FENDER GLASS SOLAR FILM	1	\$ 180.00	\$ 180.00	+
11	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	+
12	REAR WINDSCREEN INNER SHIELD	1	\$ 60.00	\$ 60.00	+
13	REAR END PANEL TOP GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00	+
14	REVERSE SENSOR	1	\$ 220.00	\$ 220.00	+
			TOTAL	\$ 1,210.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	400
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	400
3	TUFF COAT	\$ 250.00	30
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	50
6	REMOVE AND REFIX REAR FENDER GLASS LH	\$ 100.00	x
7	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 120.00	x
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	x
10	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
11	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	x
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,280.00

ESTIMATE REPORT

TOTAL PARTS COST : \$6,552.21
 TOTAL LABOUR COST : \$4,280.00
 TOTAL REPAIR COST : \$10,832.21

Adrian Lj
 2/5 28/07/20
 03 Days.
 total: 2576.20
 L/S: 2 K.