



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

22/07/2020

TP EQ

Xiao Tong

Accident date: 20/07/2020

Estimated repair cost for vehicle no: SLW2205A NISSAN QASHQAI 1.2 18'

CHASSIS: SJNFEAJ11U2171291

S/n	Qty	Items / Nett	U/price	Amount	
1	1	Front R/H Fender <i>Regis</i>		\$622.70	x.
2	1	Front R/H Fender Protector <i>Not new</i>		\$483.00	x
3	1	Front R/H Door Side Mirror Cover <i>Regis</i>		\$141.10	x
4	1	Front R/H Door <i>Regis</i>		\$1,104.80	x
5	1	Front R/H Door Lower Protector Cover <i>ut</i>		\$323.60	✓
6	10	Front R/H Door Lower Protector Clip <i>new</i>	\$6.50	\$65.00	20
7	1	Rear Bumper <i>Not new</i>		\$817.00	x
8	1	Rear R/H Door <i>Regis</i>		\$1,104.80	x
9	1	Rear R/H Door Handle <i>Not new</i>		\$96.20	x.
10	1	Rear R/H Door Lower Protector Cover <i>ut</i>		\$323.60	✓
11	10	Rear R/H Door Lower Protector Clip <i>new</i>	\$6.50	\$65.00	20
12	1	Rear R/H Fender <i>Regis</i>		\$1,105.80	x.
13	1	Rear R/H Fender Protector <i>ut</i>		\$483.00	✓
14	1	Rear R/H Petrol Tank Cap <i>Not new</i>		\$85.40	x.

Subtotal :- \$5,533.60

1170.20

1053.18

Labour charges

To check wiring		\$100.00	x
Tuff kote		\$150.00	x
Panel beating	850	\$1,000.00	150
Spray painting		\$1,400.00	700

Subtotal :- \$2,650.00

Total:- \$8,183.60

Supplementary - 588.41

total 2501.55

L/S: 2K

03 Days.

(2K) 030.11.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

07/08/2020

01-43

Singapore 417883

Accident date: 20/07/2020

Supplementary repair cost for vehicle no: SLW2205A NISSAN QASHQAI 1.2 18'

CHASSIS: SJNFEAJ11U2171291

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Door Side Mirror Assy WT		\$664.90 ✓

Subtotal :- \$664.90

664.90

598.40