

XINYA AUTO SERVICES PTE LTD

BLK 1002, BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : autolife_sin@yahoo.com.sg TEL: 6270 3481 FAX: 6278 7522

Date : 21/07/2020

Address : TOH CHIN KHONG
BLK 460 SIGLAP ROAD
#02-11 FLAMINGO VALLEY
SINGAPORE 455939

Reference : TP 1249/07/20
Vehicle No : SFF 8028R
Make/Model : VOLVO XC60
Insurance Co. : MSIG

RE : QUOTATION REPAIRS TO SFF 8028R FOR THIRD PARTY CLAIMS.

PARTS REQUIRED	QTY	COST	AMT \$
1) FRONT BUMPER <i>de</i>	1		\$1,624.00
2) FRONT BUMPER RETAINER LH <i>?</i>	1		\$88.70
3) HEADLAMP LH <i>sc</i>	1		\$1,669.20
4) FOG LAMP <i>sc</i>	1		\$465.00
LIST PRICE TOTAL			\$3,846.90
LESS DISCOUNT 5%			\$192.35
LIST PRICE TOTAL AFTER LESS			\$3,654.56

NETT PRICE TOTAL \$0.00

TOTAL PARTS COST

\$3,654.56

LABOUR AND MISCELLANEOUS CHARGES

- | | | |
|----|---|--|
| 1) | TO REMOVE & REPLACE FRONT BUMPER, HEADLAMP AND TO PANEL BEAT & ALIGN. | \$800.00 <i>300</i>
(4 Days) |
| 2) | TO PUTTY & SPRAY PAINT FRONT BUMPER. | \$400.00 <i>✓</i>
(2 Panel) |
| 3) | TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP. | \$80.00 <i>30</i> |

LABOUR TOTAL

Rase
\$1,280.00

TOTAL ESTIMATED REPAIR COST

Hp 90010068
\$ 4,934.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 days
4s
24/07/2020 @ 1000h
Resuy after surv