



VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-136, Enterprise Hub
Singapore 608586

Repair Estimate

Tel: 8287 9318
Fax: 8287 9313
www.avantage.sg

Date : 20-Jul-2020

Vehicle Num : SKR5302X

Make/Model : HYUNDAI ACCENT

Chassis No : KMHCT41BTFU860159

S/N	PARTS	QTY	PRICE	TOTAL
1	Front fender Rh <i>/ Bmc</i>	1	\$ 315.50	\$ 315.50
2	Front fender inner shield Rh <i>X SNA</i>	1	\$ 113.75	\$ 113.75
3	Front fender inner shield clips <i>X</i>	10	\$ 3.00	\$ 30.00
TOTAL PARTS				\$ 459.25
Less 20%				\$ 91.85
TOTAL AMOUNT				\$ 367.40
MISCELLANEOUS ITEM				
1	Sunderies <i>X NN</i>		\$ 50.00	\$ 50.00
2	Tuff Kote		\$ 50.00	\$ 40 50.00
LABOUR				
1	Remove and refit front fender Rh and other associated components		\$ 600.00	\$ 200 600.00
2	Surface preparation, spray paint and polish front fender Rh(Interior & Exterior), front door Rh(Interior & Exterior) and other associated components.		\$ 600.00	\$ 350 600.00
3	Perform Diagnostic full wheel alignment		\$ 100.00	\$ 100.00
TOTAL				\$ 1,767.40
GST 7%				\$ 123.72
GRAND TOTAL				\$ 1,891.12

2 Days. (3)
P/O *Temp* repair. / before paint photos.
After repair photos.
Gino Qiang - 8288 0282
23/7/2020

UK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: