

Our Ref: OD/072020/4439
Accident date: 20/7/2020
Your Ref: SLK6851X

Invoice No:
Date: 21/7/2020

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SLK6851X
Model : HYUNDAI ELANTRA AD 1.6 GLS AT

1	pc	Front bonnet ✓ BT	\$ 1,910.00
1	pc	Front RH bonnet hinge X	\$ 49.10
1	pc	Front LH bonnet hinge X } NN	\$ 49.10
1	pc	Front bonnet lock X	\$ 129.90
1	pc	Front RH headlamp X / CRA	\$ 1,750.40
1	pc	Front LH headlamp ✓ CRA	\$ 1,750.40
1	pc	Front grille with outer chrome moulding ✓ Cut	\$ 1,082.90
1	pc	Front bumper / Re.	\$ 474.00
1	pc	Front bumper top rubber / Cut.	\$ 32.40
1	pc	Front bumper no.plate garnish / Cut.	\$ 21.40
1	pc	Front bumper towing cover X NN	\$ 18.10
1	pc	Front bumper lower lip / sub.	\$ 48.90
1	pc	Front RH bumper flog lamp X	\$ 265.10
1	pc	Front RH bumper flog lamp cover X } NN	\$ 115.40
1	pc	Front RH bumper side retainer X	\$ 28.00
1	pc	Front LH bumper side retainer X } NN	\$ 28.00
1	pc	Front bumper sponge X ✓ CRA	\$ 110.70
1	pc	Front bumper reinforcement X / BT	\$ 695.80
1	pc	Front support panel X NN ?	\$ 949.30
1	pc	Front support panel top cover / Re.	\$ 78.10
1	pc	Aircon condensor X / Cut	\$ 745.10
		Less 20%	\$ 10,332.10
			\$ (2,066.42)
			\$ 8,265.68

Our Ref: OD/072020/4439
Accident date: 20/7/2020
Your Ref: SLK6851X

Invoice No:
Date: 21/7/2020

1	pc	Front no.plate / mis.	\$	40.00	N
		To refill aircond gas	\$	120.00	1
		To replace and reset headlamp system	\$	180.00	30
		To repair front damage	\$	580.00	450
		To spray painting	\$	780.00	450
			\$	9,965.68	

VIN'S MOTOR PTE LTD

4 Days.
part by part.
before paint photos.
Gino Qian - 82880282
22/7/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: