

Not Authorized
Resurvey By paint

P/P \$7,625.65

Trans-cab Auto Services Pte Ltd

AAD2007-067

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7779K

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

17 JUL 2020

SHB 7779K

JTDKB3FU503083339

TOYOTA

PRIUS

15.7.2020

III

30/8/2019

PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$ R ₁	1,300.70 ✓
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$ R	97.50 X
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$ R	110.60 X
1	CHECK ASSY, FRONT DOOR	\$ S _L	183.80 X
1	WEATHERSTRIP, FRONT DOOR, RH	\$ S _L	231.30 X
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH	\$	926.00 ? X SVC
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	238.30 ? X SVC
1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$ R	603.20 X
1	TAPE, BLACK OUT, NO.1 FRT RH	\$ M _U	13.30 —
1	TAPE, BLACK OUT, NO.2 FRT RH	\$ M _U	43.50 —
1	TAPE, BLACK OUT, NO.3 FRT RH	\$ M _U	26.30 —
1	PANEL SUB-ASSY, REAR DOOR, RH	\$ R ₁	1,294.90 —
1	TAPE, BLACK OUT, NO.1 REAR RH	\$ M _U	21.90 —
1	TAPE, BLACK OUT, NO.2 REAR RH	\$ M _U	34.90 —
1	TAPE, BLACK OUT, NO.3 REAR RH	\$ M _U	15.40 —
1	WEATHERSTRIP, REAR DOOR, RH	\$ S _L	180.10 X
1	HINGE ASSY, REAR DOOR, LOWER RH	\$ R	87.10 X
1	HINGE ASSY, REAR DOOR, UPPER RH	\$ R	98.90 X
1	CHECK ASSY, REAR DOOR, RH	\$ S _L	183.80 X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	926.00 ? X SVC
1	REGULATOR SUB-ASSY. REAR DOOR WINDOW, RH	\$	206.70 ? X SVC
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$ R ₁	594.80 ?
1	REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH	\$ R	343.40 X
1	REINFORCE SUB-ASSY, ROCKER, OUTER RH	\$	583.40 ? X SVC
1	PANEL SUB ASSY, QUARTER, RH	\$ R ₁	871.50 ✓
1	LINER, REAR WHEEL HOUSE, RH	\$	139.80 X SVC

LKK Auto Consultants hence certify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7779K**AAD2007-067**

- 1 COVER, REAR BUMPER
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 FRONT FENDER EMBLEM RH
- 1 FRONT BUMPER SIDE RETAINER RH

\$	<i>Net/In</i>	442.60	✓
\$	<i>R</i>	117.70	X
\$	<i>Su</i>	123.70	X
\$	<i>Su</i>	88.50	X
\$	<i>Ry</i>	977.80	✓
\$	<i>Su</i>	206.70	X
\$	<i>na</i>	54.60	✓
\$	<i>Su</i>	80.10	X
TOTAL	\$	11,448.80	
25%	\$	2,862.20	
	\$	8,586.60	

Special Nett

- 1 FRONT DOOR STICKER 'TRANS-CAB'
- 1 REAR DOOR STICKER "6555-3333"
- 1 REAR WHEEL RIM
- 1 REAR WHEEL RIM COVER
- 1 REAR TYRE 195/65/15
- 1SET REAR FENDER LINER CLIP
- 1SET REAR BUMPER CLIP
- 1SET REAR BUMPER RETAINER CLIP
- 1 FRONT WHEEL RIM
- 1 FRONT WHEEL RIM COVER
- 1 FRONT TYRE 195/65/15
- 1SET FRONT BUMPER RETAINER CLIP
- 1SET FRONT FENDER LINER CLIP
- 1SET FRONT BUMPER CLIP
- 1SET ROCKER PANEL MOULDING CLIP
- 2 REAR WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 REAR WINDSCREEN INNER SPONGE SEAL

\$	<i>na</i>	100.00	<i>605AL</i>
\$	<i>na</i>	100.00	<i>605AL</i>
\$	<i>Su</i>	1,879.40	X
\$	<i>na</i>	211.50	✓
\$	<i>Su</i>	350.00	X
\$	<i>na</i>	60.00	X
\$	<i>na</i>	75.00	✓
\$	<i>na</i>	65.00	X
\$	<i>Su</i>	1,879.40	X
\$	<i>Su</i>	211.50	X
\$	<i>Su</i>	350.00	X
\$	<i>na</i>	65.00	X
\$	<i>na</i>	60.00	X
\$	<i>na</i>	75.00	X
\$	<i>na</i>	60.00	✓
\$	<i>na</i>	150.00	X
\$	<i>na</i>	200.00	X
\$	<i>na</i>	130.00	X
TOTAL	\$	6,021.80	

TOTAL PARTS \$ 14,608.40

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7779K**AAD2007-067****LABOUR**

To transfer of front door fittings, attachment and perform water seepage test.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	10001
To transfer of rear door fittings, attachment and perform water seepage test.	\$	170.00	601
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	170.00	1201
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	601
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	14001
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of rear bumper fittings, attachment to facilitate bodywork repair.	\$	nn 170.00	X
To transfer of rear fender fittings, attachment to facilitate bodywork repair.	\$	nn 170.00	X
To transfer of front fender fittings, attachment to facilitate bodywork repair.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7779K**AAD2007-067**

To Remove And Refit Rear Big & Small W/Screen Glass To
Facilitate Bodywork Repair.

\$ *nn* 350.00 *X*

To reinstall rear bumper parking sensor.

\$ 170.00 *501***TOTAL** \$ **11,480.00****Over All Total** \$ **26,088.40****(PART-BY-PART) Repair Days***25 days*
*8 days***For Official Use**

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)