

Not Authorized
Recovery By Paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No.: 6287 6666 Fax No.: 6257 1330

CO/GST Reg. No. 201019626G
SHB 7779K

AAD2007-067

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident:
Third Party Insurer:
Date of Registration:

17 JUL 2020

SHB 7779K

JTDKB3FU503083339

TOYOTA

PRIUS

15.7.2020

III

30/8/2019

PART		LIST	
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$	1,300.70	✓
1 HINGE ASSY, FRONT DOOR, UPPER RH	\$	97.50	✓
1 HINGE ASSY, FRONT DOOR, LOWER RH	\$	110.60	✓
1 CHECK ASSY, FRONT DOOR	\$	183.80	✓
1 WEATHERSTRIP, FRONT DOOR, RH	\$	231.30	✓
1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH	\$	926.00	?
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	238.30	?
1 LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$	603.20	✓
1 TAPE, BLACK OUT, NO.1 FRT RH	\$	13.30	✓
1 TAPE, BLACK OUT, NO.2 FRT RH	\$	43.50	✓
1 TAPE, BLACK OUT, NO.3 FRT RH	\$	26.30	✓
1 PANEL SUB-ASSY, REAR DOOR, RH	\$	1,294.90	✓
1 TAPE, BLACK OUT, NO.1 REAR RH	\$	21.90	✓
1 TAPE, BLACK OUT, NO.2 REAR RH	\$	34.90	✓
1 TAPE, BLACK OUT, NO.3 REAR RH	\$	15.40	✓
1 WEATHERSTRIP, REAR DOOR, RH	\$	180.10	✓
1 HINGE ASSY, REAR DOOR, LOWER RH	\$	87.10	✓
1 HINGE ASSY, REAR DOOR, UPPER RH	\$	98.90	✓
1 CHECK ASSY, REAR DOOR, RH	\$	183.80	✓
1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	926.00	?
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	206.70	?
1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80	?
1 REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH	\$	343.40	✓
1 REINFORCE SUB-ASSY, ROCKER, OUTER RH	\$	583.40	?
1 PANEL SUB ASSY, QUARTER, RH	\$	871.50	✓
1 LINER, REAR WHEEL HOUSE, RH	\$	139.80	✓

LKK Auto Consultants hence notify the Repairer of the following: g
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7779K

AAD2007-067

- 1 COVER, REAR BUMPER
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 FRONT FENDER EMBLEM RH
- 1 FRONT BUMPER SIDE RETAINER RH

\$	Net/ht	442.60	✓
\$	ht	117.70	X
\$	ht	123.70	X
\$	ht	88.50	X
\$	ht	977.80	✓
\$	ht	206.70	X
\$	ht	54.60	✓
\$	ht	80.10	X
TOTAL		\$	11,448.80
25%		\$	2,862.20
		\$	8,586.60

Special Nett

- 1 FRONT DOOR STICKER "TRANS-CAB"
- 1 REAR DOOR STICKER "6555-3333"
- 1 REAR WHEEL RIM
- 1 REAR WHEEL RIM COVER
- 1 REAR TYRE 195/65/15
- 1SET REAR FENDER LINER CLIP
- 1SET REAR BUMPER CLIP
- 1SET REAR BUMPER RETAINER CLIP
- 1 FRONT WHEEL RIM
- 1 FRONT WHEEL RIM COVER
- 1 FRONT TYRE 195/65/15
- 1SET FRONT BUMPER RETAINER CLIP
- 1SET FRONT FENDER LINER CLIP
- 1SET FRONT BUMPER CLIP
- 1SET ROCKER PANEL MOULDING CLIP
- 2 REAR WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 REAR WINDSCREEN INNER SPONGE SEAL

\$	ht	100.00	60/ht
\$	ht	100.00	60/ht
\$	ht	1,879.40	X
\$	ht	211.50	✓
\$	ht	350.00	X
\$	ht	60.00	X
\$	ht	75.00	✓
\$	ht	65.00	X
\$	ht	1,879.40	X
\$	ht	211.50	X
\$	ht	350.00	X
\$	ht	65.00	X
\$	ht	60.00	X
\$	ht	75.00	X
\$	ht	60.00	✓
\$	ht	150.00	X
\$	ht	200.00	X
\$	ht	130.00	X
TOTAL		\$	6,021.80

TOTAL PARTS \$ 14,608.40

Scanned with CamScanner

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No.: 6287 6666 Fax No.: 6257 1330
 CO/GST Reg. No. 201019626G
 SHB 7779K

AAD2007-067

LABOUR		
To transfer of front door fittings, attachment and perform water seepage test.	\$	170.00 601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00 10001
To transfer of rear door fittings, attachment and perform water seepage test.	\$	170.00 601
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	170.00 1201
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00 1201
To check steering geometry and computer wheel alignment	\$	220.00 601
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 14001
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To transfer of rear bumper fittings, attachment to facilitate bodywork repair.	\$	nn 170.00 X
To transfer of rear fender fittings, attachment to facilitate bodywork repair.	\$	nn 170.00 X
To transfer of front fender fittings, attachment to facilitate bodywork repair.	\$	nn 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB 7779K

AAD2007-067

To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair.	\$	N/A	350.00	X
To reinstall rear bumper parking sensor.	\$		170.00	501
TOTAL	\$		11,480.00	
Over All Total	\$		26,088.40	

(PART-BY-PART) Repair Days

25 days 8 days

For Official Use

Prepared By :	_____
	(Accident Dept)
Verify By :	_____
	(Accident Workshop)
Checked By :	_____
	(Finance Dept)