

Our Reference :2020/0040

Your Reference:

Vehicle Number : FBN6293J

S/N	Qty	Description	Condition	Repairer Estimate (\$\$)	Our Assessment (\$\$)
Parts					
1	1sets	Side Mirror /SCR	Grazed	85.00	85.00 ✓
2	1pcs	Handle Bar /BT	Bent	120.00	120.00 ✓
3	1pcs	Brake Lever (Right) X SVC	Grazed	55.00	55.00 X
4	1pcs	Brake Lever (Left) /SCR	Grazed	55.00	55.00 ✓
5	2pcs	Right Balancer /SCR	Grazed	45.00	45.00 ✓
6	2pcs	Steering Cone X SVC	Necessary	220.00	220.00 X
7	1pcs	Steering Under Bracket X SVC	Bent	180.00	180.00 X
8	1pcs	Front Fork Assy /BT	Bent	680.00	680.00 600
9	1pcs	Front Fender /CR4	Crack	128.00	128.00 ✓
10	2pcs	Front Fender Rear Cover /CR4	Broken	108.00	108.00 ✓
11	2pcs	Front Wheel Shaft X SVC	Bent	180.00	180.00 X
12	2pcs	Front Rim X SVC	Grazed	580.00	580.00 X
13	1pcs	Left Foot Under Cover /SCR	Grazed	120.00	120.00 ✓
14	1pcs	Right Foot Under Cover X SVC	Grazed	120.00	120.00 X
15	2pcs	Right Pillion Foot Rest X SVC	Grazed	120.00	120.00 X
16	1pcs	Muffler Cover X SVC	Dented	110.00	110.00 X
17	1pcs	Left Signal Assy Front /BR	Holder Torn	85.00	85.00 ✓
18	2pcs	Left Rear Signal Assy /MTS	Broken	85.00	85.00 ✓
19	2pcs	Clutch Outer Cover X SVC	Grazed	145.00	145.00 X
20	1pcs	Main Stand X SVC	Serviceable	180.00	180.00 X
21	1sets	Side Stand X SVC	Serviceable	120.00	120.00 X
22	1pcs	Front Central Inner Cover X SVC	Crack	140.00	140.00 X
23	1pcs	Left Outer Lower Cover /BR	Crack	120.00	120.00 ✓
24	1pcs	Right Outer Lower Cover /BR	Grazed	120.00	120.00 ✓
25	1pcs	Fuel Tank Under Cover X SVC	Serviceable	140.00	140.00 X
26	2pcs	Headlight Assy /CRA	Crack	650.00	650.00 250
27	1pcs	Headlight Left Cover /SCR	Grazed	120.00	120.00 ✓
28	2pcs	Headlight Right Cover X SVC	Grazed	120.00	120.00 X
29	2pcs	Front Head Outer Bracket X SVC	Dented	140.00	140.00 X
Total				5,071.00	4,771.00
Less 10%				507.10	477.10
Parts Sub Total				4,563.90	4,293.90

Special Next

30	1set	Front Tyre (Depreciation) X SVC	Torn	220.00	180.00 X
31	1set	Body Sticker /NEC	Necessary	400.00	400.00 100
32	1pcs	No. plate (Front) X SVC	Necessary	25.00	25.00 X
33	1pcs	No. plate (Rear) /BT	Necessary	25.00	25.00 ✓
Total				670.00	630.00 125

Labour					
1		Towing		80.00	50.00 ✓
2		Front Rim Alignment		120.00	80.00 60
3		To realign body frame		300.00	250.00 X

4	Workmanship	550.00	300.00	200
5	To respray on front fender, headlamp crowing, side fairing and accident affected area.	500.00	400.00	100
	Labour Total	1,550.00	1,080.00	
	Sub Total (labour and parts)	6,783.90	6,003.90	

Adjustment / Recommendations

Not: For Lump Sum Repair

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or use of ex-stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements).

The final adjusted Lump Sum contract amount is **S\$4800**

Under normal circumstances, the repair period would be about 7 working days.

Repair day 4 days

HS

\$1,900

$$\begin{array}{r}
 P = 1,836.90 \\
 N = 125 \\
 L = 410 \\
 \hline
 2,371.90 \\
 - 2096 \\
 \hline
 1,897.52
 \end{array}$$