

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5111524590	Date of Loss:	19/07/2020
Vehicle Reg. No.:	SMN3123G	Driveable?	yes
Driver Age:	30/05/1993	Third Party Vehicle No.:	SHA3622K
Any Injuries?	no	Contact No:	91077614
Insured/Claimant:	LOW ZHEN YU	Driver:	LOW ZHEN YU

Make/Model:	Honda, Freed - GB31	Vehicle Reg. Date:	31/07/2019
Vehicle Colour:	Blue	Engine Number:	LEB5617677
Chassis No:	GB71081151	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	26,554.40
Miscellaneous Items	1,530.00
Labour	5,190.00
Paintwork Labour	1,615.00
Towing	0.00
Gross Total(S\$):	34,889.40
GST 7.00%(S\$):	2,442.26
Nett Amount(S\$):	37,331.66

This claim is handled by: Sky Toh T C

DETAILS

Estimates On Parts					
No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER / CRU	925.80	-20.00	740.64
2	1	REAR BUMPER TOWING COVER X SVC	21.00	-20.00	16.80
3	1	REAR BUMPER SIDE RETAINER LH X SVC	24.90	-20.00	19.92
4	1	REAR BUMPER SIDE RETAINER RH X SVC	24.90	-20.00	19.92
5	1	REAR BUMPER UNDER COVER ?	155.00	-20.00	124.00
6	1	REAR BUMPER BRACKET LH ?	24.90	-20.00	19.92
7	1	REAR BUMPER BRACKET RH ?	24.90	-20.00	19.92
8	1	REAR TAILGATE / DP	1,393.60	-20.00	1,114.88
9	1	REAR TAILGATE HINGE LH X SVC	50.60	-20.00	40.48
10	1	REAR TAILGATE HINGE RH X SVC	50.60	-20.00	40.48
11	1	REAR TAILGATE LOCK / Jum	248.90	-20.00	199.12
12	1	REAR TAILGATE LOCK CATCH X SVC	27.20	-20.00	21.76
13	1	REAR TAILGATE OUTER HANDLE X SVC	375.50	-20.00	300.40
14	1	REAR TAILGATE OUTER HANDLE CHROME MOULDING X SVC	320.90	-20.00	256.72
15	1	REAR TAILGATE LOGO / Nec	58.70	-20.00	46.96
16	1	REAR TAILGATE "FREED" EMBLEM / Nec	55.00	-20.00	44.00
17	1	REAR TAILGATE "HYBRID" EMBLEM / Nec	75.00	-20.00	60.00
18	1	REAR TAILGATE RUBBER / CRU	168.50	-20.00	134.80
19	1	REAR TAILGATE INNER BOARD X SVC	288.00	-20.00	230.40
20	1	REAR TAILGATE INNER BOARD HANDLE / CRU	88.00	-20.00	70.40
21	1	REAR TAILGATE REFLECTOR LH X SVC	460.00	-20.00	368.00
22	1	REAR TAILGATE REFLECTOR RH X SVC	460.00	-20.00	368.00
23	1	REAR TAILGATE DAMPER LH X SVC	135.40	-20.00	108.32
24	1	REAR TAILGATE DAMPER RH X SVC	135.40	-20.00	108.32
25	1	REAR TAILLAMP LH X SVC	680.60	-20.00	544.48
26	1	REAR TAILLAMP RH / CBA	680.60	-20.00	544.48
27	1	REAR TAILLAMP LOWER PANEL LH X SVC	195.70	-20.00	156.56
28	1	REAR TAILLAMP LOWER PANEL RH X SVC	195.70	-20.00	156.56
29	1	REAR FENDER INNER TRIM BOARD LH X SVC	586.00	-20.00	468.80
30	1	REAR FENDER INNER TRIM BOARD RH X SVC	586.00	-20.00	468.80
31	1	REAR END PANEL / DP	623.70	-20.00	498.96
32	1	REAR END PANEL - INNER / DP	577.00	-20.00	461.60
33	1	REAR END PANEL TOP GARNISH ?	115.00	-20.00	92.00
34	1	REAR END PANEL KEYLESS SENSOR ? (INNER)	185.40	-20.00	148.32
35	1	REAR END PANEL KEYLESS SENSOR ? (OUTER)	210.40	-20.00	168.32
36	1	REAR CHASSIS MEMBER LH X SVC	921.90	-20.00	737.52
37	1	REAR CHASSIS MEMBER RH X SVC	921.90	-20.00	737.52
38	1	REAR CHASSIS FRAME X SVC	3,790.00	-20.00	3,032.00
39	1	REAR EXHAUST PIPE X SVC	988.00	-20.00	790.40
40	1	REAR EXHAUST SILENCER X SVC	950.00	-20.00	760.00
41	1	REAR EXHAUST HEATSHIELD X SVC	55.00	-20.00	44.00
42	1	REAR HYBRID BATTERY X SVC	12,800.00	-20.00	10,240.00
43	1	REAR SPARE TYRE PANEL ?	1,256.80	-20.00	1,005.44
44	1	REAR SPARE TYRE BOARD ?	950.60	-20.00	760.48
45	1	REAR SPARE TYRE TOOL SPONGE ?	330.00	-20.00	264.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Total Parts (\$\$)

26,554.40

Miscellaneous Items

Qty	Particulars	Amount	%Disc	After Disc
1	REAR NUMBER PLATE X <i>suc</i>	45.00	0.00	45.00
1	REAR BUMPER CLIPS <i>/ Nec</i>	45.00	0.00	45.00
1	REAR BUMPER SENSORS (SET) <i>/ short</i>	260.00	0.00	260.00
3	REAR BUMPER TOP CHROME MOULDING <i>/ dp</i>	180.00	0.00	180.00
4	REAR TAILGATE TOP CHROME MOULDING X <i>suc</i>	180.00	0.00	180.00
5	REAR TAILGATE OUTER HANDLE LOWER X <i>suc</i>	180.00	0.00	180.00
6	CHROME MOULDING			
7	REAR TAILLAMP CLIPS LH X <i>suc</i>	35.00	0.00	35.00
8	REAR TAILLAMP CLIPS RH <i>/ Nec</i>	35.00	0.00	35.00
9	REAR WINDSCREEN SEALANT <i>/ Nec</i>	60.00	0.00	60.00
10	REAR CAMERA X <i>suc</i>	450.00	0.00	450.00
11	REAR EXHAUST MOUNTING X <i>suc</i>	60.00	0.00	60.00
Sub Total (\$\$)				1,530.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	120.00	0.00	120.00 <i>50</i>
2	1	To Do Up Interior Cleaning and Chemical Wash.	200.00	0.00	200.00 X
3	1	To Remove and Refit Rear Cushion Fittings.	80.00	0.00	80.00 X
4	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	0.00	180.00 X
5	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 <i>30</i>
6	1	To Transfer Rear Tailgate.	80.00	0.00	80.00 <i>60</i>
7	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00 <i>/</i>
8	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	50.00	0.00	50.00 <i>30</i>
9	1	To pull, straighten chassis frame and realign	1,000.00	0.00	1,000.00 X
10	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	3,300.00	0.00	3,300.00 <i>1,000</i>
Gross Labour Cost (\$\$)					5,190.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	70.00	0.00	70.00 X
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00 X
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,500.00	0.00	1,500.00 <i>800</i>

Repair days - 5 ~~4~~ days.

P/P.

Before paint photo

Sun Pin (444)

23/07/2020

TP without prejudice

Gross Labour Cost (\$\$) 1,615.00

< END OF ESTIMATES >