

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	
Policy No:	5111524590	Date of Loss:	19/07/2020
Vehicle Reg. No.:	SMN3123G	Driveable?	yes
Driver Age:	30/05/1993	Third Party Vehicle No.:	SHA3622K
Any Injuries?	no	Contact No:	91077614
Insured/Claimant:	LOW ZHEN YU	Driver:	LOW ZHEN YU
Make/Model:	Honda, Freed - GB31	Vehicle Reg. Date:	31/07/2019
Vehicle Colour:	Blue	Engine Number:	LEB5617677
Chassis No:	GB71081151	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	
Description of Accident/loss	COLLISION - HEAD TO REAR		
Remarks:			
Present Location:	Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG		
COST OF CLAIMS			
Parts		6771.68	Amount: 26,554.40
Miscellaneous Items		940.00	1,530.00
Labour		2070.00	5,190.00
Paintwork Labour		1315.00	1,615.00
Towing			0.00
Gross Total(S\$):		① 11096.68	34,889.40
GST 7.00%(S\$):			2,442.26
Nett Amount(S\$):			37,331.66

This claim is handled by: Sky Toh T C

① \$ 11,096.68

② \$ 2,146.80

\$ 13,243.48

P/P \$ 13,243.48

(PLS CONFIRM)

$P = 4,665.52$
 $Supp = 1,523.2$
 $S/N = 690$
 $L = 3,130$
10,008.72

P/P

\$ 10,008.72

11 days

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER	925.80	-20.00	740.64
2	1	REAR BUMPER TOWING COVER CR4 X SUC	21.00	-20.00	16.80
3	1	REAR BUMPER SIDE RETAINER LH X SUC	24.90	-20.00	19.92
4	1	REAR BUMPER SIDE RETAINER RH X SUC	24.90	-20.00	19.92
5	1	REAR BUMPER UNDER COVER X SUC	155.00	-20.00	124.00
6	1	REAR BUMPER BRACKET LH 2 X SUC	24.90	-20.00	19.92
7	1	REAR BUMPER BRACKET RH 2 X SUC	24.90	-20.00	19.92
8	1	REAR TAILGATE	1,393.60	-20.00	1,114.88
9	1	REAR TAILGATE HINGE LH X BT	50.60	-20.00	40.48
10	1	REAR TAILGATE HINGE RH X BT	50.60	-20.00	40.48
11	1	REAR TAILGATE LOCK	248.90	-20.00	199.12
12	1	REAR TAILGATE LOCK CATCH X SUC	27.20	-20.00	21.76
13	1	REAR TAILGATE OUTER HANDLE X SUC	375.50	-20.00	300.40
14	1	REAR TAILGATE OUTER HANDLE CHROME X SUC	320.90	-20.00	256.72
15	1	REAR TAILGATE LOGO	58.70	-20.00	46.96
16	1	REAR TAILGATE "FREED" EMBLEM	55.00	-20.00	44.00
17	1	REAR TAILGATE "HYBRID" EMBLEM	75.00	-20.00	60.00
18	1	REAR TAILGATE RUBBER	168.50	-20.00	134.80
19	1	REAR TAILGATE INNER BOARD	288.00	-20.00	230.40
20	1	REAR TAILGATE INNER BOARD HANDLE	88.00	-20.00	70.40
21	1	REAR TAILGATE REFLECTOR LH X SUC	460.00	-20.00	368.00
22	1	REAR TAILGATE REFLECTOR RH X SUC	460.00	-20.00	368.00
23	1	REAR TAILGATE DAMPER LH X SUC	135.40	-20.00	108.32
24	1	REAR TAILGATE DAMPER RH X SUC	135.40	-20.00	108.32
25	1	REAR TAILLAMP LH X SUC	680.60	-20.00	544.48
26	1	REAR TAILLAMP RH	680.60	-20.00	544.48
27	1	REAR TAILLAMP LOWER PANEL LH X SUC	195.70	-20.00	156.56
28	1	REAR TAILLAMP LOWER PANEL RH X SUC	195.70	-20.00	156.56
29	1	REAR FENDER INNER TRIM BOARD LH	586.00	-20.00	468.80
30	1	REAR FENDER INNER TRIM BOARD RH	586.00	-20.00	468.80
31	1	REAR END PANEL	623.70	-20.00	498.96
32	1	REAR END PANEL - INNER	577.00	-20.00	461.60
33	1	REAR END PANEL TOP GARNISH X SUC	115.00	-20.00	92.00
34	1	REAR END PANEL KEYLESS SENSOR (INNER) X SUC	185.40	-20.00	148.32
35	1	REAR END PANEL KEYLESS SENSOR (OUTER) X SUC	210.40	-20.00	168.32
36	1	REAR CHASSIS MEMBER LH	921.90	-20.00	737.52
37	1	REAR CHASSIS MEMBER RH	921.90	-20.00	737.52
38	1	REAR CHASSIS FRAME X SUC	3,790.00	-20.00	3,032.00
39	1	REAR EXHAUST PIPE X SUC	988.00	-20.00	790.40
40	1	REAR EXHAUST SILENCER X SUC	950.00	-20.00	760.00
41	1	REAR EXHAUST HEATSHIELD X SUC	55.00	-20.00	44.00
42	1	REAR HYBRID BATTERY X SUC	12,800.00	-20.00	10,240.00
43	1	REAR SPARE TYRE PANEL X SUC	1,256.80	-20.00	1,005.44
44	1	REAR SPARE TYRE BOARD X SUC	950.60	-20.00	760.48
45	1	REAR SPARE TYRE TOOL SPONGE X SUC	330.00	-20.00	264.00

Total Parts (\$\$)

26,554.40

6771.68

5,831.90

- 20%

4,665.52

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR NUMBER PLATE X SVC	45.00	0.00	45.00
2	1	REAR BUMPER CLIPS / Nec	45.00 ³⁰	0.00	45.00
3	1	REAR BUMPER SENSORS (SET) / Short	260.00 ²⁰⁰	0.00	260.00
4	1	REAR BUMPER TOP CHROME MOULDING / DP	180.00 ¹⁰⁰	0.00	180.00
5	1	REAR TAILGATE TOP CHROME MOULDING X / Nec	180.00 ¹⁰⁰	0.00	180.00
6	1	REAR TAILGATE OUTER HANDLE LOWER X / Nec	180.00 ¹⁰⁰	0.00	180.00
		CHROME MOULDING			
7	1	REAR TAILLAMP CLIPS LH X SVC	35.00	0.00	35.00
8	1	REAR TAILLAMP CLIPS RH / Nec	35.00 ²⁹	0.00	35.00
9	1	REAR WINDSCREEN SEALANT / Nec	60.00	0.00	60.00
40	1	REAR CAMERA X SVC	450.00	0.00	450.00
41	2	REAR EXHAUST MOUNTING X SVC	60.00	0.00	60.00

Sub Total (\$\$) 1,530.00 ^{940.00}

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	120.00	0.00	120.00 ⁵⁰
2	1	To Do Up Interior Cleaning and Chemical Wash.	200.00	0.00	200.00 X
3	1	To Remove and Refit Rear Cushion Fittings.	80.00	0.00	80.00 X
4	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	0.00	180.00 X
5	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 ³⁰
6	1	To Transfer Rear Tailgate.	80.00	0.00	80.00 ⁶⁰
7	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00 ¹⁰⁰
8	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	50.00	0.00	50.00 ³⁰
9	1	To pull, straighten chassis frame and realign	1,000.00	0.00	1,000.00 X
10	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	3,300.00	0.00	3,300.00 ^{1,600}

Gross Labour Cost (\$\$) 5,190.00 ^{3070.00}

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	70.00	0.00	70.00 ³⁶
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00 ³⁰
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,500.00	0.00	1,500.00 ^{1,200}

Gross Labour Cost (\$\$) 1,615.00 ^{1315.00}

Repair days ⁵ days.

P/P 11 days.

Before paint photo

Sun Pin (LH)

23/07/2020

TP without pre-india

< END OF ESTIMATES >

Sun Pin (LH)

07/08/2020.

before paint.

3,130

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5111524590	Date of Loss:	19/07/2020
Vehicle Reg. No.:	SMN3123G	Driveable?	yes
Driver Age:	30/05/1993	Third Party Vehicle No.:	SHA3622K
Any Injuries?	no	Contact No:	91077614
Insured/Claimant:	LOW ZHEN YU	Driver:	LOW ZHEN YU

Make/Model:	Honda, Freed - GB31	Vehicle Reg. Date:	31/07/2019
Vehicle Colour:	Blue	Engine Number:	LEB5617677
Chassis No:	GB71081151	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	2,146.80
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total(\$\$):	2,146.80
GST 7.00%(\$\$):	150.28
Nett Amount(\$\$):	2,297.08

This claim is handled by: Lai Yee Meng

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER INNER ABSORBER LH / C/P	58.00	58.00	-20.00	46.40
2	1	REAR BUMPER INNER ABSORBER RH / C/P	58.00	58.00	-20.00	46.40
3	1	REAR FLOOR PANEL / P2	1,356.90	1,356.90	1,200-20.00	1,085.52
4	1	REAR FLOOR PANEL BOARD / CM	1,210.60	1,210.60	588-20.00	968.48
			Total Parts (\$)	1,904 -20%		2,146.80
				1,523.2		

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
			Sub Total (\$)			0.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
			Gross Labour Cost (\$)			0.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
			Gross Labour Cost (\$)			0.00

< END OF ESTIMATES >