



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE  
#05-01/06  
SINGAPORE LAND TOWER  
SINGAPORE 048623

INV No. AC2005904  
INV Date 28/08/2020  
Reference CS/SMO20007607/Uvf3n2  
Code SMO



### PROFESSIONAL SERVICE FEE

Vehicle No. SMF 9554Z  
Insured Veh. SML 3099D  
Claim No. CMTD2002132/AGC  
Policy No.  
Accident Date 17/07/2020  
Inspection Date 23/07/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>250.00</b>
<b>GST (7%)</b>	<b>17.50</b>
<b>Grand Total</b>	<b>267.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20007607/Uvf3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 28-08-2020		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SML 3099D	<b>Veh. Inspected</b>	SMF 9554Z
	<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	CMTD2002132/AGC	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	23/07/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	LEXUS GS450H (A)	<b>c.c</b>	3456
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2010
	<b>Chassis No.</b>	JTHBC96S105023530	<b>Colour</b>	WHITE
	<b>Odometer</b>	216410	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	245/40 ZR18	MICHELIN	6 mm
	<b>L/H Front Tyre</b>	245/40 ZR18	MICHELIN	6 mm
	<b>R/H Rear Tyre</b>	245/40 ZR18	MICHELIN	6 mm
	<b>L/H Rear Tyre</b>	245/40 ZR18	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	17/07/2020	<b>Inspection Date</b>	23/07/2020
	<b>Survey held at</b>	SIANG HUI MOTOR WORKS BLK 3006 UBI ROAD 1 #01-338 SINGAPORE 408700		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 9554Z**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT DOOR N/S	BADLY DENTED	1,340.50	1,340.50
1	DOOR INNER LOCK N/S	SHORTED / JAMMED	770.40	395.00
1	DOOR OUTER HANDLE N/S	NOT NECESSARY	275.40	-
1	DOOR CHROME MOULDING N/S	CRACKED / BENT	223.50	223.50
1	DOOR W/STRIP N/S	NOT NECESSARY	213.20	-
1	DOOR REGULATOR GEAR N/S	BENT	313.80	313.80
1	DOOR REGULATOR MOTOR N/S	SERVICEABLE	501.30	-
1	REAR DOOR CHROME MOULDING N/S	SCRATCHED	223.50	223.50
	LESS 10% DISCOUNT		-386.16	-249.63
			3,475.44	2,246.67
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WHEEL RIM (SN)	TO REPAIR SEE LABOUR	950.00	-
			950.00	-
	<b><u>LABOUR</u></b>			
	TO CHECK WHEEL ALIGNMENT.		60.00	60.00
	TO REMOVE,REPLACE FRONT DOOR & REPAIR REAR DOOR & FENDER.INCLUSIVE OF THE REPAIR OF REAR WHEEL RIM.		880.00	400.00
	TO SPRAY PAINTING.		900.00	800.00
	TO CHECK WIRING.	NOT NECESSARY	60.00	-
			1,900.00	1,260.00
	<b>GRAND TOTAL</b>		<b>6,325.44</b>	<b>3,506.67</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,800.00</b>

Report Ref No. CS/SMO20007607/Uvf3n2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMF 9554Z

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMF 9554Z

RE-INSPECTION







## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMF 9554Z

RE-INSPECTION

