



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

22-07-2020

TP Great American

Veron

Accident date: 22/07/2020

GRB

Estimated repair cost for vehicle no: ~~GBG~~ 4118J NISSAN URVAN 3.0 5DR 09'

CHASSIS: JN1MG4E25Z0792248

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Bumper <i>to n</i>		\$723.20 ✓ 654
2	8	Front Bumper Clip <i>neu</i>	\$6.50	\$52.00 ✓ 30
3	1	Front L/H Bumper Side Retainer <i>neu</i>		\$91.90 ✓
4	1	Front L/H Bumper Fog Lamp <i>free</i>		\$323.70 ✓
5	1	Front L/H Bumper Fog Lamp Cover <i>neu</i>		\$130.10 ✓
6	1	Front L/H Side Panel <i>Dented</i>		\$588.00 ✓
7	1	Front L/H Headlamp <i>centered</i>		\$561.20 ✓
8	1	Front L/H Signal Lamp <i>centered</i>		\$219.00 ✓
9	1	Front L/H Door <i>Dented</i>		\$1,296.30 ✓
10	2	Front L/H Door Hinge <i>2</i>		\$69.60 ✓
11	1	Front L/H Door Inner Lock <i>free</i>		\$189.50 ×
12	1	Front L/H Door Inner Trim Board <i>free</i>		\$717.90 ×
13	1	Front L/H Door Weatherstrip <i>neu</i>		\$141.50 ×
14	1	Front L/H Door Window Motor & Regulator Assy <i>neu</i>		\$624.90 ×
15	1	Front L/H Door Company Sticker (Special Nett) <i>neu</i>		\$30.00 ✓
16	1	Front L/H Step Panel Garnish <i>neu</i>		\$329.30 ✓

Subtotal :- \$6,088.10

347040

312336

Labour charges

To remove & refit front R/H door, gear, motor, lock, glass,
rubber & trim board

~~\$200.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

1240

~~\$150.00~~ 30

Panel beating

~~\$1,400.00~~ 600

Spray painting

~~\$1,400.00~~ 500

Subtotal :- \$3,250.00

Total:- \$9,338.10

Adrian Lj

L/S. 27/07/20

04 days.

total: 4363.36

L/S 3.5K.

3.5K.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: