

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 4118J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TORN	723.20	654.00
8	FRONT BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
1	FRONT L/H BUMPER SIDE RETAINER	NECESSARY	91.90	91.90
1	FRONT L/H BUMPER FOG LAMP	NOT NECESSARY	323.70	-
1	FRONT L/H BUMPER FOG LAMP COVER	NOT NECESSARY	130.10	-
1	FRONT L/H SIDE PANEL	DENTED	588.00	588.00
1	FRONT L/H HEADLAMP	CRACKED	561.20	561.20
1	FRONT L/H SIGNAL LAMP	CRACKED	219.00	219.00
1	FRONT L/H DOOR	DENTED	1,296.30	1,296.30
2	FRONT L/H DOOR HINGE	NOT NECESSARY	69.60	-
1	FRONT L/H DOOR INNER LOCK	NOT NECESSARY	189.50	-
1	FRONT L/H DOOR INNER TRIM BOARD	NOT NECESSARY	717.90	-
1	FRONT L/H DOOR WEATHERSTRIP	NOT NECESSARY	141.50	-
1	FRONT L/H DOOR WINDOW MOTOR & REGULATOR ASSY	NOT NECESSARY	624.90	-
1	FRONT L/H DOOR COMPANY STICKER	NECESSARY	30.00	30.00
1	FRONT L/H STEP PANEL GARNISH	NOT NECESSARY	329.30	-
	LESS 10% DISCOUNT		-	-347.04
			6,088.10	3,123.36
	<u>LABOUR</u>			
	TO REMOVE & REFIT FRONT R/H DOOR,GEAR,MOTOR,LOCK,GLASS,RUBBER & TRIM BOARD.		200.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	30.00
	PANEL BEATING.		1,400.00	600.00
	SPRAY PAINTING.		1,400.00	500.00
			3,250.00	1,240.00
	GRAND TOTAL		9,338.10	4,363.36

RECOMMENDED COST OF LUMP SUM REPAIRS		3,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/GAI20007609/Avf3e2





Report Ref No. CS/GAI20007609/Avf3e2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.