



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20007610/AUvf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 19-10-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 7260Z	Veh. Inspected	SKE 8818Z
Policy No.	D20MTSCBU000086	Coverage (\$)	0.00
Claim No.	CMTD2002175/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	23/07/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ESTIMA	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	ACR500082581	Colour	WHITE
Odometer	126197	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/35 R20	ATLAS	6 mm
L/H Front Tyre	245/35 R20	ATLAS	6 mm
R/H Rear Tyre	245/35 R20	ATLAS	6 mm
L/H Rear Tyre	245/35 R20	ATLAS	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/07/2020	Inspection Date	24/07/2020
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------