

159 TICK HAI MOTOR
1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 53033608A

Not Authorized
1/54 1200/
3 days
27/7/20

Vehicle Number: SJQ9132K
Vehicle Model : Toyota Camry 2.0 Auto ABS Airbag
Manufacturing Year : 2009
Chassis : MR053BK4107044580

submit to 145

S/N.	Item Description	Amount (\$)
1	Rear Bumper <i>588.10 Re/70.1</i>	\$ 665.10
2	Rear Bumper Side Retainer (RH) <i>Reuf</i>	\$ 40.13
3	Taillamp Lower Retainer (RH) <i>17</i>	\$ 32.10
4	Rear Bumper Reinforcement <i>R</i>	\$ 224.70
5	Rear Bumper Reflector (RH) <i>17</i>	\$ 32.10
6	Rear Exhaust <i>11</i>	\$ 585.20
Total :		\$ 1,579.33
Less 25% :		\$ 394.83
Amount :		\$ 1,184.49

X
X
X
X

Labour	Amount (\$)
To remove, reinstall sensors	\$ 50.00
To check rear electrical wiring system	\$ 80.00
To remove, reinstall exhaust pipe	\$ 17 80.00
To remove, replace above listed parts and straighten and panel beat accident affected areas	\$ 800.00
To spray painting on affected areas	\$ 700.00
Labour Total :	\$ 1,710.00
Total (Parts & Labour)	\$ 2,894.49

✓
20
X
480
500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

2-628.23
251
471.17
1571.17
22
126