



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
 64 CECIL STREET
 #04-00 & #05-00 IOB BUILDING
 SINGAPORE 049711

Registration No : SLH949D

Chassis No : JHMRU1810GX200654

Model : HRV DX-SIN CVT YM 2016

Owner's Name : CHEW BIOW WAH

Ins Policy No. : 18-MV009535-R01

Date of Accident : 19/7/2020

Document No. : BQT20002267 Page 1

Date : 23. Jul 2020

Customer No. : WZV007

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15BA530656

Date | Time : 23. Jul 2020 9:40:50 AM

Surveyor Name : DID : +65 9248 5673

Survey Date : HP : +65 8100 5318

Authorisation Date : Email : ary@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO: 74887)						
	OWNER: CHEW BIOW WAH						
	OWNER INSURER: TOKIO MARINE INSURANCE LTD						
	ACC DATE: 19/07/2020@10.00AM						
	ACC: 84 JALAN GELENGGANG						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH: SH8761S - TOYOTA/PRIUS/BLUE TAXI						
33100-T7S-E11	HEADLIGHT ASSY,R. X	1	1869.00	25	1401.75	98.12	1499.87
91505-TM8-003	CLIP,BUMPER / APC	14	2.30	25	24.15	1.69	25.84
71130-T7A-010ZZ	BEAM COMP,FR.BUMPER X	1	228.80	25	171.60	12.01	183.61
71110-T7A-000	SPOILERFR.BUMPER AIR ?	1	56.30	25	42.22	2.96	45.18
04711-T7A-N00ZZ	FACE,FR.BUMPER / CUT	1	487.90	25	365.92	25.61	391.53
71140-T7A-000	BEAMR.FR.BUMPER UPPER ?	1	26.90	25	20.17	1.41	21.58
71105-T7A-000	GARNISHR.FR.FOG LIGHT X	1	22.10	25	16.57	1.16	17.73
71193-T7A-J00	SPACER,R.FR.BUMPER SIDE / BR	1	11.30	25	8.47	0.59	9.06
74107-T7B-003	PROTECTOR,R.FR.WHEEL ARCH / CUT	1	157.60	25	118.20	8.27	126.47
60210-T7A-J00ZZ	PANEL COMP,R.FR.FENDER X R	1	405.20	25	303.90	21.27	325.17
74100-T7A-N00	FENDER ASSYR.FR.INNER X	1	92.30	25	69.22	4.85	74.07
	Sum Item				2542.17	177.94	2,720.11
BOSUN	SUNDRIES	1	30.00 29		30.00	2.10	32.10
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	140.00 120		140.00	9.80	149.80
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS. 650	1	1800.00 650		1800.00	126.00	1926.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P) 570	1	1800.00 1040		1800.00	126.00	1926.00
	Sum Labor				3770.00	263.90	4,033.90

Printed on 23/7/2020 10:05:54 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT20002267	Page	2
Registration No	: SLH949D	Date	: 23. Jul 2020		
Chassis No	: JHMRU1810GX200654	Customer No.	: WZ1007		
Model	: HRV DX-SIN CVT YM 2016	Svc Advisor	: ARY CHUA WAI NGEE		
Owner's Name	: CHEW BIOW WAH	Engine No	: L15B4530656		
Ins Policy No.	: 18-MV009535-R01	Date Time	: 23. Jul 2020 9:40:50 AM		
Date of Accident	: 19/7/2020	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

Survey By

Date & Time

Excess

Status

Signature

Steve (LKK) 83228813

27/7/20, 10.00am

Total Amount 6,312.17 441.84 6,754.01

Total (Inclusive of GST) 6,754.01

WML PM

3 days

P/P

By Bel SL

Steve chen@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 23/7/2020 10:05:54 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.