

HONDA

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT20002267	Page	1
	64 CECIL STREET	Date	: 23. Jul 2020		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZ1007		
	SINGAPORE 049711	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SLH949D	Engine No	: L15B4530656		
Chassis No	: JHMRU1810GX200654	Date Time	: 23. Jul 2020 9:40:50 AM		
Model	: HRV DX-SIN CVT YM 2016	Surveyor Name	: DID : +65 6846 5673		
Owner's Name	: CHEW BIEW WAH	Survey Date	: HP : +65 8100 6306		
Ins Policy No.	: 18-MV009535-R01	Authorisation Date	: Email : anychua@honda.com.sg		
Date of Accident	: 19/7/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 74887)						
	OWNER: CHEW BIEW WAH						
	OWNER INSURER: TOKIO MARINE INSURANCE LTD						
	ACC DATE: 19/07/2020@10.00AM						
	ACC: 84 JALAN GELENGGANG						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH: SH8761S - TOYOTA/PRIUS/BLUE TAXI						
33100-T7S-E11	HEADLIGHT ASSY,R. X NM	1	1869.00	25	1401.75	98.12	1499.87
91505-TM8-003	CLIP,BUMPER / NPC	14	2.30	25	24.15	1.69	25.84
71130-T7A-010ZZ	BEAM COMP,FR.BUMPER X NM	1	228.80	25	171.60	12.01	183.61
71110-T7A-000	SPOILERFR.BUMPER AIR ? X NM	1	56.30	25	42.22	2.96	45.18
04711-T7A-N00ZZ	FACE,FR.BUMPER / CUT	1	487.90	25	365.92	25.61	391.53
71140-T7A-000	BEAMR.FR.BUMPER UPPER ? / BR	1	26.90	25	20.17	1.41	21.58
71105-T7A-000	GARNISHR.FR.FOG LIGHT X NM	1	22.10	25	16.57	1.16	17.73
71193-T7A-J00	SPACER,R.FR.BUMPER SIDE / BR	1	11.30	25	8.47	0.59	9.06
74107-T7B-003	PROTECTOR,R.FR.WHEEL ARCH / CUT	1	157.60	25	118.20	8.27	126.47
60210-T7A-J00ZZ	PANEL COMP,R.FR.FENDER X R	1	405.20	25	303.90	21.27	325.17
74100-T7A-N00	FENDER ASSYR.FR INNER X NM	1	92.30	25	69.22	4.85	74.07
Sum Item					2542.17	177.94	2,720.11
BOSUN	SUNDRIES	1	30.00	29	30.00	2.10	32.10
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	140.00	120	140.00	9.80	149.80
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS. 650	1	1800.00	650	1800.00	126.00	1926.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P) 570	1	1800.00	1040	1800.00	126.00	1926.00
Sum Labor					3770.00	263.90	4,033.90

Printed on 23/7/2020 10:05:54 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

Total - 2366.91

HONDA

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SLH949D
Chassis No : JHMRU1810GX200654
Model : HRV DX-SIN CVT YM 2016
Owner's Name : CHEW BLOW WAH
Ins Policy No. : 18-MV009535-R01
Date of Accident : 19/7/2020

Document No. : SQT20002267
Date : 23. Jul 2020
Customer No. : WZ1007
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B4530656
Date | Time : 23. Jul 2020 9:40:50 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

Survey By

Date & Time

Excess

Status

Signature

Steve (LKK) 83228813

27/7/20, 10:00am

Total Amount 6,312.17 441.84 6,754.01

Total (Inclusive of GST)

6,754.01

WML PR
3 days
P/P
By Bel SL

Steve Chen @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 23/7/2020 10:05:54 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.