

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

DATE: 21.07.2020

3P INSURANCE: CHINA TAIPING

MODEL: TOYOTA PRIUS

SURVEYOR: NA

VEH NO.: SHD7268H

MVA: OLIVIA

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper	1	25% 343.45	✓ \$458.60 de ✓
	Rear Bumper Re-Inforcement	1		\$318.80 XNN
	Rear Bumper Under Cover	1	25% 414.45	✓ \$552.60 de ✓
	Rear Bumper Side Retainer (RH)	1	25% 84.52	✓ \$112.70 ne ✓ 112.68
	Rear Bumper Under Side Cover (RH)	1	25% 174	✓ \$232.00 de ✓
	Rear Bumper Under Side Centre Cover(RH)	1		\$552.60 XNN
	Rear Bumper Towing Cover	1	25% 62.02	✓ \$82.70 m.s ✓
	Rear Bumper Clips	10	25% 16.50 \$2.50	✓ \$22.00 ne ✓
	Tial Lamp Assy (Upper) (RH)	1	25% 418.42	✓ \$557.90 av ✓
	Tail Lamp Assy (Lower) (RH)	1	25% 411.30	✓ \$548.40 av ✓
	Rear Fender, RH	1		\$836.70 RY
	SPARE PARTS SUB TOTAL		1925.16	\$4,275.00
	LESS 25%			\$1,068.75
	DISCOUNTED SPARE PARTS TOTAL			\$3,206.25
	Rear Bumper Reverse Sensor	1		\$135.70 Nett XNN.
	Rear Bumper Rubber Mat	1		✓ \$50.00 Nett ne ✓
	REAR BUMPER ADVERTISEMENT	1		\$50.00 ne ✓
	REAR FENDER ADVERTISEMENT RH	1		\$100.00 ne ✓
	NETT TOTAL			\$335.70
	SPARE PARTS & NETT TOTAL			\$3,541.95

200

ST NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
			SHD7268H	
	Panel Beating		\$350.00	320
	Spray Painting Charge		\$500.00	400
	Wiring Charge		\$60.00	30
	Remove/Refix Reverse Sensor		\$100.00	30
	Remove/Refix Cushion & Upholstery Rear		\$150.00	60
				840
	LABOUR TOTAL		\$1,160.00	
	ESTIMATE TOTAL		\$4,701.95	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanfin 97995749  
 - wp'  
 p/p Resury before paint  
 02 days  
 Tanfine 11kauto.com  
 21/7/20 C3pu

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

1925.16  
 200  
 840  
 -----  
 92965.16  
 02 days #