

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 21.07.2020

3P INSURANCE: CHINA TAIPING

MODEL: TOYOTA PRIUS

SURVEYOR: NA

VEH NO.: SHD7268H

MVA: OLIVIA

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper	1		\$458.60 de ✓
	Rear Bumper Re-Inforcement	1		\$318.80 X
	Rear Bumper Under Cover	1		\$552.60 de ✓
	Rear Bumper Side Retainer (RH)	1		\$112.70 ne ✓
	Rear Bumper Under Side Cover (RH)	1		\$232.00 de ✓
	Rear Bumper Under Side Centre Cover(RH)	1		\$552.60 X
	Rear Bumper Towing Cover	1		\$82.70 m.s ✓
	Rear Bumper Clips	10	\$2.50	\$22.00 ne ✓
	Tial Lamp Assy (Upper) (RH)	1		\$557.90 an ✓
	Tail Lamp Assy (Lower) (RH)	1		\$548.40 an ✓
	Rear Fender, RH	1		\$836.70 RY
SPARE PARTS SUB TOTAL				\$4,275.00
LESS 25%				\$1,068.75
DISCOUNTED SPARE PARTS TOTAL				\$3,206.25
	Rear Bumper Reverse Sensor	1		\$135.70 Nett X
	Rear Bumper Rubber Mat	1		\$50.00 Nett ne ✓
	REAR BUMPER ADVERTISEMENT	1		\$50.00 ne ✓
	REAR FENDER ADVERTISEMENT RH	1		\$100.00 ne ✓
NETT TOTAL				\$335.70
SPARE PARTS & NETT TOTAL				\$3,541.95

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
			SHD7268H	
	Panel Beating			\$350.00 320
	Spray Painting Charge			\$500.00 400
	Wiring Charge			\$60.00 30
	Remove/Refix Reverse Sensor			\$100.00 30
	Remove/Refix Cushion & Upholstery Rear			\$150.00 60
	LABOUR TOTAL			\$1,160.00
	ESTIMATE TOTAL			\$4,701.95
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanfah 97795749
 - wp'
 p/p Resurvey before paint
 02 days
 Tanfah e hantow
 21/7/20 C3pm

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: