

Shirley Hiew (LKK Auto)

From: Bryan Ang (LKKAuto)
Sent: Friday, 18 September 2020 9:42 am
To: Shirley Hiew (LKK Auto)
Cc: Steve Chen (LKK Auto)
Subject: RE: SJL6813A - Supplementary labour

Steve

Where is this speaker located?

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 18 September 2020 9:13 AM
To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>
Cc: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Subject: FW: SJL6813A - Supplementary labour

Hi Bryan,

Please let me know whether can I send out the below email once you review.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Thursday, 17 September 2020 6:42 pm
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: SJL6813A - Supplementary labour

Dear Shirley,

Our Surveyor attended the survey and noticed that the bracket inside of the (Treble Speaker and Retaining frame for loud speaker) were broken. In our opinion it is due to the impact which is consistent to the accident.

Thanks.

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)

Sent: Thursday, September 17, 2020 2:15 PM

To: Steve Chen (LKK Auto)

Cc: SUR

Subject: FW: SJL6813A - Supplementary labour

Hi Steve,

Kindly assist the below email from AIG.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>

Sent: Thursday, 17 September 2020 2:06 pm

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SJL6813A - Supplementary labour

Hi,

How could the dashboard treble speaker and trims damage be consistent with the accident?

TABLE SPEAKER	Cracked	192.00 FS
168	1	*RETAINING FRAME FOR LOUDSPEAKER TRIM LH/RH
169	1	*LOUDSPEAKER TRIM LH/RH

To remove.

Thanks & Regards

Victor Koh

AIG

Claims Technical Controller

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +65 6419 1785 | Fax +65 68357416

Victor-ck.koh@aig.com | www.aig.com

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Thursday, September 17, 2020 11:30 AM

To: Fong, Andy-SY

Cc: SUR; Koh, Victor-CK

Subject: [EXTERNAL] FW: SJL6813A - Supplementary labour

This message is from an external sender; be cautious with links and attachments.

Dear Andy,

Based on your instruction to refer email and re-adjust the labour due to mandate maintain in Merimen, kindly refer to the below email for the labour updated by our surveyor.

Kindly let us have your mandate approval.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 27 August 2020 1:45 pm
To: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJL6813A - Supplementary labour

Dear Victor,

We refer to your below email above matter.

According to our surveyor, after discuss with Premium Service advisor, the labour of supplementary 1 revised as below.

Labour 1 – The labour \$ 1,400.00 need to be maintain due to safety issue (caught fire) to be dismantle before we start replace A - pillar with sill panel RHS. (Please see resurvey photos)

Labour 2 – Premium can accept adjust the labour to \$ 1,500.00.

Labour 3 – Accept adjust the spray labour to \$ 1,100.00.

The damage photos of fender support (wheelhouse) submitted in Merimen. Please refer to the photo no. 221 – 229 in Merimen.

Kindly let us have your mandate approval.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Friday, 14 August 2020 1:45 pm
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJL6813A - Supplementary labour

Hi,

Labour to be adjusted before mandate approve.

Damage photos of fender support (wheelhouse) to be submitted – where is the damage photos? Labour is given for repair.

Thanks & Regards

Victor Koh

AIG

Claims Technical Controller

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +65 6419 1785 | Fax +65 68357416

Victor-ck.koh@aig.com | www.aig.com

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Friday, August 14, 2020 10:08 AM

To: Koh, Victor-CK

Cc: SUR

Subject: [EXTERNAL] RE: SJL6813A - Supplementary labour

This message is from an external sender; be cautious with links and attachments.

Dear Victor,

Refer to your below email above matter. Our surveyor still negotiate the repair cost with Premium.

We are seeking your approval of the supplementary 2.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>

Sent: Thursday, 6 August 2020 3:42 pm

To: SUR <sur@lkkauto.com>

Subject: RE: SJL6813A - Supplementary labour

TO REMOVE AND REINSTALL RHS FRONT SEAT, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS- not necessary this labour for replacement of side sill.

From: Koh, Victor-CK

Sent: Thursday, August 06, 2020 3:36 PM

To: SUR

Subject: SJL6813A - Supplementary labour

Hi,

TO CUT OUT AND WELD RHS A-PILLAR AND RHS SILL PANEL – replacement of a pillar at 2 day \$1000.

TO RESPRAY RHS A-PILLAR AND RHS SILL PANEL AND DOOR ENTRANCES – Spray paint at 2 panel \$1100.

Damage photos of fender support (wheelhouse) to be submitted.

B/f paint needed.

Kindly adjust labour in report.

Thanks & Regards

Victor Koh

AIG

Claims Technical Controller

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +65 6419 1785 | Fax +65 68357416

Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.