

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 42618

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0511/2020/GW
Date	:	23/7/2020

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Chua Chee Hwee Matthias
Address	:	33 Mangis Road #05-09 Singapore 424968
Telephone	:	(HP) +65 98556604
Type of Claim	:	Own Damage Claims
Policy No.	:	1900022368-01
Vehicle No	:	SJL 6813 A
Model Code	:	Audi A5 SB 2.0 TFS
Model / Year	:	1/2/2019
Engine No	:	CVK073345
Chassis No	:	WAUZZZF53KA010195
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22/7/2020
Place of Accident	:	Joo Chiat Place (Near Lamp Post 17)

remium Automobiles

Jbi Road 1, Singapore 408699
: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJL 6813 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N	\$ 280.00	X
2	To carry out first measurement test on car o-liner	S/N	\$ 800.00	? <i>photo</i>
3	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N	\$ 280.00	/
4	To remove and renew aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,400.00	/
5	To remove center console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit. Pillar trims, roof lining and both curtain air bags.	S/N	\$ 3,600.00	/

SUB TOTAL LABOUR CHARGES

: \$ 6,360.00

remium Automobiles

bi Road 1, Singapore 408699
: 6366 2323 Fax : 6841 1183

Telex

Estimated Labour Charges for Accident Vehicle SJL 6813 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
6	To remove and reinstall engine assy with gearbox assy to facillitate car o-liner repairs.	S/N	\$ 2,800.00	? photo
7	To remove and reinstall front suspension assy with subframe to facillitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N	\$ 2,400.00	/
8	To place vehicle on car-o liner.	S/N	\$ 1,800.00	? photo
9	To renew front windscreen.	S/N	\$ 480.00	/
10	To install solar film for front windscreen.	S/N	\$ 480.00	/
SUB TOTAL LABOUR CHARGES		:	\$ 7,960.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJL 6813 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
11	To carry out windscreen water seepage test.	S/N	\$ 200.00	/
12	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 280.00	X
13	^{LHS} To dismantle and reinstall rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N	\$ 350.00	280 560 /
14	To remove and transfer rhs headlight control unit and power module.	S/N	\$ 400.00	/
15	To dismantle and renew front bumper, bonnet, rhs front fender, rhs headlight, rhs sill panel trim and rhs front door. Cut out and reweld rhs fender support and closing element. Align both front chassis frames to specification of origin. Renew lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.		\$ 9,600.00	4500

9 days x 500

SUB TOTAL LABOUR CHARGES

: \$ 10,830.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJL 6813 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
16	To respray front bumper, rhs front fender, bonnet, hinges, rhs upper A-pillar, engine compartment, rhs front fender top support, rhs sill panel trim and rhs front door. To carry out joint sealant work and stone chip treatment. <i>LH fnd door - Sp X 1 7 x 550</i>	\$ 7,800.00	3850
17	To renew rhs front rim and tyre. To carry out wheel alignment	S/N \$ 280.00 /	
18	To carry out pre-repair diagnostic check and post repair diagnostic check.	S/N \$ 384.00 /	
TOTAL LABOUR CHARGES		: \$ 33,614.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 6813 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER / BR	\$ 2,251.00	
2	FRONT BUMPER FIXING PARTS / MC	\$ 402.00	
3	FRONT BUMPER SECURING STRIP / MC 1 X	\$ 70.00	
4	FRONT BUMPER GRILLE CENTER / BR	\$ 194.00	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE / BR	\$ 225.00	
6	FRONT BUMPER SPOILER / MIS	\$ 529.00	
7	FRONT AIR GUIDE-RH / MIS	\$ 62.00	
8	RADIATOR GRILLE / BR	\$ 2,300.00	
9	FRONT SENSOR SUPPORT-LH/RH / MC 2	\$ 102.00	
10	RADIATOR GRILLE COVER-UPPER ?	\$ 187.00	
11	FRONT AIR GUIDE GRILLE-RH / MIS	\$ 468.00	
12	FRONT FANFARE-RH X	\$ 124.00	
13	FAN FARE SPRING SHACKLE-RH / BT	\$ 29.00	
14	FRONT SENSOR -OUTER / MIS	TBC	
15	FRONT SENSOR -INNER / MIS	TBC	
16	FRONT SENSOR SEAL RING / MC 4	\$ 14.00	
17	FRONT BUMPER WIRING / BR	\$ 505.00	
18	FRONT BUMPER REINFORCEMENT BAR / BT	\$ 795.00	
19	FRONT FOAM FILLIER PIECE / BR	\$ 123.00	
20	FRONT BUMPER COVER / CRU	\$ 126.00	
SUB- TOTAL SPARE PARTS CHARGES		\$ 8,506.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 6813 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	FRONT BUMPER GUIDE SECTION-RH / BR	\$	36.00
22	FRONT BUMPER BRACKET-RH / BR	\$	212.00
23	SIGN 'CAUTION' STICKER / MC	\$	14.00
24	AIR CONDITIONER STICKER / MC	\$	8.00
25	FRONT LOCK CARRIER BRACKET / BR	\$	136.00
26	FRONT LOCK CARRIER SUPPORT-LH/RH / MC	\$	56.00
27	FRONT FENDER-RH / DD	\$	1,048.00
28	FRONT FENDER ATTACHMENT PARTS / MC	\$	53.00
29	FRONT FENDER CLOSING ELEMENT-RH X- ✓ BR	\$	73.00
30	FRONT FENDER BRACKET-RH / DT	\$	35.00
31	FRONT FENDER POP RIVET / MC	5 \$	16.00
32	FRONT FENDER CENTRE BRACKET-RH / DT	\$	57.00
33	FRONT FENDER UPPER BRACKET-RH / DT	\$	35.00
34	FRONT FENDER BRACE-RH / DT	\$	117.00
35	FRONT FENDER BRACKET DEFORMATION-RH / DT	\$	49.00
36	FRONT FENDER COVER-RH / CUT	\$	18.00
37	FRONT FENDER CLOSING ELEMENT-RH / ?	\$	33.00
38	FRONT WHEEL HOUSING LINER-RH / TN	\$	272.00
39	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH / MC	\$	90.00
40	FRONT WHEEL SPOILER-RH / MIS	\$	73.00

SUB- TOTAL SPARE PARTS CHARGES

\$ 2,431.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 6813 A

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
41	FRONT WHEEL SPOILER OUTER-RH / MIS	\$	36.00	
42	FRONT WHEEL SPOILER BRACKET TRIM-RH / MIS	\$	24.00	
43	FRONT STONE CHIP GUARD-RH / NC	\$	50.00	
44	BONNET / 00	\$	2,817.00	
45	BONNET ATTACHMENT PARTS X NN	\$	121.00	
46	BONNET HINGE-LH/RH / BT	2 \$	830.00	
47	BONNET IMPACT PROTECTION-LH/RH / NA	2 \$	55.00	
48	BONNET IMPACT PROTECTION-CENTER / m	\$	27.00	
49	BONNET NOISE INSULATION / CRU	\$	339.00	
50	FRONT FENDER TOP LEDGE COVER-RH INNER X- ✓	\$ CRA	72.00	
51	FRONT FENDER TOP LEDGE COVER-RH UPPER / BR	\$	35.00	
52	FRONT FENDER TOP LEDGE COVER-RH LOWER / NIS	\$	16.00	
53	BONNET GAS FILLED STRUT X NN	2 \$	235.00	
54	BONNET STRICKER-RH / BT	\$	50.00	
55	BONNET LID LOCK ?	\$	212.00	
56	BONNET BOWDEN CABLE -CENTER ?	\$	57.00	
57	BONNET BOWDEN CABLE COVER 1 X NN	\$	10.00	
58	CABLE FOR BONNET ?	\$	57.00	
59	BONNET RELEASE LEVER ?	\$	13.00	
60	BONNET LID LOCK CABLE	\$	73.00	
61	PLENUM CHAMBER COVER 1 X NN	\$	96.00	

SUB- TOTAL SPARE PARTS CHARGES

\$ 5,225.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 6813 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
61	PLENUM CHAMBER COVER X NN	\$	96.00
62	FRONT FENDER TOP SUPPORT LOWER-RH / DD	\$	248.00
63	FRONT FENDER TOP SUPPORT UPPER-RH / DD	\$	214.00
64	LED HEADLIGHT -RH / DR	\$	7,812.00
65	LED HEADLIGHT POWER MODULE-RH / SL	\$	749.00
66	LED HEADLIGHT CONTROL UNIT-RH / SL	\$	742.00
67	LED WITH HEAT SINK / SL	\$	1,140.00
68	HOSE FOR HEADLIGHT / MS	\$	36.00
69	LIFT CYLINDER FOR HEADLIGHT-RH / DR	\$	196.00
70	LIFT CYLINDER BRACKET-RH / MS	\$	15.00
71	HOSE FOR LIFT CYLINDER -RH / TN	\$	85.00
72	FRONT LOCK CARRIER / BT	\$	1,004.00
73	FRONT LOCK CARRIER SUPPORT ?	\$	38.00
74	A/C CONDENSER X NN	\$	615.00
75	REFRIGERANT LINE FOR A/C COMPRESSOR X NN	\$	165.00
76	REFRIGERANT LINE FOR CUT OFF POINT X NN	\$	336.00
77	REFRIGERANT BRACKET X ✓ NEC	\$	18.00
78	EXTERNAL TEMPERATURE SENSOR X NE NN	\$	56.00
79	CHARGE AIR COOLER X NN	\$	580.00
80	CHARGE AIR COOLER PRESSURE HOSE X NN	\$	353.00

SUB- TOTAL SPARE PARTS CHARGES

\$ 14,498.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 6813 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
81	EXHAUST GAS TURBOCHARGE X NN	\$	5,344.00
82	RADIATOR X NN	\$	837.00
83	RADIATOR COOLANT / REC 4	\$	177.00
84	RADIATOR FAN RING X NN	\$	242.00
85	RADIATOR FAN CONTROL UNIT X NN	\$	1,896.00
86	RADIATOR AIR GUIDE-RH OUTER / MIS	\$	31.00
87	RADIATOR AIR GUIDE-RH INNER / MIS	\$	16.00
88	RADIATOR AIR GUIDE-RH UPPER / MIS	\$	16.00
89	RADIATOR AIR GUIDE-RH LOWER / MIS	\$	22.00
90	INTAKE AIR DUCT-RH ?	\$	22.00
91	INTAKE AIR GUIDE ?	\$	53.00
92	AIR FILTER / BR	\$	382.00
93	INTAKE HOSE ?	\$	94.00
94	AIR MASS METER X NN	\$	551.00
95	INTAKE MANIFOLD X NN	\$	657.00
96	THROTTLE VALVE ADAPTER X NN	\$	1,006.00
97	ENGINE UNDER SHIELD ?	\$	566.00
98	FRONT FENDER TRIM-RH / BR	\$	157.00
99	FRONT DOOR TRIM-RH / REC	\$	157.00
100	FRONT WINDSCREEN / BR	\$	1,191.00

SUB- TOTAL SPARE PARTS CHARGES

\$ 13,417.00

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 6813 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
101	FRONT WINDSCREEN SPRING CLIP / <i>np</i>	\$ 21.00	
102	AIR BAG UNIT FOR STEERING WHEEL / <i>BR</i>	\$ 3,641.00	
103	AIR BAG UNIT / <i>np</i>	\$ 4,324.00	
104	HEAD AIR BAG UNIT-LH/RH / <i>BR</i>	2 \$ 3,684.00	
105	HEAD AIR BAG CONTROL UNIT / <i>np</i>	\$ 2,088.00	
106	FRONT SEAT BELT -LH / <i>jud</i>	\$ 1,056.00	
107	FRONT SEAT BELT -RH / <i>jud</i>	\$ 1,091.00	
108	FROTN SEAT BELT HEIGHT ADJUSTE-LH/RH ?	2 \$ 332.00	
109	A-PILLAR TRIM-LH/RH / <i>CR4</i>	2 \$ 404.00	
110	B-PILLAR TRIM-LH/RH <i>CR4</i> ?	2 \$ 464.00	
111	C-PILLAR TRIM-LH/RH ?	2 \$ 620.00	
112	D-PILLAR TRIM-LH/RH ? DEF ✓	2 \$ 404.00	
113	FRONT GRAB HANDLE-RH ?	\$ 139.00	
114	REAR GRAB HANDLE-LH/RH ?	2 \$ 280.00	
115	SPORT STEERING WHEEL / <i>CUT</i>	\$ 2,347.00	
116	DASH BOARD WITH AIR DUCT / <i>BR</i>	\$ 5,229.00	
117	DASH BOARD TOP LOWER COVER <i>X</i> ✓ CRA	\$ 166.00	
118	DASH BOARD TOP UPPER COVER <i>X</i> NN	\$ 122.00	
119	FRONT SIDE MEMBER TRIM-RH / <i>CPL</i>	\$ 816.00	
120	FRONT SIDE MEMBER TRIM-RH <i>X Rjw</i>	\$ 816.00	

SUB- TOTAL SPARE PARTS CHARGES

\$ 28,044.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 6813 A

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
121	FRONT SIDE MEMBER TRIM ATTACHMENT PARTS / <i>MC</i>		129.00	
122	1 SET OF ADHESIVE TAPE / <i>MC</i>	\$	210.00	
123	FRONT DOOR-RH X <i>R</i>	\$	3,091.00	
124	FRONT OUTER DOOR SEAL-RH X <i>NN</i>	\$	220.00	
125	BONDING AGENT X <i>NN</i>	\$	47.00	
126	CLEANING SOLUTION X <i>NN</i>	\$	65.00	
127	APPLICATOR X <i>NN</i>	\$	7.00	
128	FRONT DOOR CATCH-RH X <i>NN</i>	\$	119.00	
129	FRONT RIM-RH / <i>OR</i>		TBC	
130	FRONT TRYE-RH / <i>1</i>		TBC	
131	STONE CHIP / <i>MC</i>	S/N \$	180.00	
132	ACRYLIC SEALANT / <i>MC</i>	S/N \$	140.00	
133	CAVITY WAX / <i>MC</i>	S/N \$	180.00	
134	FRONT WINDSCREEN SEALANT / <i>MC</i>	S/N \$	200.00	
135	FRONT NO .PLATE / <i>MC</i>	S/N \$	60.00	
136	SUNDRIES / <i>1</i>	\$	500.00	
TOTAL SPARE PARTS CHARGES		\$	77,269.00	
TOTAL LABOUR CHARGES		\$	33,614.00	
GRAND TOTAL		\$	110,883.00	

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

: Steve (LKK)

Surveyed Date

:

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

24/7/25, 11.39 am

DD - Mt Adhark
EXcess - ?

20 dys

P/P

Ry BoL sy

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0511/2020/GW

24-Jul-20

Glory Tan

1 OF 1

SJL 6813 A

Audi A5 SB 2.0 TFS

Quantity	Description	Unit Price	Amount
Parts			
21	A-pillar with sill panel RHS <i>bt</i>	\$ 2,154.00	
22	Chassis tag <i>new</i>	\$ 457.00	
23	Sill trim strip RHS <i>new</i>	\$ 119.00	
24	Potential distributor <i>bro</i>	\$ 527.00	
Labours			
1	To remove and reinstall rhs front seat, floor carpets, electronic components and fuse trays. s/n	\$ 1,400.00	
2	To cut out and weld rhs A-pillar and rhs sill panel.	\$ 3,200.00	<i>2000</i>
3	To respray rhs A-pillar and rhs sill panel and door entrance.	\$ 2,300.00	<i>1650</i>
4	To repair wiring set for engine components. s/n	\$ 980.00	
TOTAL		\$ 29,813.00	30,113.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0511/2020/GW

24-Jul-20

Glory Tan

1 OF 1

SJL 6813 A

Audi A5 SB 2.0 TFS

Quantity	Description	Unit Price	Amount
Parts			
1	Front door chrome trim LHS <i>nee</i> ✓	\$ 157.00	
2	Engine mounting RHS <i>X</i>	\$ 417.00	
3	Subframe console RHS <i>X</i>	\$ 467.00	
4	Front subframe <i>bt</i> ✓	\$ 1,869.00	
5	Front wishbone link RHS <i>bt</i> ✓	\$ 533.00	
6	Front suspension guide RHS <i>bt</i> ✓	\$ 932.00	
7	Front guide upper front RHS <i>bt</i> ✓	\$ 506.00	
8	Front guide upper rear RHS <i>bt</i> ✓	\$ 506.00	
9	Wheel bearing housing RHS <i>bt</i> ✓	\$ 957.00	
10	Swivel joint <i>bt</i> ✓	\$ 191.00	
11	Suspension forks RHS <i>bt</i> ✓	\$ 261.00	
12	Coupling rod RHS <i>bt</i> ✓	\$ 127.00	
13	Front shock absorber RHS <i>?</i>	\$ 289.00	
14	Steering rack <i>nw (report)</i> ✓	\$ 6,234.00	
15	Tie rod end RHS <i>bt</i> ✓	\$ 195.00	
16	Roof lining <i>de</i> ✓	\$ 2,025.00	
17	Battery central protection <i>short</i> ✓	\$ 527.00	
18	Steering column <i>bt</i> ✓	\$ 2,214.00	
19	Water reservoir tank <i>de</i> ✓	\$ 141.00	
20	Anti-roll bar <i>bt</i> ✓	\$ 428.00	
TOTAL		\$ 18,976.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Paul
29/07/2020

Subject to

insurance
approval