

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 04 Aug 2020

Preliminary Advice

Vehicle No	: SJL6813A	Accident Date	: 22/07/2020
Make	: AUDI A5	Policy No.	: 1900022368
Assignment Date	: 24/07/2020	Excess	: S\$1,600.00
Date of Inspection	: 24/07/2020	Est. Duration of Repair	: 30 Days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front o/s portion, interior and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	140,996.00 (inclusive supp)
Revised Amount	:S\$	101,591.00 (inclusive supp)
Check Items (Estimated)	:S\$	9,429.00 (inclusive supp)
Total	:S\$	111,020.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	199,000.00
Pre-Accident Value	:S\$	155,000.00
COE / PARF Rebate	:S\$	64,518.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	134,482.00
Margin for Repair		90,482.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Margin for repair (New for old value) is \$ 134,482.00, Margin for repair is \$ 90,482.00. Supplementary amount is \$ 27,379.00 (inclusive check items \$ 289.00).