## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way

#09-16

Attn:

Singapore 079120

om: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Azlan, Syazairdina Date: 03 Sep 2020

## **Preliminary Advice**

Vehicle No : SJL6813A Accident Date : 22/07/2020 Make : AUDI A5 Policy No. : 1900022368 : 24/07/2020 : S\$800.00 Assignment Date **Excess** Date of Inspection Est. Duration of Repair : 30 : 24/07/2020

Inspection At : 24 BENOI SECTOR

REPAIRER: PREMIUM AUTOMOBILES PTE LTD

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	143,119.00 (Estimate \$142,621.00 + supp 5 \$36
-----------------------------	------	-------------------------------------------------

Revised Amount :S\$ 102,921.00 (inclusive supp)

 Check Items (Estimated)
 :S\$ 9,429.00

 Total
 :S\$ 112,350.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$	199,000.00
Pre-Accident Value	:S\$	155,000.00
COE / PARF Rebate	:S\$	64,518.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	134,482.00

# Margin for Repair (New Ior Old Value) .3\$ 134,402.00 Margin for Repair (Pre-Accident Value) :S\$ 90,482.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy cover	rage.
	Kindly let us have your authorisation.Margin for repair (New for old value) is \$ 134,482.00	

- ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Kindly approve on supplementary.